

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM21002180/Qtf3e2	
	8 SHENTON WAY TOWERSINGAPOR			Date:	19/03/2021	
	ATTN : YU DOMINI	IC YISHAN		Code:	ASM	
1.	. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHA 88Y	Veh. Inspected		SLM 6513L	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	S1M03416	Excess (\$)		0.00	
	Assign From	YU DOMINIC YISHAN	Assign Date		16/02/2021	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA SHUTTLE 1.5G	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	GK81007648	Colour		BLUE	
	Odometer	43211 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	185/60 R15	ROADSTONE		6 mm	
	L/H Front Tyre	185/60 R15	ROADSTONE		6 mm	
	R/H Rear Tyre	185/60 R15	ROADSTONE		6 mm	
	L/H Rear Tyre	185/60 R15	ROADSTONE		6 mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.					
5.	5. General Information					
	Accident Date	12/02/2021	Inspect Date / 1	Гime	18/02/2021 (11:54 AM)	
	Survey held at	BLK 5035 ANG MO KIO IND PAR	RK 2 #01-365			
	Repairer	AABE SERVICES				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000					
5b. Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					

Report Ref No. CS3/ASM21002180/Qtf3e2

Inspected By

OI SUN PIN

K.K.LAU CPT(RET)

Asst. Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser