

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 8247S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	EMBLEM-HYBRID	NECESSARY	24.30	24.30
1	EMBLEM-IONIQ	NECESSARY	31.30	31.30
1	COVER-RR BUMPER	TO REPAIR SEE LABOUR	459.40	-
1	MOULDING ASSY-RR BUMPER C	TORN	451.25	451.25
1	CAP-RR HOOK	NOT NECESSARY	98.80	-
1	REFLECTOR/REFLEX ASSY-RR	CUT	41.45	41.45
10	BUMPER COVER CLIP REAR	NECESSARY	22.00	22.00
1	LAMP ASSY-REAR COMB OUTSI	CUT	870.40	870.40
1	LAMP ASSY-REAR COMB INSID	CUT	794.40	794.40
	LESS 20% DISCOUNT		-558.66	-447.02
			2,234.64	1,788.08
	NETT ITEMS			
1	REAR BOOT LOGO CTPL (N)	NECESSARY	30.00	30.00
1	APP LOGO REAR DOOR L/R CT (N)	NECESSARY	40.00	40.00
1	REAR BOOT TEL NUMBER CTPL (N)	NECESSARY	30.00	30.00
	LESS 10% DISCOUNT		-	-10.00
			100.00	90.00
	SPECIAL NETT ITEMS			
1	PROTECTOR MAT (SN)	NOT NECESSARY	50.00	-
			50.00	-
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF COVER-RR BUMPER.		400.00	350.00
	SPRAYPAINT CHARGE.		600.00	500.00
	CHECK ALL LIGHTING.		50.00	30.00
	REMOVE/REFIX REVERSE SENSOR.		80.00	30.00
			1,130.00	910.00
	GRAND TOTAL		3,514.64	2,788.08

Report Ref No. NS/INC21002186/T1qd3q2





Page No.:2 of 2

RECOMMENDED COST OF REPAIRS		2,788.08
(CONFIRMED)		

Report Ref No. NS/INC21002186/T1qd3q2

**MOHAMAD TAUFIKH** 

M.MATAI, AMSAE-A

**Automotive Assessor** 

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser**