

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/AIG21002192/KTF3Q2**Date:** 10/03/2021REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100223955  
**Claimant**  
**Vehicle No :** SDF882S **Insured Vehicle No :** SQ63D  
Date of Loss: 11/02/2021 Nature of Claim: TP Claim No: 5260880358SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDF882S**  
Make & Model: MERCEDES-BENZ E250 BLUE EFFICIENCY, 1.8 (A) Engine No: 27186030467641  
Reg. Date: 01/11/2012 (Man. Year: 2012) Chassis No: WDD2120472A619788  
Colour: Metallic Dark Blue Odometer: 118550 km  
Engine Capacity: 1796 cc  
Market Value/New Car Price: N/A  
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40R18 Rear Tyre Size: 265/35R18  
Front Left Side: Continental 3 mm Rear Left Side: Continental 5 mm  
Front Right Side: Continental 3 mm Rear Right Side: Continental 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	25,376.88	6,290.78	19,086.10	75.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,360.00	1,530.00	2,830.00	64.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>29,736.88</b>	<b>7,820.78</b>	<b>21,916.10</b>	<b>73.70</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>6,200.00</b>		
	<b>(\$\$)</b> 29,736.88	6,200.00	23,536.88	79.15
<b>+ GST 7.00/7.00% (\$\$)</b>	2,081.58	434.00	1,647.58	79.15
<b>Nett Amount (\$\$)</b>	<b>31,818.46</b>	<b>6,634.00</b>	<b>25,184.46</b>	<b>79.15</b>

INSPECTION

Date of Assignment: 16/02/2021  
Date Inspected: 17/02/2021 Inspected At: S Three Automotive Recovery Pte Ltd (HQ)  
Blk 8 Sin Ming Industrial Estate, #01-64/66 Sector C  
Singapore 575643  
Estimated Period of Repair: 5.0 days

**Adjuster:** KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	2,080.00 FL	*1,590.00 FL
2	1		*REAR BUMPER LOWER COVER	Dented	960.00 FL	*622.00 FL
3	1		*REAR BUMPER LOWER GARNISH	No such part	680.00 FL	*- FL
4	1		*REAR BUMPER SIDE REFLECTOR LH	No such part	198.00 FL	*- FL
5	1		*REAR BUMPER SIDE REFLECTOR RH	No such part	198.00 FL	*- FL
6	1		*REAR BUMPER REINFORCEMENT	Bent	765.00 FL	*765.00 FL
7	2		*REAR BUMPER REINFORCEMENT STAYS	Serviceable	900.00 FL	*- FL
8	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	62.00 FL	*- FL
9	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	62.00 FL	*- FL
10	1		*REAR BUMPER TOWING COVER	Serviceable	88.00 FL	*- FL
11	3		*REAR BUMPER PLASTIC BRACKET	Repair	288.00 FL	*- FL
12	1		*REAR BUMPER BRACKET LH	Cracked	90.00 FL	*90.00 FL
13	1		*REAR BUMPER BRACKET RH	Cracked	90.00 FL	*90.00 FL
14	4		*REAR BUMPER BRACKET HOLDER	Serviceable	360.00 FL	*- FL
15	1		*REAR END PANEL	Bent	1,532.00 FL	*1,245.35 FL
16	1		*REAR END PANEL INNER GARNISH	Mtg Cracked	268.00 FL	*182.00 FL
17	1		*REAR PANEL INNER CROSSMEMBER	Repair	1,860.00 FL	*- FL
18	1		*BOOTLID	Repair	2,110.00 FL	*- FL
19	1		*BOOTLID EMBLEM-C&C	Necessary	80.20 FL	*80.20 FL
20	1		*BOOTLID LOGO	Necessary	62.00 FL	*62.00 FL
21	1		*BOOTLID EMBLEM E250	Necessary	76.00 FL	*76.00 FL
22	1		*BOOTLID EMBLEM 7G	Necessary	76.00 FL	*76.00 FL
23	1		*BOOTLID OUTER CHROME MOULDING	Dented	128.00 FL	*128.00 FL
24	1		*BOOTLID SWITCH	Serviceable	132.00 FL	*- FL
25	1		*BOOTLID INNER GARNISH	Serviceable	488.00 FL	*- FL
26	1		*BOOTLID LOCK	Dented	407.00 FL	*361.10 FL
27	1		*BOOTLID INNER TRIM	Serviceable	446.00 FL	*- FL
28	1		*BOOTLID RUBBER BEADING	Serviceable	158.00 FL	*- FL
29	1		*BOOTLID INNER CATCH	Repair	82.00 FL	*- FL
30	1		*REAR TAILLAMP LH	Cut	713.00 FL	*536.00 FL
31	1		*REAR TAILLAMP RH	Serviceable	713.00 FL	*- FL
32	1		*REAR EXHAUST PIPE SILENCER RH	Serviceable	1,905.00 FL	*- FL
33	1		*REAR EXHAUST PIPE SILENCER LH	Serviceable	1,905.00 FL	*- FL
34	1		*REAR EXHAUST PIPE SILENCER CHROME LH	Serviceable	380.00 FL	*- FL
35	1		*REAR EXHAUST PIPE SILENCER CHROME LH	Dented	380.00 FL	*225.00 FL
36	1		*SET REAR EXHAUST MOUNTING	Serviceable	240.00 FL	*- FL
37	1		*REAR CENTRE EXHAUST PIPE	Serviceable	1,059.00 FL	*- FL
38	1		*REAR CENTRE EXHAUST PIPE HEAT SHIELD	Repair	210.00 FL	*- FL
39	2		*REAR EXHAUST HEAT SHIELD	Serviceable	448.00 FL	*- FL
40	2		*REAR SPARETYRE SPONGE BOARD	Serviceable	380.00 FL	*- FL
41	1		*REAR FLOOR BOARD FIBRE	Serviceable	272.00 FL	*- FL
42	1		*REAR TYRE COMPARTMENT TOP BOARD	Serviceable	632.00 FL	*- FL
43	1		*SET REAR REVERSE SENSOR	Shorted	1,200.00 FS	*600.00 FS
44	1		*REAR REVERSE CAMERA	Serviceable	680.00 FS	*- FS
45	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*30.00 FS
46	1		*SET REAR END PANEL INNER GARNISH CLIPS	Necessary	50.00 FS	*50.00 FS
47	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
48	1		*REAR NUMBER PLATE	Dented	50.00 FS	*45.00 FS
49	1		*REAR BOOTLID SPOILER	No such part	680.00 FS	*- FS
50	1		*REAR BOOTLID SPOILER SEALANT	Not Necessary	80.00 FS	*- FS
51	2		*REAR BOOTLID STOPPER RH & LH	Serviceable	80.00 FS	*- FS
52	1		*REAR BOOTLID BREAKDOWN SIGN	Serviceable	380.00 FS	*- FS
53	1		*REAR BOOTLID REFLECTOR HOLDER	Serviceable	120.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
54	1		*REAR COMPARTMENT SEALANT	Not Necessary	80.00 FS	*- FS	
55	1		*REAR SPORT TYRE FIBRE SEALANT	Not Necessary	280.00 FS	*- FS	
F=Franchise part. S=SpcNett. L=ListItemDisc.							
					<b>Sub Total (S\$)</b>	<b>27,773.20</b>	<b>6,903.65</b>
					<b>- List Item Discount on L Items 10.00/10.00% (S\$)</b>	<b>2,396.32</b>	<b>612.87</b>
					<b>Total Parts (S\$)</b>	<b>25,376.88</b>	<b>6,290.78</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	STRAIGHTEN & PANEL BEAT ACCIDENT AREAS	New	1,600.00	700.00
2	SPRAY PAINTING ON ACCIDENT AREAS	New	1,400.00	660.00
3	CHECK & REPAIR WIRING SYSTEM	New	120.00	20.00
4	R&R SPARETYRE BOARD,INNER TRIM	New	120.00	60.00
5	R&R BOOTLID COMPONENTS	New	120.00	0.00
6	RESPRAY TUFF KOTE ON ACCIDENT AREAS	New	180.00	30.00
7	R&R EXHAUST PIPE SYSTEM	New	280.00	0.00
8	R&R REAR REVERSE SENSOR	New	180.00	60.00
9	R&R REAR SEAT AND COMPARTMENT TO ASSIST REPAIR	New	180.00	0.00
10	RESET BOOTLID SYSTEM	New	180.00	0.00
<b>Gross Labour Cost (\$)</b>			<b>4,360.00</b>	<b>1,530.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >