

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT LONPAC INSURANCE BHD CS3/LPC21002196/Qqf3e2 Ref: 300 BEACH ROAD #17-04/07 THE CONCOURSE Date: 02/03/2021 SINGAPORE 199555 Code: LPC2 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. XD 4006C SKX 4996T Veh. Inspected Policy No. Coverage (\$) 0.00 Claim No. 20/21/21/VC05/024238 Excess (\$) 0.00 **GERALD POH** 16/02/2021 **Assign From Assign Date** 2. **Vehicle Particulars & Condition VOLKSWAGEN TIGUAN** c.c 0 Make & Model HIDDEN Engine No. Year of Reg. WVGZZZ5NZGW036823 **BLACK** Chassis No. Colour 60323 KM Odometer Steering IN ORDER IN ORDER STANDARD ALLOY RIM **Brakes** Modification **FAIR** General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 255/40Z R19 DUNLOP 6 mm 255/40Z R19 DUNLOP L/H Front Tyre 6 mm 255/40Z R19 DUNLOP R/H Rear Tyre 6 mm **DUNLOP** L/H Rear Tyre 255/40Z R19 6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. 5. **General Information** 08/02/2021 17/02/2021 ( 10:11 AM ) **Accident Date** Inspect Date / Time Survey held at 3A Ontario AvenueThe Windsor#01-02 Repairer 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

Report Ref No. CS3/LPC21002196/Qqf3e2

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

**Inspected By** 

OI SUN PIN

K.K.LAU CPT(RET)

Asst. Automotive Assessor

BEng(Hons), B. Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser