



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com

Website: www.nhtmotor.com

Tel: 6747 9241

Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

15/02/2021

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP Budget Direct.
Xiao Chen.

Accident date: 12/02/2021

Estimated repair cost for vehicle no: SLJ2175X NISSAN QASHQAI 1.2 CVT 16'

CHASSIS: SJNFEAJ11U1724208

S/n	Qty	Items	U/price	Amount	
				\$1,061.30	✓
1	1	Front Bonnet <i>Distorted.</i>		\$119.60	✓
2	2	Front Bonnet Hinge <i>Bent.</i>	\$59.80	\$69.90	✓
3	1	Front Bonnet Lock <i>Dented</i>		\$96.40	X
4	1	Front Bonnet Inner Rubber <i>new</i>		\$194.80	X
5	1	Front Bonnet Insulator <i>3 M</i>		\$91.00	+
6	14	Front Bonnet Insulator Clip <i>3 M</i>	\$6.50	\$1,934.50	689
7	1	Front Bumper <i>Distorted.</i>		\$65.00	30
8	10	Front Bumper Clip <i>new</i>	\$6.50	\$380.80	X
9	1	Front Bumper Top Garnish <i>new</i>		\$58.80	✓
10	2	Front Bumper Side Retainer <i>new</i>	\$29.40	\$219.00	✓
11	1	Front Bumper Inner Sponge <i>Cracked</i>		\$28.10	X
12	1	Front Bumper Towing Cover <i>new</i>		\$457.70	✓
13	1	Front Bumper Reinforcement <i>Bent.</i>		\$387.40	193.70
14	2	Front Bumper Reinforcement Bracket <i>Bent KIT</i>	\$193.70	\$647.40	323.70
15	2	Front Bumper Fog Lamp <i>LH cracked</i>	\$323.70	\$260.20	130.10
16	2	Front Bumper Fog Lamp Cover <i>LH cracked</i>	\$130.10	\$335.00	X
17	1	Front Bumper Lower Grille <i>new</i>		\$486.00	✓
18	1	Front Grille <i>Cracked.</i>		\$65.00	20
19	10	Front Grille Clip <i>new</i>	\$6.50	\$79.90	✓
20	1	Front Grille Emblem Logo <i>new</i>		\$160.80	✓
21	1	Front Grille Chrome Moulding <i>cut</i>		\$1,507.20	753.60
22	2	Front Fender <i>LH Buckled</i>	\$753.60	\$256.60	+
23	2	Front Fender Cowling <i>3 M</i>	\$128.30	\$104.00	+
24	16	Front Fender Cowling Clip <i>3 M</i>	\$6.50	\$1,308.00	265
25	2	Front Fender Arch Protector <i>LH cracked</i>	\$654.00	\$104.00	20
26	16	Front Fender Protector Clip <i>new</i>	\$6.50	\$588.10	✓
27	1	Front Support Panel <i>Dented</i>		\$6,486.00	1218
28	2	Front Head Lamp <i>Cracked</i>	\$3,243.00		

29	2	Front Head Lamp Lower Bracket	2	\$38.10	\$76.20	x
30	2	Front Relay Fuse Box	HP	\$220.00	\$440.00	x
31	1	Front Relay Fuse Box Wire Harness	HP		\$2,255.90	x
32	1	Front Relay Fuse Box Bracket			\$180.50	x
33	1	Rear Boot Lid Dented			\$2,936.80	✓
34	2	Rear Boot Lid Hinge	3HP	\$51.60	\$103.20	x
35	2	Rear Boot Lid Shock Absorber	HP	\$209.80	\$419.60	x
36	1	Rear Boot Lid Emblem Logo	3HP		\$72.30	✓
37	1	Rear Boot Lid Qashqai Logo	HP		\$87.00	✓
38	1	Rear Boot Lid Centre Moulding	3HP		\$436.00	x
39	6	Rear Boot Lid Centre Moulding Clip	HP	\$6.50	\$39.00	x
40	1	Rear Boot Lid Number Plate	HP		\$50.00	x
41	2	Rear Boot Lid Side Reflector	HP	\$388.60	\$777.20	x
42	1	Rear Boot Lid Inner Lock	Damaged		\$161.50	✓
43	1	Rear Boot Lid Inner Rubber	Cut		\$158.70	✓
44	1	Rear Boot Lid Inner Trim Board	HP		\$316.50	x
45	1	Rear Boot Lid Windscreen Moulding	HP		\$130.10	✓
46	1	Rear Boot Lid Windscreen Seal	HP		\$85.00	✓
47	2	Rear Tail Lamp	Cracked	\$423.70	\$847.40	✓
48	4	Rear Tail Lamp Clip	HP	\$8.00	\$32.00	✓
49	1	Rear Bumper Distorted			\$2,014.00	786.70
50	10	Rear Bumper Clip	HP	\$6.50	\$65.00	30
51	2	Rear Bumper Side Retainer	HP	\$51.50	\$103.00	✓
52	2	Rear Bumper Side Reflector	Cracked	\$66.60	\$133.20	✓
53	1	Rear Bumper Towing Cover	HP		\$28.10	✓
54	1	Rear Bumper Lower Lid	HP		\$480.00	x
55	1	Rear Bumper Inner Foam	Cracked		\$183.80	✓
56	1	Rear Bumper Reinforcement	Best		\$619.20	✓
57	2	Rear Bumper Reinforcement Bracket	Dented	\$186.00	\$372.00	✓
58	2	Rear Fender Arch Protector	Cracked	\$584.40	\$1,168.80	580
59	2	Rear Fender Inner Trim Board	3HP	\$361.70	\$723.40	x
60	16	Rear Fender Inner Trim Board Clip	HP	\$6.50	\$104.00	x
61	1	Rear End Panel	Dented		\$482.60	✓
62	1	Rear End Panel Top Garnish	Cracked		\$105.00	✓
63	1	Rear End Panel Lock Sensor	HP		\$97.90	x
64	1	Rear Spare Tyre Panel	Cracked		\$1,860.00	1680
65	1	Rear Spare Tyre Panel Top Cover	Dented		\$513.30	284
66	1	Rear Spare Tyre Panel Top Sponge	HP		\$126.00	x
67	2	Rear Spare Tyre Side Panel	Reg	\$397.00	\$794.00	x
68	1	Rear Spare Tyre Lock	HP		\$67.40	x
69	1	Rear Tool Box	Cracked		\$378.00	✓
70	1	Rear Exhaust	Dented		\$830.00	✓

18060.60

16254.54

Subtotal :- \$38,406.10

S/n	Qty	Items / Special Nett	U/price	Amount
1	1	Front Air-Con Condenser <i>Dented</i>		\$658.20 ✓
2	1	Front Air-Con Section Pipe <i>3 m</i>		\$237.40 +
3	1	Front Air-Con Discharge Pipe <i>3 m</i>		\$291.50 +
4	1	Front Radiator <i>Dented</i>		\$687.40 ✓
5	1	Front Radiator Fan Motor Assy <i>Crushed</i>		\$621.70 ✓
6	1	Front Intercooler <i>Dented</i>		\$212.60 ✓
7	1	Front Oil Coolant Assy <i>Dented</i>		\$471.70 ✓
8	1	Rear Boot Lid Camera <i>New</i>		\$680.00 +
9	1	Rear Boot Lid Windscreen Seal <i>Good as</i>		\$60.00 +
10	2	Rear Bumper Reverse Sensor <i>Dented</i>	\$294.00	\$588.00 <i>200</i>
11	1	Rear Spare Tyre Panel & End Panel Insulator <i>New</i>		\$450.00 <i>50</i>
12	1	Rear Centre Exhaust <i>New</i>		\$809.30 +

Subtotal :- \$6,059.40

5010.60

Labour charges

To remove & refit air-con condenser, radiator, fan motor & top up gas	\$380.00 <i>120</i>
To remove & refit cushion & trim board	\$280.00 <i>250</i>
To remove & refit rear & center exhaust	\$380.00 <i>80</i>
To remove & refit reverse sensor	\$100.00 <i>50</i>
To remove & refit reverse camera	\$180.00 <i>50</i>
To remove & refit rear windscreen	\$120.00 ✓
Gum	\$50.00 ✓
Towing fee	\$150.00 <i>60</i>
To check wiring	\$100.00 <i>60</i>
Tuff kote	\$150.00 <i>120</i>
Panel beating	\$3,500.00 <i>2400</i>
Spray painting	<i>5360</i> \$2,800.00 <i>2000</i>

Subtotal :- \$8,190.00

Total:- \$52,655.50

total: 2662514

4/5: 21.31c.

15 Days

21.31c.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: