

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21002200/GTF3N2**Date:** 01/09/2021REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00017362001

Claimant Vehicle No : SJR9162T **Insured Vehicle No :** GBJ3464Z

Date of Loss: 01/02/2021 Nature of Claim: TP Claim No: SNM21D200616C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJR9162T**

Make & Model: TOYOTA COROLLA, 1.5 (A) Engine No: 3ZZEE

Reg. Date: 22/07/2009 (Man. Year: 2009) Chassis No: MR053ZEE106147943

Colour: Blue Odometer: 190871 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15

Front Left Side: Firenza 6 mm Rear Left Side: Firenza 6 mm

Front Right Side: Firenza 6 mm Rear Right Side: Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,275.52	4,334.46	6,941.06	61.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,380.00	1,590.00	2,790.00	63.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	15,655.52	5,924.46	9,731.06	62.16
Approved Total (Overridden) (\$\$)		4,700.00		
(\$\$)	15,655.52	4,700.00	10,955.52	69.98
+ GST 7.00/7.00% (\$\$)	1,095.89	329.00	766.89	69.98
Nett Amount (\$\$)	16,751.41	5,029.00	11,722.41	69.98

INSPECTION

Date of Assignment: 16/02/2021

Date Inspected: 19/02/2021 Inspected At: RICO 60 AUTO SERVICES PTE LTD (HQ)
8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT
Singapore 415875

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 Aug 2021)
Parts:	143	TOYOTA COROLLA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJR9162T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BONNET	Bent	1,036.20 FL	*739.10 FL
2	1	*BONNET INNER LOCK	Bent	372.40 FL	*82.60 FL
3	2	*BONNET STOPPER	Not Necessary	60.00 FL	*- FL
4	1	*BONNET RUBBER	Torn	106.10 FL	*31.00 FL
5	1	*BONNET INSULATOR	Not Necessary	217.30 FL	*- FL
6	2	*BONNET HINGE	Not Necessary	495.80 FL	*- FL
7	2	*HEAD LAMP	Cracked	1,477.00 FL	*1,060.20 FL
8	4	*HEAD LAMP BOTTOM RETAINER	Not Necessary	200.00 FL	*- FL
9	1	*FRONT BUMPER	Deformed	681.70 FL	*459.00 FL
10	1	*FRONT BUMPER TOP RUBBER	Not Necessary	120.00 FL	*- FL
11	1	*FRONT BUMPER SIDE RETAINER	O/s Deformed/N/s Not Necessary	188.60 FL	*35.00 FL
12	1	*FRONT BUMPER BADGE	Necessary	96.00 FL	*38.00 FL
13	1	*FRONT BUMPER BADGE BASE	Not Necessary	124.00 FL	*- FL
14	1	*FRONT BUMPER REINFORCEMENT	Bent	480.10 FL	*379.00 FL
15	2	*FRONT BUMPER REINFORCEMENT BRACKET	Not Necessary	164.00 FL	*- FL
16	1	*FRONT BUMPER LOWER GRILLE	Broken	235.00 FL	*102.30 FL
17	1	*FRONT BUMPER UNDER COVER	Broken	271.00 FL	*133.00 FL
18	1	*FRONT FOG LAMP	O/s Broken/N/s Not Necessary	700.00 FL	*266.98 FL
19	1	*FRONT FOG LAMP COVER	O/s Broken/N/s Not Necessary	194.40 FL	*62.50 FL
20	2	*FRONT FOG COVER CHROME MOULDING	Not Necessary	91.20 FL	*- FL
21	1	*FRONT GRILLE	Broken	438.00 FL	*266.20 FL
22	2	*FRONT GRILLE CHROME MOULDING (SHORT)	Not Necessary	192.00 FL	*- FL
23	1	*FRONT GRILLE CHROME MOULDING (LONG)	Not Necessary	136.00 FL	*- FL
24	1	*SUPPORT PANEL	Bent	1,425.00 FL	*728.10 FL
25	1	*RADIATOR	Not Necessary	1,109.50 FL	*- FL
26	1	*RADIATOR TOP GARNISH	Not Necessary	317.00 FL	*- FL
27	2	*RADIATOR TOP BRACKET	Not Necessary	70.00 FL	*- FL
28	1	*RADIATOR FAN COWLING	Broken	297.50 FL	*230.00 FL
29	1	*RADIATOR FAN MOTOR	Not Necessary	357.90 FL	*- FL
30	1	*RADIATOR FAN BLADE	Not Necessary	87.90 FL	*- FL
31	1	*AIR CON CONDENSER	Cut	890.10 FL	*890.10 FL
32	1	*AIR CON PIPE	Not Necessary	432.00 FL	*- FL
33	1	*WASHER TANK	Not Necessary	125.30 FL	*- FL
34	1	*WASHER TANK MOTOR	Not Necessary	97.60 FL	*- FL
35	1	*FRONT FENDER RH	Repair	799.80 FL	*- FL
36	1	*FRONT FENDER EMBLEM (VVTI)	Necessary	109.00 FL	*65.00 FL
37	1	*FRONT FENDER INNER SHIELD RH	Deformed	265.30 FL	*171.20 FL
38	1	*BONNET INSULATOR CLIP	Not Necessary	60.00 FS	*- FS
39	1	*SET BONNER RUBBER CLIP	Not Necessary	30.00 FS	*- FS
40	1	*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
41	1	*SET FRONT BUMPER UNDER COVER CLIP	Not Necessary	40.00 FS	*- FS
42	1	*FRONT FOG LAMP BULK	Not Necessary	30.00 FS	*- FS
43	1	*SET FRONT GRILLE CLIP	Not Necessary	40.00 FS	*- FS
44	1	*SUPPORT PANEL SEALANT	Not Necessary	70.00 FS	*- FS
45	1	*RADIATOR COOLANT	Not Necessary	60.00 FS	*- FS
46	1	*SET FRONT FENDER INNER SHIELD CLIP	Not Necessary	50.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$\$)	14,890.70
					- List Item Discount on L Items 25.00/25.00% (\$\$)	3,615.18
					Total Parts (\$\$)	11,275.52
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,REMOVAL AND REPLACING PARTS	New	1,800.00	600.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	800.00
3	TO PERFORM LIGHTING & WIRING CHECK	New	100.00	30.00
4	TO APPLY ANTI-RUST & TUFF KOTE	New	200.00	60.00
5	REMOVE AND INSTALL RADIATOR AND REFILL COOLANT AND HIGH PRESSURE TEST	New	180.00	100.00
6	REMOVE AND INSTALL CARPET,SEAT,DASHBOARD AND INTERIOR	New	350.00	0.00
7	REMOVE AND INSTALL CONDENSER AND REFILL AIRCON GAS	New	150.00	0.00
Gross Labour Cost (\$)			4,380.00	1,590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >