

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21002218/APS3Q2
Date: 05/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070123526
Claimant Vehicle No :	GBG7366M	Insured Vehicle No :	SLR707H
Date of Loss:	13/02/2021	Nature of Claim:	TP
		Claim No:	8542525843SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG7366M		
Make & Model:	NISSAN NV200, 1.5 L MT ABS AIRBAG 2WD 6DR (M)	Engine No:	K9KC400D057223
Reg. Date:	12/10/2017 (Man. Year: 2017)	Chassis No:	VSKYBAM20Z0148251
Colour:	Silver	Odometer:	54221 km
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	175/70 R14C	Rear Tyre Size:	175/70 R14C
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,408.84	2,806.08	602.76	17.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	860.00	630.00	230.00	26.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,268.84	3,436.08	832.76	19.51
Approved Total (Overridden) (S\$)		2,750.00		

Nett Amount (S\$)	4,268.84	2,750.00	1,518.84	35.58
+ Loss of Use (3.0 x S\$80.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,997.45		
Global Sum Settlement (S\$)		2,990.00		

INSPECTION

Date of Assignment: 16/02/2021

Date Inspected: 16/02/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Premium Carz Services Pte Ltd (HQ)
 1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki
 Singapore 417883

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER LH (NPA)	Repair	0.00 FL	*- FL
2	1		*FRONT BUMPER	Deformed	855.20 FN	*589.70 FN
3	1		*FRONT BUMPER SIDE RETAINER LH	Necessary	96.80 FN	*35.20 FN
4	1		*FRONT BUMPER TOW HOOK COVER	Deformed	28.00 FN	*28.00 FN
5	1		*FRONT BUMPER FOAM	Deformed	358.90 FN	*291.60 FN
6	1		*FRONT BUMPER REINFORCEMENT	Bent	756.90 FN	*614.90 FN
7	1		*ENGINE UNDER COVER	Deformed	250.30 FN	*250.30 FN
8	1		*FOG LAMP LH	Cracked	258.00 FN	*258.00 FN
9	1		*HEADLAMP LOWER PAD LH	Deformed	368.50 FN	*368.50 FN
10	1		*HEADLAMP LH	Cracked	615.00 FN	*615.00 FN
11	10		*FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
12	8		*FRONT FENDER INNER SHIELD CLIP	Not Necessary	40.00 FS	*- FS
13	10		*ENGINE UNDER COVER CLIP	Necessary	50.00 FS	*30.00 FS
14	1		*FRONT NUMBER PLATE W/CASING	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	3,767.60	3,111.20
- List Item Discount on L Items 30.00/30.00% (\$\$)	0.00	0.00
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	358.76	305.12
Total Parts (\$\$)	3,408.84	2,806.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	60.00	30.00
2	PANEL BEATING CHARGES TO REMOVE AND REPLACE ,TO CUT AND WELD,TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS	New	400.00	300.00
3	SPRAY PAINTING ALL AFFECTED PARTS & AREAS	New	400.00	300.00
Gross Labour Cost (S\$)			860.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >