

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21002221/T1QD3N2**Date:** 13/10/2021**REFERENCE**

Insured/Claimant: MALCOLM WONG WEE LEONG Policy No: 2070123526
Date of Loss: 13/02/2021 Nature of Claim: OD Claim No: 8542525843SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLR707H**
Make & Model: AUDI A3, 1.4 TFSI (A) Engine No: CHZC38043
Reg. Date: 25/08/2020 (Man. Year: 2019) Chassis No: WAUZZZ8V9LA033673
Colour: Black Odometer: 10965 km
Engine Capacity: 999 cc
Market Value/New Car Price: S\$110,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/40R18 Rear Tyre Size: 225/40R18
Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,273.40	8,746.24	6,527.16	42.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	18,192.00	13,142.00	5,050.00	27.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	33,465.40	21,888.24	11,577.16	34.59
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	32,865.40	21,288.24	11,577.16	35.23
+ GST 7.00/7.00% (S\$)	2,300.58	1,490.18	810.40	35.23
Nett Amount (S\$)	35,165.98	22,778.42	12,387.56	35.23

INSPECTION

Date of Assignment: 17/02/2021
Date Inspected: 16/02/2021 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 11.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SECTIONAL PART-SIDE MEMBER	Bent	2,293.00 FS	*1,834.40 FS
2	1		*REAR DOOR RH	Bent	2,767.00 FS	*2,213.60 FS
3	1		*REAR DOOR OUTER SEAL RH	Necessary	161.00 FS	*128.40 FS
4	1		*BONDING AGENT	Not Necessary	49.00 FS	*- FS
5	1		*CLEANING SOLUTION	Not Necessary	68.00 FS	*- FS
6	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
7	1		*REAR DOOR ATTACHMENT PARTS RH	Not Necessary	129.00 FS	*- FS
8	1		*REAR DOOR CATCH RH	Not Necessary	94.00 FS	*- FS
9	1		*REAR DOOR SEAL,INNER RH	Not Necessary	191.00 FS	*- FS
10	1		*REAR DOOR WINDOW SLOT SEAL TRIM RH	Not Necessary	270.00 FS	*- FS
11	1		*REAR DOOR WINDOW GUIDE RH	Not Necessary	420.00 FS	*- FS
12	1		*REAR DOOR WINDOW REGULATOR RH	Not Necessary	268.00 FS	*- FS
13	1		*REAR DOOR LOCK RH	Not Necessary	543.00 FS	*- FS
14	1		*REAR DOOR PANEL RH	Not Necessary	1,651.00 FS	*- FS
15	1		*REAR DOOR HINGE RH-UPPER	Not Necessary	44.00 FS	*- FS
16	1		*REAR DOOR HINGE HALVE RH-UPPER	Not Necessary	46.00 FS	*- FS
17	1		*REAR DOOR HINGE RH-LOWER	Bent	47.00 FS	*37.60 FS
18	1		*REAR DOOR HINGE HALVE RH-LOWER	Bent	48.00 FS	*37.84 FS
19	1		*FRONT DOOR RH	Bent	2,767.00 FS	*2,213.60 FS
20	1		*FRONT DOOR OUTER SEAL RH	Necessary	128.40 FS	*128.40 FS
21	1		*BONDING AGENT	Not Necessary	49.00 FS	*- FS
22	1		*CLEANING SOLUTION	Not Necessary	68.00 FS	*- FS
23	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
24	1		*FRONT DOOR ATTACHMENT PARTS RH	Not Necessary	241.00 FS	*- FS
25	1		*FRONT DOOR CATCH RH	Not Necessary	105.00 FS	*- FS
26	1		*FRONT DOOR DATA PLATE FOR TYRE PRESSURE	Necessary	30.00 FS	*24.00 FS
27	1		*ARYCLIX SEALANT	Necessary	180.00 FS	*180.00 FS
28	1		*CAVITH WAX	Necessary	140.00 FS	*140.00 FS
29	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
30	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
31	1		*SUNDRIES	Necessary	350.00 FS	*28.40 FS
32	1		*REAR DOOR WIRE HARNESS - RH (Supplementary)	Cut	334.00 FS	*267.20 FS
33	1		*B-PILLAR INNER PANEL - RH (Supplementary)	Bent	1,316.00 FS	*1,052.80 FS

F=Franchise part. S=SpcNett.

Total Parts (\$)	15,273.40	8,746.24
-------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT AND REAR DOORS;MULTI-LOCK SYSTEMS AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES AND RENEW IF NECESSARY	New	700.00	700.00
2	TO REMOVE AND REINSTALL RHS FRONT SEAT ASSY,ABCD PILLARS TRIMS,SILL TRIMS,FLOOR CARPETS,ELECTRONIC COMPONENTS AND FUSE TRAYS.DISENGAGE RHS SEAT BELT AND HEAD AIRBAG	New	1,800.00	1,800.00
3	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR-O-LINER	New	800.00	800.00
4	TO PUT UP THE VEHICLE ON CAR-O-LINER TO FACILITATE THE REPAIR	New	2,400.00	2,400.00
5	TO DISMANTLE AND RENEW RHS FRONT DOOR AND RHS REAR DOOR.TO CUT OUT AND WELD RHS SILL PANEL AND RHS B-PILLAR.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	4,900.00	3,000.00
6	TO RESPRAY RHS FRONT DOOR,RHS REAR DOOR,HINGES,DOOR ENTRANCES,RHS SILL PANEL AND RHS B-PILLAR.TO CARRY OUT JOINT SEALER WORKS AND CARRY OUT STONE CHIP TREATMENT	New	4,500.00	2,200.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
8	TO CUT OUT AND WELD RHS B-PILLAR INNER REINFORCEMENT PANEL (Supplementary)	New	2,000.00	1,500.00
9	TO RESPRAY RHS B-PILLAR INNER REINFORCEMENT (Supplementary)	New	900.00	550.00
Gross Labour Cost (S\$)			18,192.00	13,142.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >