

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/III21002225/ABA3Q2
Date: 08/07/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MPC0006416
Claimant Vehicle No :	SMQ4118A	Insured Vehicle No :	SKU977R
Date of Loss:	10/02/2021	Nature of Claim:	TP
		Claim No:	MPC2021D0000695

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ4118A	Engine No:	G4FGKU152515
Make & Model:	HYUNDAI AD AVANTE, 1.6 GLS S (A)	Chassis No:	KMHD841CMKU916080
Reg. Date:	15/11/2019 (Man. Year: 2019)	Odometer:	22653 km
Colour:	Blue		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,482.56	12,580.40	5,902.16	31.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,880.00	4,140.00	3,740.00	47.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,362.56	16,720.40	9,642.16	36.58
Approved Total (Overridden) (S\$)		13,300.00		

(S\$)	26,362.56	13,300.00	13,062.56	49.55
+ GST 7.00/7.00% (S\$)	1,845.38	931.00	914.38	49.55
Nett Amount (S\$)	28,207.94	14,231.00	13,976.94	49.55
+ Loss of Use (19.0 x S\$100.00/day) (S\$)		1,900.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		50.00		
Nett Liability (S\$)		16,188.45		
Global Sum Settlement (S\$)		15,700.00		

INSPECTION

Date of Assignment: 16/02/2021

Date Inspected: 16/02/2021

Inspected At:

MG Solution Pte Ltd (HQ)
 23 Kaki Bukit Avenue 4 #02-03B, VICOM Inspection Centre
 Singapore 415933

Estimated Period of Repair: 14.0 days

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Jun 2021)
Parts:	143	HYUNDAI AD AVANTE 1.6 GLS S (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMQ4118A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Dented	1,855.30 FL	*1,741.00 FL
2	1		*FRONT BONNET LOCK	Damaged	230.00 FL	*129.00 FL
3	1		*FRONT BUMPER	Deformed	720.00 FL	*474.00 FL
4	2		*FRONT BUMPER SIDE RETAINER	Necessary	124.80 FL	*70.00 FL
5	1		*FRONT BUMPER NUMBER PLATE GARNISH	Cracked	150.30 FL	*150.30 FL
6	1		*FRONT BUMPER REINFORCEMENT BAR	Bent	480.00 FL	*385.00 FL
7	1		*FRONT BUMPER REINFORCEMENT BAR SPONGE	Cracked	160.00 FL	*160.00 FL
8	1		*FRONT CENTRE GRILLE	Cracked	1,085.20 FL	*460.00 FL
9	1		*FRONT CENTRE GRILLE LOGO	Necessary	90.00 FL	*90.00 FL
10	2		*HEADLAMP	Cut	3,710.60 FL	*3,710.60 FL
11	2		*HEADLAMP LOWER BRACKET	Not Necessary	100.00 FL	*- FL
12	1		*FRONT FENDER LH	Repair	755.30 FL	*- FL
13	1		*SUPPORT PANEL	Cracked	1,188.30 FL	*859.00 FL
14	1		*BOOTLID	Dented	1,820.30 FL	*1,820.30 FL
15	1		*BOOTLID LOGO	Necessary	88.20 FL	*88.20 FL
16	1		*BOOTLID EMBLEM AVANTE	Necessary	130.00 FL	*130.00 FL
17	2		*BOOTLID HINGE	Not Necessary	285.00 FL	*- FL
18	1		*BOOTLID LOCK	Damaged	255.60 FL	*116.00 FL
19	1		*BOOTLID WEATHERSTRIP	Cut	210.00 FL	*210.00 FL
20	1		*BOOTLID DETECTOR	Not Necessary	188.20 FL	*- FL
21	1		*REAR BUMPER	Distorted	630.00 FL	*474.00 FL
22	1		*REAR BUMPER LOWER LID	Distorted	420.00 FL	*353.00 FL
23	2		*REAR BUMPER RETAINER	Necessary	119.20 FL	*119.20 FL
24	2		*REAR BUMPER REFLECTOR	Cracked	320.00 FL	*320.00 FL
25	2		*REAR BUMPER INNER HOCK	Damaged	150.00 FL	*90.00 FL
26	1		*REAR BUMPER REINFORCEMENT	Bent	422.00 FL	*339.00 FL
27	2		*REAR BUMPER REINFORCEMENT BRACKET	Bent	361.20 FL	*361.20 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*SET NUMBER PLATE LAMP	Cracked	120.00 FL	*120.00 FL
29	1		*REAR NUMBER PLATE GARNISH	Deformed	150.30 FL	*150.30 FL
30	2		*TAILLAMP	Cracked	910.60 FL	*910.60 FL
31	1		*TAILLAMP PANEL	N/S Dented	420.00 FL	*210.00 FL
32	1		*REAR END PANEL	Distorted	577.30 FL	*577.30 FL
33	1		*REAR END PANEL TOP GARNISH	Deformed	180.10 FL	*180.10 FL
34	1		*REAR FLOOR PANEL	Repair	1,060.30 FL	*- FL
35	1		*REAR FLOOR PANEL TOP BOARD	Deformed	430.00 FL	*246.00 FL
36	1		*EXHAUST PIPE SILENT	Not Necessary	1,330.70 FL	*- FL
37	1		*EXHAUST PIPE SILENT INSULATION	Not Necessary	230.50 FL	*- FL
38	1		*REAR UNDER COVER LH	Torn	81.40 FL	*81.40 FL
39	1		*FRONT NUMBER PLATE	Dented	50.00 FS	*50.00 FS
40	1		*SET FRONT BUMPER CLIP	Necessary	20.00 FS	*20.00 FS
41	1		*SET CENTRE GRILLE CLIP	Necessary	20.00 FS	*20.00 FS
42	1		*COOLANT	Necessary	100.00 FS	*40.00 FS
43	1		*REAR NUMBER PLATE	Bent	50.00 FS	*50.00 FS
44	1		*SET REAR BUMPER CLIP	Necessary	20.00 FS	*20.00 FS
45	1		*REAR END PANEL INSULATION SEALANT	Necessary	100.00 FS	*60.00 FS
46	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
47	1		*REAR FLOOR PANEL INSULATION SEALANT	Not Necessary	100.00 FS	*- FS
48	1		*REAR FLOOR PANEL TOP MAT	Not Necessary	550.00 FS	*- FS
49	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	22,790.70	15,605.50
- List Item Discount on L Items 20.00/20.00% (\$\$)	4,308.14	3,025.10
Total Parts (\$\$)	18,482.56	12,580.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,REMOVING AND REPLACING PARTS	New	1,400.00	800.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,400.00	600.00
3	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	New	100.00	60.00
4	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	100.00	60.00
5	REFOCUS HEADLAMP BEAM	New	60.00	30.00
6	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	2,000.00	1,100.00
7	TO SPRAY PAINT AFFECTED AREA	New	2,000.00	1,200.00
8	TO APPLY RUST PROOFING AND TUFF COAT	New	150.00	100.00
9	WIRING CHECK	New	60.00	30.00
10	TRANSFER BOOTLID MECHANISM	New	150.00	60.00
11	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
12	REMOVE AND REFIX REAR EXHAUST PIPE	New	120.00	0.00
13	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	120.00	50.00
14	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	120.00	50.00
Gross Labour Cost (S\$)			7,880.00	4,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >