

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21002234/DQD3Q2

Date: 19/03/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001377646

Claimant
Vehicle No : SMJ8937M

Insured Vehicle No : YP2102X

Date of Loss: 10/02/2021

Nature of Claim: TP

Claim No: 253422

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMJ8937M**

Make & Model: BMW 520D, 2.0 M SPORT (A)

Engine No: 69049953B47D20A

Reg. Date: 29/11/2017 (Man. Year: 2017)

Chassis No: WBAJC320X0WB56554

Colour: White

Odometer: 41602 km

Engine Capacity: 1995 cc

Market Value/New Car

Price: N/A

Sum Insured (\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/35R20

Rear Tyre Size:

245/35R20

Front Left Side: Goodyear 5 mm

Rear Left Side:

Goodyear 5 mm

Front Right Side: Goodyear 5 mm

Rear Right Side:

Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	46,473.80	8,561.79	37,912.01	81.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,500.00	2,360.00	4,140.00	63.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$)	52,973.80	10,921.79	42,052.01	79.38
+ GST 7.00/7.00% (\$)	3,708.17	764.53	2,943.64	79.38
Nett Amount (\$)	56,681.97	11,686.32	44,995.65	79.38

INSPECTION

Date of Assignment: 17/02/2021

Date Inspected: 17/02/2021 Inspected At:

JWG International Pte Ltd (HQ)
Blk 10, Ang Mo Kio Ind Park 2A,, #03-08
AMK AutoPoint
Singapore 568047

Estimated Period of Repair: 6.0 days

Adjuster: BRYAN TANI

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Mar 2021)
Parts:	143	BMW 520D 2.0 M SPORT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMJ8937M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEAD LAMP LH	Not Necessary	3,810.00 F	*- FL
2	1		*HEAD LAMP LOWER BRACKET LH	Not Necessary	198.00 F	*- FL
3	1		*HEAD LAMP ECU LH	Not Necessary	1,680.00 F	*- FL
4	1		*HEAD LAMP WIRE HARNESS	Not Necessary	1,992.00 F	*- FL
5	1		*FRONT BUMPER	Not Necessary	2,901.00 F	*- FL
6	2		*FRONT BUMPER SIDE RETAINER LH/RH	Not Necessary	390.00 F	*- FL
7	1		*FRONT FENDER LH	Repair	2,110.00 F	*- FL
8	1		*FRONT FENDER INNER SHIELD LH	Not Necessary	201.00 F	*- FL
9	1		*SIDE MIRROR ASSY LH	Broken	3,015.00 F	*1,682.00 FL
10	1		*SIDE MIRROR ASSY GARNISH LH	Broken	384.00 F	*384.00 FL
11	1		*FRONT DOOR LH	Dented	2,560.00 F	*1,951.40 FL
12	1		*FRONT DOOR WINDOW LH	Scratched	1,982.40 F	*485.00 FL
13	1		*FRONT DOOR WINDOW MOULDING LH	Cut/Scratched	310.00 F	*310.00 FL
14	1		*FRONT DOOR BLACK PLASTIC LH	Necessary	194.00 F	*194.00 FL
15	1		*FRONT DOOR HANDLE LH	Repair	298.00 F	*- FL
16	1		*FRONT DOOR HANDLE CHROME LH	Not Necessary	329.00 F	*- FL
17	1		*FRONT DOOR LOCK LH	Not Necessary	432.00 F	*- FL
18	1		*FRONT DOOR WEATHER STRIP INNER LH	Not Necessary	493.00 F	*- FL
19	1		*FRONT DOOR WEATHER STRIP OUTER LH	Necessary	480.00 F	*163.15 FL
20	1		*FRONT DOOR INNER TRIM BOARD LH	Not Necessary	1,692.00 F	*- FL
21	1		*FRONT DOOR WINDOW MOTOR LH	Not Necessary	1,149.00 F	*- FL
22	1		*FRONT DOOR WINDOW REGULATOR LH	Not Necessary	690.00 F	*- FL
23	1		*REAR DOOR LH	Broken	2,830.00 F	*1,951.40 FL
24	1		*REAR DOOR WINDOW LH	Not Necessary	1,992.40 F	*- FL
25	1		*REAR DOOR WINDOW MOULDING LH	Bent	340.00 F	*340.00 FL
26	1		*REAR DOOR BLACK PLASTIC LH	Necessary	199.00 F	*199.00 FL
27	1		*REAR DOOR HANDLE LH	Not Necessary	194.00 F	*- FL
28	1		*REAR DOOR LOCK LH	Not Necessary	452.00 F	*- FL
29	1		*REAR DOOR WEATHER STRIP INNER LH	Not Necessary	499.00 F	*- FL
30	1		*REAR DOOR WEATHER STRIP OUTER LH	Necessary	495.00 F	*163.15 FL
31	1		*REAR DOOR INNER TRIM BOARD LH	Not Necessary	1,701.00 F	*- FL
32	1		*REAR DOOR WINDOW MOTOR LH	Not Necessary	1,182.00 F	*- FL
33	1		*REAR DOOR WINDOW REGULATOR LH	Not Necessary	679.00 F	*- FL
34	1		*SIDE SKIRT LH	Not Necessary	1,918.00 F	*- FL
35	1		*ROCKER PANEL LH	Not Necessary	2,192.00 F	*- FL
36	1		*CENTER PILLAR LH	Not Necessary	2,390.00 F	*- FL
37	1		*SIDE MIRROR CAMERA LH	Damaged	1,690.00 F	*1,690.00 FL
38	1		*HEAD LAMP CLIPS	Not Necessary	50.00 FS	*- FS
39	1		*FRONT BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
40	1		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS
41	1		*SIDE MIRROR GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
42	1		*FRONT DOOR INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
43	1		*REAR DOOR INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*SIDE SKIRT CLIPS	Not Necessary	50.00 FS	*- FS
45	1		*ROCKER PANEL SEALANT	Not Necessary	80.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
				Sub Total (\$\$)	46,473.80	9,513.10
				- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	951.31
				Total Parts (\$\$)	46,473.80	8,561.79

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILITATE REPAIRS	New	400.00	120.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,400.00	1,000.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,400.00	800.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
5	TO RNR FRONT DOOR MECHANISM TO FACILITATE REPAIRS	New	250.00	80.00
6	TO RNR REAR DOOR MECHANISM TO FACILITATE REPAIRS	New	250.00	80.00
7	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	New	200.00	60.00
8	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS.RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	180.00
Gross Labour Cost (S\$)			6,500.00	2,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >