

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21002237/AGA3Q2**Date:** 19/05/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070028266
Claimant Vehicle No :	SLS5720E	Insured Vehicle No :	SKE4100L
Date of Loss:	09/02/2021	Nature of Claim:	TP
		Claim No:	4171649142SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS5720E		
Make & Model:	MERCEDES-BENZ C180, 1.6 Avantgarde (R17 LED) (A)	Engine No:	27491031025405
Reg. Date:	28/09/2017 (Man. Year: 2017)	Chassis No:	WDD2050402R300728
Colour:	White	Odometer:	62359 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,776.00	2,956.00	6,820.00	69.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,480.00	810.00	670.00	45.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,256.00	3,766.00	7,490.00	66.54
Approved Total (Overridden) (S\$)		3,000.00		
Nett Amount (S\$)	11,256.00	3,000.00	8,256.00	73.35
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
(S\$)		3,180.00		
Liabile Amount (50.00%) (S\$)		1,590.00		

INSPECTION

Date of Assignment:	10/02/2021	Advance Auto Garage (HQ) 23 KAKI BUKIT AVENUE 4 #04-01 AAS KAKI BUKIT CENTRE Singapore 415933
Date Inspected:	10/02/2021 Inspected At:	
Estimated Period of Repair:	3.0 days	

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,510.00 F	*1,510.00 FL
2	1		*FRONT BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
3	1		*FRONT BUMPER SIDE HOLDER LH	Not Necessary	79.00 F	*- FL
4	1		*FRONT LH WHEEL RIM	Cut	1,350.00 FS	*850.00 FS
5	1		*FRONT LH LOWER ARM	Bent	335.00 F	*335.00 FL
6	1		*FRONT LH KNUCKLE ARM	Not Necessary	1,208.00 F	*- FL
7	1		*FRONT LH WHEEL HUB C/W BEARING	Damaged	495.00 F	*495.00 FL
8	1		*FRONT LH SHOCK ABSORBER	Not Necessary	749.00 F	*- FL
9	1		*HEADLAMP LH	Not Necessary	3,650.00 F	*- FL
10	1		*FRONT LH TYRE	Not Necessary	350.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$\$)	9,776.00 3,190.00
- List Item Discount on L Items 0.00/10.00% (\$\$)					0.00	234.00
					Total Parts (\$\$)	9,776.00 2,956.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	400.00	250.00
2	SPRAY PAINTING	New	400.00	250.00
3	WIRING	New	50.00	30.00
4	TO REMOVE FRONT BUMPER SENSOR	New	100.00	50.00
5	TO REMOVE FRONT UNDERCARRIAGE	New	380.00	150.00
6	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
Gross Labour Cost (\$)			1,480.00	810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >