

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG21002238/KPA3Q2
Date: 12/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070121422
Claimant Vehicle No :	SHF785S	Insured Vehicle No :	GBF3812Z
Date of Loss:	15/02/2021	Nature of Claim:	TP
		Claim No:	3737615079SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHF785S		
Make & Model:	RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR (A)	Engine No:	M9R8839C003389
Reg. Date:	30/06/2016 (Man. Year: 2015)	Chassis No:	VF1ABL15AUC283341
Colour:	Metallic White/Red	Odometer:	468092 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Falken 7 mm	Rear Left Side:	Sailun 9 mm
Front Right Side:	Falken 7 mm	Rear Right Side:	Sailun 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,886.48	8,431.12	18,455.36	68.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,580.00	3,880.00	3,700.00	48.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	34,466.48	12,311.12	22,155.36	64.28
Approved Total (Overridden) (S\$)		9,750.00		
(S\$)	34,466.48	9,750.00	24,716.48	71.71
+ GST 7.00/7.00% (S\$)	2,412.65	682.50	1,730.15	71.71
Nett Amount (S\$)	36,879.13	10,432.50	26,446.63	71.71
+ Loss of Use (16.0 x S\$50.00/day) (S\$)		800.00		
+ Car Rental (16.0 x S\$81.13/day) (S\$)		1,298.08		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		12,538.03		
Global Sum Settlement (S\$)		12,500.00		

INSPECTION

Date of Assignment:	16/02/2021		
Date Inspected:	16/02/2021	Inspected At:	Trans-Cab Auto Services Pte Ltd (HQ) 2 Ang Mo Kio Street 63 Singapore 569111

5/12/2021

Adjuster Report

Estimated Period of Repair: 16.0 days

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Bent	561.70 FL	*561.70 FL
2	1		*BUMPER LOWER REAR	Missing	411.90 FL	*411.90 FL
3	1		*BUMPER REFLECTOR LH	Cracked	16.60 FL	*16.60 FL
4	1		*BUMPER BRACKET CTR REAR	Distorted	98.10 FL	*98.10 FL
5	1		*BUMPER BRACKET SIDE RH REAR	Distorted	82.10 FL	*82.10 FL
6	1		*BUMPER RETAINER RH REAR	Distorted	59.80 FL	*59.80 FL
7	1		*BUMPER BRACKET SIDE LH REAR	Distorted	80.80 FL	*80.80 FL
8	1		*BUMPER RETAINER LH REAR	Distorted	54.20 FL	*54.20 FL
9	1		*ABSORBER REAR	No such part	217.30 FL	*- FL
10	1		*BUMPER BEAM REAR	Bent	547.80 FL	*547.80 FL
11	1		*BUMPER BEAM BRACKET LH REAR	Bent	114.50 FL	*114.50 FL
12	1		*BUMPER BEAM BRACKET RH REAR	Bent	114.50 FL	*114.50 FL
13	1		*OUTER PANEL REAR (END PANEL)	Bent	745.80 FL	*745.80 FL
14	1		*OUTER PANEL REAR (END PANEL)TRIM	Dented	404.56 FL	*404.56 FL
15	1		*SPARE WHEEL PANEL	Bent / Buckled	1,229.40 FL	*1,229.40 FL
16	1		*SPARE WHEEL PANEL BRACKET LH	Repair	70.60 FL	*- FL
17	1		*SPARE WHEEL PANEL BRACKET RH	Repair	69.20 FL	*- FL
18	1		*FUEL FLAP	Serviceable	244.70 FL	*- FL
19	1		*FENDER PANEL FRT RH	Repair	437.10 FL	*- FL
20	1		*FENDER PANEL FRT LH	Repair	437.10 FL	*- FL
21	1		*FENDER PANEL INNER REAR LH	Repair	1,241.60 FL	*- FL
22	1		*FENDER PANEL INNER REAR RH	Repair	1,241.60 FL	*- FL
23	1		*SPARE TYRE BOARD	Serviceable	680.90 FL	*- FL
24	1		*FENDER INNER BOARD LH	Serviceable	561.40 FL	*- FL
25	1		*FENDER INNER BOARD RH	Serviceable	561.40 FL	*- FL
26	1		*WHEEL HOUSE PRE ASSY LH (CENTER)	Repair	1,241.60 FL	*- FL
27	1		*WHEEL HOUSE PRE ASSY RH (CENTER)	Repair	1,241.60 FL	*- FL
28	1		*SILL PANEL OUTER LH (BENT)	Not Consistent With The Impact	1,902.00 FL	*- FL
29	1		*SILL PANEL INNER LH (BENT)	Not Consistent With The Impact	483.20 FL	*- FL
30	1		*SILL PANEL OUTER RH (Repair)	Not Consistent With The Impact	1,856.50 FL	*- FL
31	1		*SILL PANEL INNER RH (Repair)	Not Consistent With The Impact	371.10 FL	*- FL
32	1		*TAILLAMP LH	Cracked	401.40 FL	*401.40 FL
33	1		*TAILLAMP RH	Cracked	401.40 FL	*401.40 FL
34	1		*EXHAUST REAR	Repair	5,263.60 FL	*- FL
35	1		*EXHAUST BRACKET REAR	Serviceable	24.80 FL	*- FL
36	1		*EXHAUST CAP REAR	Dented	125.40 FL	*125.40 FL
37	1		*BOOT REAR	Bent	1,677.20 FL	*1,677.20 FL
38	1		*BOOT BADGE RENAULT	Necessary	82.40 FL	*82.40 FL
39	1		*BOOT BADGE	Necessary	95.80 FL	*95.80 FL
40	1		*BOOT REFLECTOR LAMP LH	Cracked	277.70 FL	*277.70 FL
41	1		*BOOT REFLECTOR LAMP RH	Cracked	277.70 FL	*277.70 FL
42	1		*BUMPER REFLECTOR LH	Repeated	16.60 FL	*- FL
43	1		*BUMPER REFLECTOR RH	Cracked	16.60 FL	*16.60 FL
44	1		*BOOT HINGE LH	Bent	254.20 FL	*254.20 FL
45	1		*BOOT HINGE RH	Bent	254.20 FL	*254.20 FL
46	1		*BOOT STRUT LH	Serviceable	145.10 FL	*- FL
47	1		*BOOT STRUT RH	Serviceable	145.10 FL	*- FL
48	1		*BOOT LOCK LINKAGE	Serviceable	20.60 FL	*- FL
49	1		*BOOT LOCK LINKAGE HOLDER	Serviceable	99.50 FL	*- FL
50	1		*BOOT LOCK	Jammed	246.60 FL	*246.60 FL
51	1		*BOOT LOCK CATCH	Repair	41.70 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*BOOT FINISHER	Serviceable	344.70 FL	*- FL
53	1		*SET PARKING AID	Shorted	700.00 FS	*400.00 FS
54	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
55	1		*SET BUMPER BRACKET CTR CLIP	Not Necessary	33.00 FS	*- FS
56	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
57	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
58	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
59	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
60	1		*SET BONNET LOCK NUT	Not Necessary	60.00 FS	*- FS
61	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
62	1		*EXHAUST MOUNTING REAR	Serviceable	17.82 FS	*- FS
63	1		*REAR BOOT STICKER TRANS-CAB	Necessary	80.00 FS	*30.00 FS
64	1		*REAR BOOT STICKER 6555-3333	Necessary	80.00 FS	*30.00 FS
65	1		*BUMPER CLIP FRT	Not Necessary	85.00 FS	*- FS
66	1		*BUMPER RETAINER CLIP FRT	Not Necessary	70.00 FS	*- FS
67	1		*BUMPER GRILLE LOWER CLIP	Not Necessary	70.00 FS	*- FS
68	1		*BUMPER FOG LAMP GRILLE CLIP	Not Necessary	65.00 FS	*- FS
69	1		*LICENSE PLATE WITH HOLDER FRT	Serviceable	120.00 FS	*- FS
70	2		*WINDSCREEN SEALANT	Necessary	150.00 FS	*40.00 FS
71	1		*WINDSCREEN MOULDING	Not Necessary	200.00 FS	*- FS
72	1		*WINDSCREEN INNER SPONGE SEAL	Necessary	130.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	29,645.78	9,294.36
- List Item Discount on L Items 10.00/10.00% (\$)	2,759.30	863.24
Total Parts (\$)	26,886.48	8,431.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	1,320.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	3,000.00	2,000.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	120.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
5	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	60.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE }	New	170.00	60.00
7	TO DROP REAR EXHAUST BOX ,RENEW THE SAME ,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE }	New	170.00	0.00
8	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	120.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
10	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
11	TO TRANSFER OF REAR WINDSCREEN FITTINGS CONDUCT WATER SEEPAGE TEST	New	170.00	120.00
Gross Labour Cost (\$\$)			7,580.00	3,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >