



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 8

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 5512R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	COVER ,REAR BUMPER	BENT	442.60	442.60
1	REINFORCEMENT SUB-ASSY ,REAR BUMPER	BENT	332.70	332.70
1	COVER ,REAR BUMPER LOWER	MISSING	15.40	15.40
1	GUARD ,REAR BUMPER ,CENTER	BENT	576.30	576.30
1	RETAINER ,REAR BUMPER SIDE ,LH	MTG CRACKED	116.50	116.50
1	RETAINER ,REAR BUMPER SIDE ,RH	MTG CRACKED	117.70	117.70
1	FILLER ,REAR BUMPER EXTENSION ,RH	MTG CRACKED	123.70	123.70
1	FILLER ,REAR BUMPER EXTENSION ,LH	MTG CRACKED	123.70	123.70
1	PANEL SUB-ASSY ,BACK DOOR	BENT	1,147.80	1,147.80
1	GARNISH SUB-ASSY ,BACK DOOR ,OUTSIDE	CRACKED	925.60	925.60
1	COVER ,REAR COMBINATION LAMP ,RH	SERVICEABLE	64.50	-
1	COVER ,REAR COMBINATION LAMP ,LH	SERVICEABLE	64.50	-
1	BOARD ASSY ,BACK DOOR TRIM	MTG CRACKED	259.20	259.20
1	WEATHERSTRIP ,BACK DOOR	DISTORTED /DENTED	372.30	372.30
1	MOULDING ,BACK DOOR OUTSIDE GARNISH ,LOWER RH	SERVICEABLE	56.50	-
1	BOARD ,BACK DOOR TRIM	REPEATED	225.20	-
1	LENS & BODY ,REAR COMBINATION LAMP ,LH	CRACKED	443.30	443.30
1	LENS & BODY ,REAR COMBINATION LAMP ,RH	CRACKED	451.80	451.80
1	LENS AND BODY ,REAR LAMP ,LH	SCRATCHED	502.00	502.00
1	LENS AND BODY ,REAR LAMP ,RH	CUT	502.00	502.00
1	PANEL ASSY ,DECK TRIM SIDE ,RH	SERVICEABLE	355.90	-
1	BOX ,DECK FLOOR ,RH	SERVICEABLE	313.60	-
1	BOX ,DECK FLOOR ,LH	SERVICEABLE	313.00	-
1	BOARD ,REAR FLOOR ,NO.1	SERVICEABLE	519.00	-
1	COVER ASSY ,TONNEAU	SERVICEABLE	979.40	-
1	BOX ,DECK FLOOR REAR	SERVICEABLE	105.80	-
1	PANEL ASSY ,DECK TRIM SIDE ,LH	SERVICEABLE	355.90	-
1	MOULDING ,BACK DOOR OUTSIDE GARNISH ,LOWER LH	SERVICEABLE	56.50	-
1	DUCT ASSY ,QUARTER VENT ,RH	SERVICEABLE	67.00	-

Report Ref No. CC3/TP21002240/Kga3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	PANEL SUB-ASSY ,QUARTER ,RH	TO REPAIR SEE LABOUR	871.50	-
1	LINER ,REAR WHEEL HOUSE ,RH	SERVICEABLE	139.80	-
1	SEAL ,REAR BUMPER SIDE ,RH	SERVICEABLE	88.50	-
1	TROUGH ,BACK DOOR OPENING ,LH	SERVICEABLE	103.40	-
1	TROUGH ,BACK DOOR OPENING ,RH	SERVICEABLE	103.40	-
1	COVER ,FLOOR UNDER ,NO.1	SERVICEABLE	175.10	-
1	COVER ,FLOOR UNDER ,NO.2	SERVICEABLE	241.90	-
1	COVER ,REAR FLOOR	MISSING	229.90	229.90
1	COVER ,DECK TRIM ,REAR	SERVICEABLE	126.70	-
1	PAN ,REAR FLOOR	TO REPAIR SEE LABOUR	583.40	-
1	EXTENSION ,REAR FLOOR PAN TO QUARTER PANEL,LH	TO REPAIR SEE LABOUR	196.50	-
1	EXTENSION ,REAR FLOOR SIDE PANEL ,LH	SERVICEABLE	78.30	-
1	INSULATOR ,MAIN MUFFLER HEAT ,RH	SERVICEABLE	141.00	-
1	PANEL SUB-ASSY ,BODY LOWER BACK	TO REPAIR SEE LABOUR	651.00	-
1	LOCK ASSY ,BACK DOOR ,W/COURTESY LAMP SWITCH	TO REPAIR SEE LABOUR	467.00	-
1	SWITCH ASSY ,BACK DOOR OPENER	SERVICEABLE	179.10	-
1	COVER ,BACK DOOR LOCK	TO REPAIR SEE LABOUR	30.20	-
1	SEAL ,REAR BUMPER SIDE ,LH	SERVICEABLE	88.50	-
1	PANEL SUB-ASSY ,QUARTER ,LH	TO REPAIR SEE LABOUR	871.50	-
1	LINER ,REAR WHEEL HOUSE ,LH	SERVICEABLE	139.80	-
1	DUCT ASSY ,QUARTER VENT ,LH	SERVICEABLE	67.00	-
1	SPOILER SUB ASSY ,REAR	TO REPAIR SEE LABOUR	1,575.40	-
1	SEAL ,REAR SPOILER	NECESSARY	16.70	16.70
1	PROTECTOR ,REAR SPOILER ,NO.4	SERVICEABLE	16.70	-
1	PROTECTOR ,REAR SPOILER ,NO.3	SERVICEABLE	16.70	-
1	PROTECTOR ,REAR SPOILER ,NO.1	SERVICEABLE	16.70	-
1	LAMP SET ,STOP CENTER	SCRATCHED	192.30	192.30
1	LAMP SUB-ASSY ,LICENSE PLATE	SERVICEABLE	287.80	-

Report Ref No. CC3/TP21002240/Kga3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	GLASS ,BACK WINDOW FIX	SHATTERED	761.40	761.40
1	MOULDING ,BACK WINDOW ,LOWER NO.2	NECESSARY	23.60	23.60
1	MOULDING ,BACK WINDOW ,OUTSIDE LH NO.2	NECESSARY	30.90	30.90
1	MOULDING ,BACK WINDOW ,OUTSIDE RH NO.2	NECESSARY	30.90	30.90
1	DAM ,BACK DOOR GLASS ADHESIVE .NO.2	NECESSARY	28.90	28.90
1	WIRE ,LUGGAGE ROOM ,NO.3	SERVICEABLE	170.70	-
1	WIRE ,BACK DOOR ,NO.2	SERVICEABLE	294.40	-
1	WIRE ,BACK DOOR ,NO.1	SERVICEABLE	247.40	-
1	SOCKET & WIRE SUB-ASSY REAR COMBINATION LAMP ,LH	SERVICEABLE	63.30	-
1	SOCKET & WIRE SUB-ASSY REAR COMBINATION LAMP ,RH	SERVICEABLE	63.30	-
1	STAY ASSY ,BACK DOOR ,LH	SERVICEABLE	242.50	-
1	STAY ASSY ,BACK DOOR ,RH	SERVICEABLE	242.50	-
1	HINGE ASSY ,BACK DOOR ,LH	TO REPAIR SEE LABOUR	61.00	-
1	HINGE ASSY ,BACK DOOR ,RH	TO REPAIR SEE LABOUR	61.00	-
1	HANDLE ,DOOR PULL	MISSING	23.40	23.40
1	COVER ,FRONT BUMPER	BENT	516.00	516.00
1	BRACKET ,FRONT BUMPER EXTENSION MOUNTING	DISTORTED	103.40	103.40
1	REINFORCEMENT SUB-ASSY ,FRONT BUMPER	BENT	716.60	716.60
1	REINFORCEMENT ,FRONT BUMPER ,NO.2	DISTORTED	246.10	246.10
1	ABSORBER ,FRONT BUMPER ,LOWER	CRACKED	132.70	132.70
1	ABSORBER ,FRONT BUMPER ENERGY	SERVICEABLE	79.60	-
1	SUPPORT ,FRONT BUMPER SIDE ,RH	SERVICEABLE	80.10	-
1	SUPPORT ,FRONT BUMPER SIDE ,LH	DISTORTED	82.30	82.30
1	COVER ,ENGINE UNDER NO.1	SERVICEABLE	472.40	-
1	COVER SUB-ASSY ,ENGINE UNDER NO.2	SERVICEABLE	241.90	-
1	EXTENSION ,FRONT BUMPER ,RH	SERVICEABLE	120.10	-
1	EXTENSION ,FRONT BUMPER ,LH	SERVICEABLE	120.10	-
1	COVER ,FRONT BUMPER HOLE ,LH	CRUMPLED	29.30	29.30
1	COVER ,FRONT BUMPER HOLE ,RH	DENTED	29.30	29.30
1	LAMP ASSY ,FOG, LH	SERVICEABLE	951.40	-
1	LAMP ASSY ,FOG, RH	SERVICEABLE	951.40	-

Report Ref No. CC3/TP21002240/Kga3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	UNIT ASSY ,HEADLAMP ,LH	MTG BROKEN	2,637.60	2,637.60
1	COMPUTER SUB-ASSY ,HEADLAMP ,LH NO.1	SERVICEABLE	960.50	-
1	UNIT ASSY ,HEADLAMP ,RH	CRACKED	2,637.60	2,637.60
1	COMPUTER SUB-ASSY ,HEADLAMP ,RH NO.1	SERVICEABLE	960.50	-
1	MOTOR HEADLAMP LEVELING ,RH	SERVICEABLE	487.50	-
1	GRILLE SUB-ASSY ,RADIATOR	CRACKED	346.00	346.00
1	GRILLE ,RADIATOR ,LOWER NO.1	DISTORTED	170.10	170.10
1	EMBLEM ASSY ,RADIATOR GRILLE	NECESSARY	90.80	90.80
1	FENDER SUB-ASSY ,FRONT LH	BUCKLED	977.80	977.80
1	LINER ,FRONT FENDER ,LH	SERVICEABLE	202.50	-
1	EMBLEM ,SIDE PANEL	NECESSARY	54.60	54.60
1	SUPPORT ,RADIATOR ,UPPER RH	SERVICEABLE	78.90	-
1	SUPPORT ,RADIATOR ,UPPER LH	SERVICEABLE	78.90	-
1	SUPPORT SUB-ASSY ,RADIATOR ,UPPER	BENT	377.10	377.10
1	SUPPORT SUB-ASSY ,RADIATOR ,LOWER	SERVICEABLE	409.90	-
1	SUPPORT SUB-ASSY ,RADIATOR,LH	SERVICEABLE	245.10	-
1	SUPPORT SUB-ASSY ,RADIATOR ,RH	SERVICEABLE	245.10	-
1	HOOD SUB-ASSY	BUCKLED	983.10	983.10
1	HINGE ASSY ,HOOD ,LH	DISTORTED	58.90	58.90
1	HINGE ASSY ,HOOD ,RH	DISTORTED	58.90	58.90
1	BRACE ,HOOD LOCK SUPPORT	BENT	78.30	78.30
1	INSULATOR HOOD	DEFORMED	410.90	410.90
1	LOCK ASSY ,HOOD	DISTORTED	135.00	135.00
1	CABLE ASSY ,HOOD LOCK CONTROL	SERVICEABLE	54.90	-
1	SUPPORT ASSY ,HOOD	SERVICEABLE	44.20	-
1	SEAL ,HOOD TO FRONT END PANEL	SERVICEABLE	51.60	-
1	WIRE ,ENGINE ROOM MAIN	SERVICEABLE	7,323.90	-
1	HORN ASSY ,HIGH PITCHED	SERVICEABLE	134.80	-
1	HORN ASSY ,LOW PITCHED	SERVICEABLE	134.80	-
1	GUIDE ,RADIATOR AIR ,NO.1 LH	SERVICEABLE	69.90	-
1	GUIDE ,RADIATOR AIR ,NO.1 RH	SERVICEABLE	65.30	-
1	GUIDE ,RADIATOR AIR ,NO.3	SERVICEABLE	112.70	-
1	GUIDE ,RADIATOR AIR ,NO.2	SERVICEABLE	53.40	-

Report Ref No. CC3/TP21002240/Kga3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SEAL ,RADIATOR TO SUPPORT ,NO.3	SERVICEABLE	32.40	-
1	SEAL ,RADIATOR TO SUPPORT ,NO.2	SERVICEABLE	32.60	-
1	INLET ,AIR CLEANER NO.1	SERVICEABLE	155.60	-
1	INLET ,AIR CLEANER NO.3	SERVICEABLE	42.10	-
1	INLET ,AIR CLEANER NO.2	SERVICEABLE	112.70	-
1	HOSE ,AIR CLEANER ,NO.1	SERVICEABLE	74.00	-
1	JAR ASSY ,WINDSHIELD WASHER	SERVICEABLE	219.10	-
1	MOTOR AND PUMP ASSY ,WINDSHIELD WASHER	SERVICEABLE	292.40	-
1	INLET SUB-ASSY ,WASHER	SERVICEABLE	67.00	-
1	CONDENSER ASSY ,COOLER	SERVICEABLE	1,783.20	-
1	HOSE SUB-ASSY ,SUCTION	SERVICEABLE	646.80	-
1	HOSE SUB-ASSY ,DISCHARGE	SERVICEABLE	402.90	-
1	PIPE SUB-ASSY ,SUCTION	SERVICEABLE	465.80	-
1	SENSOR ,AIRCONDITIONER PRESSURE	SERVICEABLE	342.80	-
1	TUBE & ACCESSORY ASSY ,AIR CONDITIONER	SERVICEABLE	691.00	-
1	COMPRESSOR ASSY ,W/MOTOR	SERVICEABLE	4,771.60	-
1	RADIATOR ASSY	SERVICEABLE	2,218.00	-
1	SHROUD ,FAN	SERVICEABLE	264.70	-
1	FAN ,RH	SERVICEABLE	281.30	-
1	FAN ,LH	SERVICEABLE	219.10	-
1	MOTOR ,COOLING FAN ,LH	SERVICEABLE	655.10	-
1	MOTOR ,COOLING FAN ,RH	SERVICEABLE	535.50	-
1	TANK ASSY ,INVERTER RESERVE	SERVICEABLE	443.00	-
1	INVERTER WATER PUMP ASSY (W/MOTOR)	SERVICEABLE	518.60	-
1	BATTERY	SERVICEABLE	1,584.90	-
1	CLAMP ,BATTERY ,NO.2	SERVICEABLE	51.80	-
1	CLAMP SUB-ASSY ,BATTERY	SERVICEABLE	115.50	-
1	TERMINAL ,BATTERY POSITIVE	SERVICEABLE	58.10	-
1	COVER ,FUSIBLE LINK	SERVICEABLE	33.90	-
1	SENSOR ASSY ,BATTERY STATE	SERVICEABLE	306.10	-
1	BLOCK ASSY ,FUSIBLE LINK	SERVICEABLE	119.60	-
1	TANK RESERVE SEALED W/O CAP	SERVICEABLE	151.40	-
1	CLEANER ASSY ,AIR	CRACKED	1,147.00	1,147.00

Report Ref No. CC3/TP21002240/Kga3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:6 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BRACKET ,HEADLAMP ,LH	SERVICEABLE	34.80	-
1	BRACKET ,HEADLAMP ,RH	SERVICEABLE	34.80	-
1	STAY ,SUB-ASSY ,FRONT BUMPER ,LH	SERVICEABLE	47.50	-
1	STAY ,SUB-ASSY ,FRONT BUMPER ,RH	SERVICEABLE	47.50	-
1	BRACKET ,FRONT BUMPER SIDE ,LH	SERVICEABLE	59.30	-
1	BRACKET ,FRONT BUMPER SIDE ,RH	SERVICEABLE	59.30	-
1	BRACKET ,RADIATOR GRILLE MOULDING ,LH	SERVICEABLE	36.60	-
1	BRACKET ,RADIATOR GRILLE MOULDING ,RH	SERVICEABLE	36.60	-
1	MEMBER SUB-ASSY ,FRONT SIDE ,RH	SERVICEABLE	2,342.30	-
1	COVER ,RADIATOR SUPPORT OPENING	SERVICEABLE	235.30	-
1	THERMISTOR ASSY	SERVICEABLE	80.90	-
1	MEMBER SUB-ASSY ,SIDE ,REAR RH	TO REPAIR SEE LABOUR	288.50	-
1	ACTUATOR ASSY ,SHIFT CONTROL	SERVICEABLE	1,036.40	-
1	COOLER ,MOTOR COOLING	SERVICEABLE	297.20	-
	LESS 25% DISCOUNT		-17,261.70	-4,952.50
			51,785.10	14,857.50
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET PARKING AID (SN)	SHORTED	700.00	220.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	95.00	66.00
2	WINDSCREEN SEALANT (SN)	NECESSARY	150.00	80.00
1	WINDSCREEN MOULDING (SN)	NECESSARY	200.00	200.00
1	WINDSCREEN INNER SPONGE SEAL (SN)	NECESSARY	130.00	30.00
1	REAR TAILGATE TOYOTA LOGO (SN)	NECESSARY	47.90	47.90
1	REAR TAILGATE WORDING 'PRIUS' (SN)	NECESSARY	54.60	54.60
1	REAR TAILGATE WORDING 'HYBRID' (SN)	NECESSARY	54.60	54.60
1	REAR TAILGATE STICKER 'TRANS-CAB' (SN)	NECESSARY	80.00	30.00
1	REAR TAILGATE STICKER '6555-3333' (SN)	NECESSARY	80.00	30.00
1	REAR BUMPER PROTECTOR (SN)	NOT NECESSARY	180.00	-
2	SEAM SEALANT (SN)	NOT NECESSARY	250.00	-
1	SET REAR BUMPER LINER CLIP (SN)	NOT NECESSARY	85.00	-
1	SET REAR BUMPER RETAINER CLIP (SN)	NOT NECESSARY	85.00	-
1	REAR BUMPER PLATE WITH HOLDER (SN)	DENTED	140.00	45.00

Report Ref No. CC3/TP21002240/Kga3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:7 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET TAILLAMP LOWER CLIP (SN)	NOT NECESSARY	55.00	-
1	SET TAILLAMP UPPER CLIP (SN)	NOT NECESSARY	55.00	-
1	END PANEL TRIM CLIP (SN)	NECESSARY	65.00	65.00
1	REAR SPOILER CLIP (SN)	NOT NECESSARY	70.00	-
1	SET BUMPER CLIP FRT (SN)	NECESSARY	95.00	66.00
1	FRONT NUMBER PLATE WITH MOULDING (SN)	DENTED	200.00	45.00
1	SET CLIP, FRONT FENDER LINER (SN)	NOT NECESSARY	85.00	-
1	SET FRONT BUMPER RETAINER CLIP (SN)	NOT NECESSARY	85.00	-
4	L RADIATOR COOLANT (SN)	NECESSARY	120.00	30.00
1	HOOD INSULATOR CLIP (SN)	NOT NECESSARY	55.00	-
1	ENGINE UNDER COVER CLIP (SN)	NOT NECESSARY	60.00	-
			3,277.10	1,064.10
	<b>LABOUR</b>			
	TO REMOVE AND REFIT REAR BIG AND SMALL W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR		300.00	180.00
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR.		380.00	100.00
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF PANEL SUB-ASSY ,QUARTER ,RH ,PAN,REAR FLOOR,EXTENSION ,REAR FLOOR PAN TO QUARTER PANEL,LH,PANEL SUB-ASSY ,BODY LOWER BACK,LOCK ASSY ,BACK DOOR ,W/SCREEN LAMP SWITCH,COVER ,BACK DOOR LOCK,PANEL SUB-ASSY ,QUARTER ,LH, SPOILER ,SUB ASSY ,REAR, }		-	-
	HINGE ASSY ,BACK DOOR ,LH,HINGE ASSY ,BACK DOOR ,RH AND MEMBER SUB-ASSY ,SIDE ,REAR RH.		2,200.00	1,400.00
	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF TAILGATE FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		180.00	60.00
	TO REMOVE AND REFIT ELECTRICAL WIRING ,BATTERY AND OTHER NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	480.00	-
	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	480.00	-

Report Ref No. CC3/TP21002240/Kga3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:8 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE AND REFIT AIRCON ASSY AND ATTACHMENT ,VACUUM AND CHARGE-INER -GAS.	NOT NECESSARY	380.00	-
	LABOUR CHARGE TO MOUNT AND DISMANTLE VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR .	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS .		250.00	90.00
	TOWING FEES.		150.00	50.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION .		2,200.00	1,980.00
	TO REINSTALL REAR BUMPER PARKING SENSOR .		170.00	50.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED .		170.00	40.00
	TO TRANSFER OF LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING .	NOT NECESSARY	220.00	-
	TO REPLACE ,REFIX AND TOP UP COOLANT FOR RADIATOR .		170.00	50.00
	TO LIFT-UP /OUT ENGINE WITH GEAR BOX AND REFIT .	NOT NECESSARY	440.00	-
	TO REMOVE AND REFIT RADIATOR SUPPORT CROSS - MEMBER AND OTHER NECESSARY ITEMS TO ENABLE BODYWORK REPAIR .	NOT NECESSARY	380.00	-
	TO CONDUCT AND PERFORM A COMPREHENSIVE VEHICLE DIAGNOSTIC CHECK AND RESET VEHICLE WARNING INDICATORS.	NOT NECESSARY	380.00	-
			10,290.00	4,000.00
<b>GRAND TOTAL</b>			<b>65,352.20</b>	<b>19,921.60</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>19,921.60</b>

Report Ref No. CC3/TP21002240/Kga3q2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.