

ASS. REC. BY:

REF: AG /

ASSIGNMENT

Kenneth

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Trans Cab

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 8587184

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 11 days Res.: Yes or NoLum Sum: 1.8.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHD 5522R Yr Regn: 11, 18Type: M.Car / M.Cycle / Bus / Van / Lorry / Truck / Prime Mover /

Truck / Trailer or

Make: Toy Pro c.c. 1798Colour M.P. White / Red A/C: Insured / Std / NI / NASp. Reading 161865 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: STDK93FU 30 30 76924Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rlm / STD orTyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHSU / PIR / SUMI /

TOYO / YOKO or Polar

Front

Rear

R/Bal. 9 mm R/Bal. 9 mmL/Bal. 9 mm L/Bal. 9 mmD.O.A. 15/2/21 D.O.I. 16/2/2021

Survey held at _____

Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or2.15.1

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 Got BI

Date/Time, File Pass to?

☐ : Prell. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S - RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5512R**AAD2102-068***Not Authored
Purvey B&Paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

16 FEB 2021**SHD5512R**

JTDKB3FU303076924

TOYOTA

PRIUS

15/02/2021

AIG

22/11/2018

| PART | | LIST | |
|---|----|-----------------------|---|
| 1 COVER, REAR BUMPER | \$ | <i>R</i> 442.60 | ✓ |
| 1 REINFORCEMENT SUB-ASSY, REAR BUMPER | \$ | <i>R</i> 332.70 | ✓ |
| 1 COVER, REAR BUMPER, LOWER | \$ | <i>mri</i> 15.40 | ✓ |
| 1 GUARD, REAR BUMPER, CENTER | \$ | <i>R</i> 576.30 | ✓ |
| 1 RETAINER, REAR BUMPER SIDE, LH | \$ | <i>mjem</i> 116.50 | ✓ |
| 1 RETAINER, REAR BUMPER SIDE, RH | \$ | <i>mjem</i> 117.70 | ✓ |
| 1 FILLER, REAR BUMPER EXTENSION, RH | \$ | <i>y cm</i> 123.70 | ✓ |
| 1 FILLER, REAR BUMPER EXTENSION, LH | \$ | <i>y cm</i> 123.70 | ✓ |
| 1 PANEL SUB-ASSY, BACK DOOR | \$ | <i>R</i> 1,147.80 | ✓ |
| 1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE | \$ | <i>cm</i> 925.60 | ✓ |
| 1 COVER, REAR COMBINATION LAMP, RH | \$ | <i>sn</i> 64.50 | X |
| 1 COVER, REAR COMBINATION LAMP, LH | \$ | <i>sn</i> 64.50 | X |
| 1 BOARD ASSY, BACK DOOR TRIM | \$ | <i>mjem</i> 259.20 | ✓ |
| 1 WEATHERSTRIP, BACK DOOR | \$ | <i>dit m</i> 372.30 | ✓ |
| 1 MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER RH | \$ | <i>sn</i> 56.50 | X |
| 1 BOARD, BACK DOOR TRIM | \$ | <i>Removal</i> 225.20 | X |
| 1 LENS & BODY, REAR COMBINATION LAMP, LH | \$ | <i>cm</i> 443.30 | ✓ |
| 1 LENS & BODY, REAR COMBINATION LAMP, RH | \$ | <i>cm</i> 451.80 | ✓ |
| 1 LENS AND BODY, REAR LAMP, LH | \$ | <i>scn</i> 502.00 | ✓ |
| 1 LENS AND BODY, REAR LAMP, RH | \$ | <i>cm</i> 502.00 | ✓ |
| 1 PANEL ASSY, DECK TRIM SIDE, RH | \$ | <i>sn</i> 355.90 | X |
| 1 BOX, DECK FLOOR, RH | \$ | <i>sn</i> 313.60 | X |
| 1 BOX, DECK FLOOR, LH | \$ | <i>sn</i> 313.00 | X |
| 1 BOARD, REAR FLOOR, NO.1 | \$ | <i>sn</i> 519.00 | X |
| 1 COVER ASSY, TONNEAU | \$ | <i>sn</i> 979.40 | X |
| 1 BOX, DECK FLOOR, REAR | \$ | <i>sn</i> 105.80 | X |
| 1 PANEL ASSY, DECK TRIM SIDE, LH | \$ | 355.90 | ? |
| 1 MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER LH | \$ | <i>sn</i> 56.50 | X |

Trans-cab Auto Services Pte Ltd**AAD2102-068**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5512R

| | | | | |
|--|----|-----------|----------|---|
| 1 DUCT ASSY, QUARTER VENT, RH | \$ | SL | 67.00 | X |
| 1 PANEL SUB-ASSY, QUARTER, RH | \$ | N | 871.50 | X |
| 1 LINER, REAR WHEEL HOUSE, RH | \$ | SL | 139.80 | X |
| 1 SEAL, REAR BUMPER SIDE, RH | \$ | SL | 88.50 | X |
| 1 TROUGH, BACK DOOR OPENING, LH | \$ | SL | 103.40 | X |
| 1 TROUGH, BACK DOOR OPENING, RH | \$ | SL | 103.40 | X |
| 1 COVER, FLOOR UNDER, NO.1 | \$ | SL | 175.10 | X |
| 1 COVER, FLOOR UNDER, NO.2 | \$ | SL | 241.90 | X |
| 1 COVER, REAR FLOOR | \$ | SL | 229.90 | ✓ |
| 1 COVER, DECK TRIM, REAR | \$ | SL | 126.70 | X |
| 1 PAN, REAR FLOOR | \$ | N | 583.40 | X |
| 1 EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, LH | \$ | N | 196.50 | X |
| 1 EXTENSION, REAR FLOOR SIDE PANEL, LH | \$ | SL | 78.30 | X |
| 1 INSULATOR, MAIN MUFFLER HEAT, RH | \$ | SL | 141.00 | X |
| 1 PANEL SUB-ASSY, BODY LOWER BACK | \$ | N | 651.00 | X |
| 1 LOCK ASSY, BACK DOOR, W/COURTESY LAMP SWITCH | \$ | N | 467.00 | X |
| 1 SWITCH ASSY, BACK DOOR OPENER | \$ | SL | 179.10 | X |
| 1 COVER, BACK DOOR LOCK | \$ | N | 30.20 | X |
| 1 SEAL, REAR BUMPER SIDE, LH | \$ | SL | 88.50 | X |
| 1 PANEL SUB-ASSY, QUARTER, LH | \$ | N | 871.50 | X |
| 1 LINER, REAR WHEEL HOUSE, LH | \$ | SL | 139.80 | X |
| 1 DUCT ASSY, QUARTER VENT, LH | \$ | SL | 67.00 | X |
| 1 SPOILER, SUB ASSY, REAR | \$ | N | 1,575.40 | X |
| 1 SEAL, REAR SPOILER | \$ | N | 16.70 | ✓ |
| 1 PROTECTOR, REAR SPOILER, NO.4 | \$ | SL | 16.70 | X |
| 1 PROTECTOR, REAR SPOILER, NO.3 | \$ | SL | 16.70 | X |
| 1 PROTECTOR, REAR SPOILER, NO.1 | \$ | SL | 16.70 | X |
| 1 LAMP SET, STOP CENTER | \$ | SL | 192.30 | ✓ |
| 1 LAMP SUB-ASSY, LICENSE PLATE | \$ | SL | 287.80 | X |
| 1 GLASS, BACK WINDOW FIX | \$ | Shattered | 761.40 | ✓ |
| 1 MOULDING, BACK WINDOW, LOWER NO.2 | \$ | N | 23.60 | ✓ |
| 1 MOULDING, BACK WINDOW, OUTSIDE LH NO.2 | \$ | N | 30.90 | ✓ |
| 1 MOULDING, BACK WINDOW, OUTSIDE RH NO.2 | \$ | N | 30.90 | ✓ |
| 1 DAM, BACK DOOR GLASS ADHESIVE, NO.2 | \$ | N | 28.90 | ✓ |
| 1 WIRE, LUGGAGE ROOM, NO.3 | \$ | SL | 170.70 | X |
| 1 WIRE, BACK DOOR, NO.2 | \$ | SL | 294.40 | X |
| 1 WIRE, BACK DOOR, NO.1 | \$ | SL | 247.40 | X |

Trans-cab Auto Services Pte Ltd**AAD2102-068**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5512R

| | | | | | |
|---|---|----|-------------------------------|----------|---|
| 1 | SOCKET & WIRE SUB-ASSY, REAR COMBINATION LAMP, LH | \$ | P _L | 63.30 | X |
| 1 | SOCKET & WIRE SUB-ASSY, REAR COMBINATION LAMP, RH | \$ | S _L | 63.30 | X |
| 1 | STAY ASSY, BACK DOOR, LH | \$ | P _L | 242.50 | X |
| 1 | STAY ASSY, BACK DOOR, RH | \$ | S _L | 242.50 | X |
| 1 | HINGE ASSY, BACK DOOR, LH | \$ | N | 61.00 | X |
| 1 | HINGE ASSY, BACK DOOR, RH | \$ | N | 61.00 | X |
| 1 | HANDLE, DOOR PULL | \$ | M ₁ | 23.40 | ✓ |
| 1 | COVER, FRONT BUMPER | \$ | B ₁ | 516.00 | ✓ |
| 1 | BRACKET, FRONT BUMPER EXTENSION MOUNTING | \$ | D ₁ | 103.40 | ✓ |
| 1 | REINFORCEMENT SUB-ASSY, FRONT BUMPER | \$ | B ₁ | 716.60 | ✓ |
| 1 | REINFORCEMENT, FRONT BUMPER, NO.2 | \$ | D ₁ | 246.10 | ✓ |
| 1 | ABSORBER, FRONT BUMPER, LOWER | \$ | CM | 132.70 | ✓ |
| 1 | ABSORBER, FRONT BUMPER ENERGY | \$ | | 79.60 | ? |
| 1 | SUPPORT, FRONT BUMPER SIDE, RH | \$ | OR | 80.10 | X |
| 1 | SUPPORT, FRONT BUMPER SIDE, LH | \$ | D ₁ | 82.30 | ✓ |
| 1 | COVER, ENGINE UNDER, NO.1 | \$ | | 472.40 | ? |
| 1 | COVER SUB-ASSY, ENGINE UNDER, NO.2 | \$ | | 241.90 | ? |
| 1 | EXTENSION, FRONT BUMPER, RH | \$ | P _L | 120.10 | X |
| 1 | EXTENSION, FRONT BUMPER, LH | \$ | S _L | 120.10 | X |
| 1 | COVER, FRONT BUMPER HOLE, LH | \$ | CM | 29.30 | ✓ |
| 1 | COVER, FRONT BUMPER HOLE, RH | \$ | N | 29.30 | ✓ |
| 1 | LAMP ASSY, FOG, LH | \$ | P _L | 951.40 | X |
| 1 | LAMP ASSY, FOG, RH | \$ | S _L | 951.40 | X |
| 1 | UNIT ASSY, HEADLAMP, LH | \$ | M ₃ B ₂ | 2,637.60 | ✓ |
| 1 | COMPUTER SUB-ASSY, HEADLAMP, LH NO.1 | \$ | | 960.50 | ? |
| 1 | UNIT ASSY, HEADLAMP, RH | \$ | CM | 2,637.60 | ✓ |
| 1 | COMPUTER SUB-ASSY, HEADLAMP, RH NO.1 | \$ | | 960.50 | ? |
| 1 | MOTOR, HEADLAMP LEVELING, RH | \$ | S _L | 487.50 | X |
| 1 | GRILLE SUB-ASSY, RADIATOR | \$ | CM | 346.00 | ✓ |
| 1 | GRILLE, RADIATOR, LOWER NO.1 | \$ | D ₁ | 170.10 | ✓ |
| 1 | EMBLEM ASSY, RADIATOR GRILLE | \$ | N | 90.80 | ✓ |
| 1 | FENDER SUB-ASSY, FRONT LH | \$ | B ₁ | 977.80 | ✓ |
| 1 | LINER, FRONT FENDER, LH | \$ | S _L | 202.50 | X |
| 1 | EMBLEM, SIDE PANEL | \$ | N | 54.60 | ✓ |
| 1 | SUPPORT, RADIATOR, UPPER RH | \$ | | 78.90 | ? |
| 1 | SUPPORT, RADIATOR, UPPER LH | \$ | | 78.90 | ? |
| 1 | SUPPORT SUB-ASSY, RADIATOR, UPPER | \$ | B ₁ | 377.10 | ✓ |

Trans-cab Auto Services Pte Ltd**AAD2102-068**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5512R

| | | | | |
|---|--|----|----------|---|
| 1 | SUPPORT SUB-ASSY, RADIATOR, LOWER | \$ | 409.90 | ? |
| 1 | SUPPORT SUB-ASSY, RADIATOR, LH | \$ | 245.10 | ? |
| 1 | SUPPORT SUB-ASSY, RADIATOR, RH | \$ | 245.10 | ? |
| 1 | HOOD SUB-ASSY | \$ | 983.10 | ✓ |
| 1 | HINGE ASSY, HOOD, LH | \$ | 58.90 | ✓ |
| 1 | HINGE ASSY, HOOD, RH | \$ | 58.90 | ✓ |
| 1 | BRACE, HOOD LOCK SUPPORT | \$ | 78.30 | ✓ |
| 1 | INSULATOR, HOOD | \$ | 410.90 | ✓ |
| 1 | LOCK ASSY, HOOD | \$ | 135.00 | ✓ |
| 1 | CABLE ASSY, HOOD LOCK CONTROL | \$ | 54.90 | ? |
| 1 | SUPPORT ASSY, HOOD | \$ | 44.20 | X |
| 1 | SEAL, HOOD TO FRONT END PANEL | \$ | 51.60 | X |
| 1 | WIRE, ENGINE ROOM MAIN | \$ | 7,323.90 | X |
| 1 | HORN ASSY, HIGH PITCHED | \$ | 134.80 | ? |
| 1 | HORN ASSY, LOW PITCHED | \$ | 134.80 | ? |
| 1 | GUIDE, RADIATOR AIR, NO.1 LH | \$ | 69.90 | X |
| 1 | GUIDE, RADIATOR AIR, NO.1 RH | \$ | 65.30 | X |
| 1 | GUIDE, RADIATOR AIR, NO.3 | \$ | 112.70 | X |
| 1 | GUIDE, RADIATOR AIR, NO.2 | \$ | 53.40 | X |
| 1 | SEAL, RADIATOR TO SUPPORT, NO.3 | \$ | 32.40 | X |
| 1 | SEAL, RADIATOR TO SUPPORT, NO.2 | \$ | 32.60 | X |
| 1 | INLET, AIR CLEANER, NO.1 | \$ | 155.60 | X |
| 1 | INLET, AIR CLEANER, NO.3 | \$ | 42.10 | X |
| 1 | INLET, AIR CLEANER, NO.2 | \$ | 112.70 | X |
| 1 | HOSE, AIR CLEANER, NO.1 | \$ | 74.00 | X |
| 1 | JAR ASSY, WINDSHIELD WASHER | \$ | 219.10 | ? |
| 1 | MOTOR AND PUMP ASSY, WINDSHIELD WASHER | \$ | 292.40 | X |
| 1 | INLET SUB-ASSY, WASHER | \$ | 67.00 | X |
| 1 | CONDENSER ASSY, COOLER | \$ | 1,783.20 | ? |
| 1 | HOSE SUB-ASSY, SUCTION | \$ | 646.80 | ? |
| 1 | HOSE SUB-ASSY, DISCHARGE | \$ | 402.90 | ? |
| 1 | PIPE SUB-ASSY, SUCTION | \$ | 465.80 | ? |
| 1 | SENSOR, AIRCONDITIONER PRESSURE | \$ | 342.80 | ? |
| 1 | TUBE & ACCESSORY ASSY, AIR CONDITIONER | \$ | 691.00 | ? |
| 1 | COMPRESSOR ASSY, W/MOTOR | \$ | 4,771.60 | X |
| 1 | RADIATOR ASSY | \$ | 2,218.00 | ? |
| 1 | SHROUD, FAN | \$ | 264.70 | ? |

Trans-cab Auto Services Pte Ltd**AAD2102-068**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5512R

| | | | |
|---|-----------|------------------|---|
| 1 FAN, RH | \$ | 281.30 | ? |
| 1 FAN, LH | \$ | 219.10 | ? |
| 1 MOTOR, COOLING FAN, LH | \$ | 655.10 | ? |
| 1 MOTOR, COOLING FAN, RH | \$ | 535.50 | ? |
| 1 TANK ASSY, INVERTER RESERVE | \$ | 443.00 | X |
| 1 INVERTER WATER PUMP ASSY(W/MOTOR) | \$ | 518.60 | X |
| 1 BATTERY | \$ | 1,584.90 | ? |
| 1 CLAMP, BATTERY, NO.2 | \$ | 51.80 | X |
| 1 CLAMP SUB-ASSY, BATTERY | \$ | 115.50 | X |
| 1 TERMINAL, BATTERY POSITIVE | \$ | 58.10 | X |
| 1 COVER, FUSIBLE LINK | \$ | 33.90 | X |
| 1 SENSOR ASSY, BATTERY STATE | \$ | 306.10 | X |
| 1 BLOCK ASSY, FUSIBLE LINK | \$ | 119.60 | X |
| 1 TANK, RESERVE SEALED W/O CAP | \$ | 151.40 | X |
| 1 CLEANER ASSY, AIR | \$ | 1,147.00 | ✓ |
| 1 BRACKET, HEADLAMP, LH | \$ | 34.80 | X |
| 1 BRACKET, HEADLAMP, RH | \$ | 34.80 | X |
| 1 STAY SUB-ASSY, FRONT BUMPER, LH | \$ | 47.50 | X |
| 1 STAY SUB-ASSY, FRONT BUMPER, RH | \$ | 47.50 | X |
| 1 BRACKET, FRONT BUMPER SIDE, LH | \$ | 59.30 | X |
| 1 BRACKET, FRONT BUMPER SIDE, RH | \$ | 59.30 | X |
| 1 BRACKET, RADIATOR GRILLE MOUNTING, LH | \$ | 36.60 | X |
| 1 BRACKET, RADIATOR GRILLE MOUNTING, RH | \$ | 36.60 | X |
| 1 MEMBER SUB-ASSY, FRONT SIDE, RH | \$ | 2,342.30 | X |
| 1 COVER, RADIATOR SUPPORT OPENING | \$ | 235.30 | X |
| 1 THERMISTOR ASSY | \$ | 80.90 | X |
| 1 MEMBER SUB-ASSY, SIDE, REAR RH | \$ | 288.50 | X |
| 1 ACTUATOR ASSY, SHIFT CONTROL | \$ | 1,036.40 | X |
| 1 COOLER, MOTOR COOLING | \$ | 297.20 | X |
| TOTAL | \$ | 69,046.80 | |
| 25% | \$ | 17,261.70 | |
| | \$ | 51,785.10 | |

Special Nett

| | | | |
|-----------------------|----|--------|-------|
| 1SET PARKING AID | \$ | 700.00 | 22012 |
| 1SET REAR BUMPER CLIP | \$ | 95.00 | 6812 |
| 2 WINDSCREEN SEALANT | \$ | 150.00 | 8012 |

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2102-068

SHD5512R

| | | | | |
|-------------------------------------|-----------|----|-----------------|------|
| 1 WINDSCREEN MOULDING | \$ | Mr | 200.00 | ✓ |
| 1 WINDSCREEN INNER SPONGE SEAL | \$ | Mr | 130.00 | 30sn |
| 1 REAR TAILGATE TOYOTA LOGO | \$ | Mr | 47.90 | — |
| 1 REAR TAILGATE WORDING 'PRIUS' | \$ | Mr | 54.60 | — |
| 1 REAR TAILGATE WORDING 'HYBRID' | \$ | Mr | 54.60 | — |
| 1 REAR TAILGATE STICKER "Trans-Cab" | \$ | Mr | 80.00 | 30sn |
| 1 REAR TAILGATE STICKER "6555-3333" | \$ | Mr | 80.00 | 30sn |
| 1 REAR BUMPER PROTECTOR | \$ | Mr | 180.00 | X |
| 2 SEAM SEALANT | \$ | Mr | 250.00 | X |
| 1SET REAR FENDER LINER CLIP | \$ | Mr | 85.00 | X |
| 1SET REAR BUMPER RETAINER CLIP | \$ | Mr | 85.00 | X |
| 1 REAR NUMBER PLATE WITH HOLDER | \$ | Mr | 140.00 | 45sn |
| 1SET TAILLAMP LOWER CLIP | \$ | Mr | 55.00 | X |
| 1SET TAILLAMP UPPER CLIP | \$ | Mr | 55.00 | X |
| 1 END PANEL TRIM CLIP | \$ | Mr | 65.00 | — |
| 1 REAR SPOILER CLIP | \$ | Mr | 70.00 | X |
| 1SET BUMPER CLIP FRT | \$ | Mr | 95.00 | 60sn |
| 1 FRONT NUMBER PLATE WITH MOULDING | \$ | Mr | 200.00 | 45sn |
| 1SET CLIP, FRONT FENDER LINER | \$ | Mr | 85.00 | X |
| 1SET FRNT BUMPER RETAINER CLIP | \$ | Mr | 85.00 | X |
| 4L Radiator Coolant | \$ | Mr | 120.00 | 30sn |
| 1 HOOD INSULATOR CLIP | \$ | Mr | 55.00 | X |
| 1 Engine Under Cover Clip | \$ | Mr | 60.00 | X |
| TOTAL | \$ | | 3,277.10 | |

TOTAL PARTS \$ 55,062.20**LABOUR**

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.

\$ 300.00 1800

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 380.00 1000

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 2,200.00 14000

Trans-cab Auto Services Pte Ltd**AAD2102-068**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5512R

| | | | |
|---|----|-----------|-------|
| To transfer of rear end panel fittings, attachment and perform water seepage test. | \$ | nn 380.00 | X |
| To transfer of Tailgate fittings, attachments and perform water seepage test. | \$ | 180.00 | 601 |
| To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair. | \$ | 480.00 | ? |
| To transfer of Fender fittings, attachments and perform water seepage test. | \$ | nn 480.00 | X |
| To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas. | \$ | 380.00 | 1001 |
| Labour charge to mount and dismount vehicle on jig bench, to facilitate repair. | \$ | 380.00 | ? |
| To check steering geometry and computer wheel alignment | \$ | nn 220.00 | X |
| To Rust-Proofing and apply undercoat Of The Affected Areas. | \$ | 250.00 | 901 |
| Towing Fees | \$ | 150.00 | 501 |
| Putty And Spray Painting Of The Affected Portion. | \$ | 2,200.00 | 19801 |
| To reinstall rear bumper parking sensor. | \$ | 170.00 | 501 |
| To Check Electrical Lighting Concerned. | \$ | 170.00 | 401 |
| To transfer of luggage floor panel fittings, attachment and perform water seepage test. | \$ | nn 380.00 | X |
| To transfer of tire, rim and on wheel balancing. | \$ | nn 220.00 | X |
| To replace, refix and top up coolant for radiator | \$ | 170.00 | 501 |

Trans-cab Auto Services Pte Ltd

AAD2102-068

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5512R

To lift-up / out engine with gear box and refit.

\$ *nn* 440.00 X

To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.

\$ *nn* 380.00 X

To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.

\$ *nn* 380.00 X

TOTAL \$ **10,290.00**

Over All Total \$ **65,352.20**

(PART-BY-PART) Repair Days

~~25 DAYS~~

11 days

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 15/02/2021 18:50 (SGT)
Date of Accident 15/02/2021 11:25 (SGT)
Exact Location of Accident Singapore
Additional Location Information BARTLEY ROAD EAST
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHD5512R

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner TRANS-CAB SERVICES PTE LTD
Company Reg No 2XXXXXXX8K
Email Address claims@transcab.com.sg
Mobile Phone No (Phone) +65-62866666
Alternative Phone No (Office) +65-62866666

VEHICLE PARTICULARS

Manufacturer Toyota
Model PRIUS 5DR HATCHBACK (AUTO)
Variant -
Exact purpose for which vehicle was being used at time of accident Private hire
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Taxi

INSURANCE COMPANY

Name of Insurance Company Axa
Type of Coverage ThirdParty
Fleet Policy Yes
Policy Number VFX/P2413997
Cover Note Number -

DRIVER

Name of Driver ABDUL RAZAK BIN IBRAHIM
NRIC No SXXXX099F
Date Of Birth 14/07/1957
Occupation Outdoor

Date Of Driving Pass 13/12/1979
 Driving experience 41 YEARS AND 2 MONTHS
 Gender Male
 Mobile Number (Phone) +65-93589609
 Alt. Phone Number -
 Email Address claims@transcab.com.sg
 Address HDB Tampines Green Vale, 742 Tampines Street 72
 Address complement #02-98
 Postcode 520742
 Is the driver the policyholder? No
 If No, Relationship of the Driver with the Insured Hirer
 Does Driver Own Other Vehicles? No
 Vehicle Registration Number of Other Vehicle Owned by Driver -
 Insurance Company of Other Vehicle Owned by Driver -

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Chain Collision
 Weather Conditions Clear
 Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
 Number of vehicles involved in the accident 3
 Was anybody injured in the Accident? Yes
 Was any injured conveyed to hospital by ambulance? No
 Was any other material or property damaged? Yes
 Number of Passengers (Including Driver) 2
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

PASSENGER 1

Name GOE
 Gender Male

DETAILS OF POLICE ACTION

Was the accident reported to the police? Yes
 Police Station Name Traffic Police
 Police Station Phone No (Phone) +65-65470000
 Alt. Police Station Phone No (Fax) +65-65474900
 Police Station Address 10 Ubi Avenue 3 Singapore 408865
 Was notice of intended Prosecution given? No
 If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

REFER TO POLICE REPORT:T/20210215/7012 LODGED AT TRAFFIC POLICE

ATTACHMENT(S)

Are accident photos available for attachment? Yes
 Was there any video captured by Car Camera? No
 Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBC6722X
 Vehicle Manufacturer Toyota
 Vehicle Model HIACE MANUAL
 Vehicle Variant -

| | |
|---|--------------------|
| Vehicle Colour | - |
| Vehicle Category | Commercial vehicle |
| Name of Driver | - |
| Contact Number | - |
| Address | - |
| Address complement | - |
| Postcode | - |
| Insurance Company Name | - |
| Nature Of Damage | - |
| Details of property damaged in accident | - |
| No. Of Passenger (Including Driver) | 1 |

DETAILS OF OTHER VEHICLE PROPERTY 2

| | |
|---|--------------------------|
| Vehicle Registration Number | SBS3946C |
| Vehicle Manufacturer | Volvo |
| Vehicle Model | B9TL 9.4L AUTO TURBO ABS |
| Vehicle Variant | - |
| Vehicle Colour | - |
| Vehicle Category | Bus |
| Name of Driver | - |
| Contact Number | - |
| Address | - |
| Address complement | - |
| Postcode | - |
| Insurance Company Name | - |
| Nature Of Damage | - |
| Details of property damaged in accident | - |
| No. Of Passenger (Including Driver) | 1 |

INJURED PERSONS DETAILS

INJURED 1

| | |
|---|---|
| Name of injured person | ABDUL RAZAK BIN IBRAHIM |
| Address | HDB Tampines Green Vale, 742 Tampines Street 72 |
| Address Complement | #02-98 |
| Post Code | 520742 |
| Approximate Age Years Old | - |
| Injuries Sustained | - |
| Injured person in which vehicle? | SHD5512R |
| Were seat belts worn? | Yes |
| Was this injured conveyed to hospital by ambulance? | No |

SKETCH PLAN

A: 910552R

B: GBC6727X

C: 9282946C



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO ATTACHED STATEMENT.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

VERIFY BY AJAX MARS (ARC)
REPORTING OFFICER
WONG JUN KEAT

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SINGAPORE POLICE FORCE



T/20210215/7012

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20210215/7012

REPORT OF A TRAFFIC ACCIDENT

| | | | |
|---|------------|---|------------------------------|
| Date/Time Report Made: 15/02/2021 13:42 | | Vide Report No.: | Station Diary No.: |
| Informant's Particulars | | | |
| Name of Informant: ABDUL RAZAK BIN IBRAHIM | | Address: 742 TAMPINES STREET 72 #02-98 SINGAPORE 520742 | |
| ID Type / ID No.: NRIC NO / S1279099F | | Contact No.: Home/Office: Mobile: 93589609 | |
| Nationality: SINGAPORE CITIZEN | | Email: john.pyj@hotmail.com | |
| Sex: Male | Age: 63 | Date of Birth: 14/07/1957 | Type of Informant: Driver |
| Race: Malay | | Language: English | Institution / School Name: |
| Occupation: Taxi Driver | | Driving Licence Information: Class: 2B,3 Date of Expiry: | |

General Information of the Accident

| | | | | |
|--|------------------|------------------------------------|--|------------------------------------|
| Type of Accident: | Injury Others | Drink Drive: No | Date/Time of Accident: 15/02/2021 11:25 | Type of Location: Straight Road |
| Location: BARTLEY ROAD EAST | | | | |
| Weather: Clear | | Road Surface: Dry | Road Speed Limit: | |
| Traffic Flow: One Way | | Traffic Control: Not Controlled | Traffic Volume: Moderate | |
| Type of Collision: Between Moving Vehicles - Head To Rear | | | Anyone conveyed by ambulance: No | |

Details of Vehicle Involved

| Vehicle No. | Type | Make | Model | Color | Conditio | No of |
|-------------|-------------------|------|-------|-------|-------------------|-------|
| GBC6722X | Van | | | | Seriously Damaged | 0 |
| SBS3946C | Bus/Coach/Minibus | | | | | 0 |
| SHD5512R | Car | | | | Seriously Damaged | 1 |



**SINGAPORE
POLICE FORCE**



T/20210215/7012

2 of 3

Police Station Of Origin:

Traffic Police

10 Ubi Avenue 3 SINGAPORE 408865

Tel No: 65470000

Report No. T/20210215/7012

CONTINUATION OF REPORT

| Details of Person Involved | | | |
|-----------------------------------|-------------------------|-----------------------------------|------------------------------------|
| Any Pedestrian Involved: No | | | |
| No. of Pedestrians Injured: NIL | | Use of Pedestrian Crossing: NA | |
| Driver | | | |
| Name | ABDUL RAZAK BIN IBRAHIM | ID No. | S1279099F |
| Related Vehicle | SHD5512R (Car) | Contact No. | 93589609 |
| Hospital/Clinic | NIL | Class of Driving Licence & Expiry | Class: 2B,3 Date of Expiry: NIL |
| Date | 15/02/2021 | Date | 15/02/2021 |
| No. of Days granted Medical Leave | 05 | Degree of | Slight |

Brief Details.

On the dated stated, time and location I was traveling on bedok north road towards bartley flyover. I was stationary about half a min at the slip rd to bartley road waiting for main road to clear. Infront of my vehicle there is a SBS BUS (SBS3946C). Out of all sudden my rear was collided by vehicle "B"(GBC6722X) and force my vehicle to move toward and collided onto SBS BUS(SBS3964C). The impact was huge. After awhile we exchange particular and move on. I felt pain on my body and went to consult my family doctor and was given 5 days MC.