



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving	TPVD Volkswagen Golf (SKP9375U)
Date of Loss	4 February 2021
Time of Loss	18.50
Loss Description	SLV2600Y (INSD) C/W SKP9375U (TP)
Comment	<input type="text"/>

Workshop Details

Total Rebate Amount	<input type="text" value="26624"/>
Nett Loss Amount	\$18,376.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (TP)
Days of work completion *	<input type="text" value="20"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details



Vehicle Registration#	SKP9375U	Purchase Date	<div>dd/mm/yyyy</div> <div></div>
Registration State	<div>SINGAPORE</div>	Registration Date *	<div>23/10/2014</div> <div></div>
Mileage	<div>111511</div>	Age of Vehicle	6

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year	2017	<div>2014</div>
Make	TOYOTA	<div>VOLKSWAGEN</div>
		<div></div>

Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	WEN HUIJUN	<div></div>
Date of Birth		<div>dd/mm/yyyy</div> <div></div>

Model CATEGORY	WISH 1.8 POLICY INFORMATION	GOLF A7 1.4 T INFORMATION
Type		<input type="text" value=""/>
Type of Paint		<input type="text" value=""/>
Chassis No	JTDGG20WX0J008501	<input type="text" value="WWWZZZAUZ"/>
Engine No	2ZR0A40852	<input type="text" value="CXS202358"/>
Engine Capacity		<input type="text" value="1395"/>
Sum Insured	0	<input type="text" value="0"/>
Market Value	0	<input type="text" value="45000"/>

CATEGORY Age	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	<input type="text" value=""/>
Education Qualification	Other	<input type="text" value=""/>
Driving Experience	0	
Driver License #		<input type="text" value=""/>
License Type		<input type="text" value=""/>
License Issue Date		<input type="text" value="dd/mm/yyyy"/> 
License Expiration Date		<input type="text" value="dd/mm/yyyy"/> 

CATEGORY	FNOL INFORMATION	POST SURVEY
Address	SG, Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text" value="▼"/>
Gender	Unknown	<input type="text" value="▼"/>
Marital status	Unknown	<input type="text" value="▼"/>
Identification #	S7420516Z	<input type="text"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

23/02/2021



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver
Excess

0

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Other Excess

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

Rear Tyre Size

Front left side

Rear left side

Front right side

Rear right side



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%	<input type="text"/>	Salvage%	<input type="text"/>
Discount%	<input type="text" value="10"/>	Settlement%	<input type="text" value="100"/>

Paint Labour/Material Ratio

Paint Labour Ratio	<input type="text" value="20"/>	Paint Material Ratio	<input type="text" value="80"/>
--------------------	---------------------------------	----------------------	---------------------------------

Cash Loss

YesNo

Part Supplied by AXA

YesNo

Save



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts













Add

Approve

Deny

Submit All

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		REAR TAIL-GATE ASSY	Bent	0	1450	No		10			1305	Reviewing
<input type="checkbox"/>		0	2		REAR TAIL-GATE REFLECTOR	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR TAIL-GATE EMBLEM "GOLF"	Necessary	0	88	No		10			79.2	Reviewing
<input type="checkbox"/>		0	1		REAR TAIL-GATE EMBLEM "TSI"	Necessary	0	85	No		10			76.5	Reviewing
<input type="checkbox"/>		0	1		REAR TAIL-GATE INNER TRIM BOARD	Cracked	0	310	No		10			279	Reviewing
<input type="checkbox"/>		0	1		REAR TAIL-GATE INNER LOCK	Dented	0	145	No		10			130.5	Reviewing
<input type="checkbox"/>		0	2		REAR TAIL-LAMP	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR BOOT RUBBER	Serviceable	0	0	No		10			0	Deny








	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	2		REAR NO PLATE LAMP	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR END PANEL	Repair	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR END PANEL INNER GARNISH	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	2		REAR FENDER INNER TRIM BOARD	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR BUMPER	Buckled	0	905.1	No		10			814.59	Reviewing
<input type="checkbox"/>		0	1		REAR BUMPER LOWER GARNISH	Dented	0	285	No		10			256.5	Reviewing
<input type="checkbox"/>		0	1		REAR BUMPER REINFORCEMENT	Repair	0	0	No		10			0	Deny
<input type="checkbox"/>		0	2		REAR BUMPER SIDE RETAINER	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	2		REAR BUMPER BRACKET	Repair	0	0	No		10			0	Deny
<input type="checkbox"/>		0	2		REAR BUMPER REFLECTOR	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR EXHAUST SILENCER	Repair	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR TAIL-GATE GLASS MOULDING	Serviceable	0	0	No		10			0	Deny
Labour															

Add

Approve

Deny

Submit All

EDIT		SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
<input type="checkbox"/>		0		REMOVE / RENEW THE ABOVE PARTS. CUT OUT & REWELD REAR END PANEL, KNOCK OUT & RESHAPE REAR BOOT FLOOR PANEL ETC	0	400	0	0	Reviewing	
<input type="checkbox"/>		0		TO PUTTY AND SPRAY PAINT	0	600	0	0	Reviewing	
<input type="checkbox"/>		0		CHECK / RECONNECT WIRING	0	20	0	0	Reviewing	
<input type="checkbox"/>		0		TO SPRAY ANTI RUST ON ACCIDENT AFFECTED PORTION	0	30	0	0	Reviewing	
<input type="checkbox"/>		0		REMOVE / RENEW REAR WINDSCREEN GLASS	0	120	0	0	Reviewing	
<input type="checkbox"/>		0		REMOVE / REFIT REAR BOOT LID LOCK MECHANISM, INNER TRIM TO NEW LID	0	60	0	0	Reviewing	
<input type="checkbox"/>		0		REMOVE / RENEW EXHAUST SILENCER	0	0	0	0	Deny	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary





Add

Approve

Deny

Submit All

	EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		0	DAYS OF REPAIR : 4 DAYS	Reviewing		0		
<input type="checkbox"/>		0	REAR WINDSCREEN SEALANT	Reviewing		40	NECESSARY	
<input type="checkbox"/>		0	REAR REVERSE SENSOR	Reviewing		200	SHORTED	
<input type="checkbox"/>		0	BUMPER CLIP	Reviewing		30	NECESSARY	

			(15PCS)				
EDIT		SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT REMOVE
<input type="checkbox"/>		0	BADGE AND STICKER	Reviewing		20	NECESSARY 
<input type="checkbox"/>		0	NO PLATE	Reviewing		45	DENTED 



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details		Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Estimated Claim Amount		\$0.00		Adjusted Claim Amount		\$4,506.29	
CATEGORY		ESTIMATE		ADJUSTED			
Spare Parts		\$0.00		\$2,941.29			
Labour		\$0.00		\$1,230.00			
Miscellaneous		\$0.00		\$335.00			


Submit for Review

<<

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

- Add
- Approve
- Deny
- Submit All

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>	0	FINAL LUMP SUM	Reviewing		3600		

Submit for Review