

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315



AUTOMOBILE INSPECTION REPORT



NTUC INCOME INSURANCE CO-OPERATIVE LTD				NS/INC21002248/T1tf3n2		
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	12-04-2021 INC4		
4						
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SLR 9987G		nspected	SHB 6262R	
	Policy No.	5117915451		age (\$)	0.00	
	Claim No.	MT/1120969-002	Exces	,	0.00	
	Assign From		Assign		16/02/2021	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA PRIUS HYBRID	C.C		1798	
	Engine No.	HIDDEN	Year o		2019	
	Chassis No.	JTDKB3FU203089230	Colou		BLUE	
	Odometer	-	Steering		IN ORDER	
	Brakes	IN ORDER	Modifi	cation	SPORTS RIM	
	General GOOD					
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	DAVAN		6 mm	
	L/H Front Tyre	195/65 R15	DAVAN	ITI	6 mm	
	R/H Rear Tyre	195/65 R15	DAVAN		6 mm	
	L/H Rear Tyre	195/65 R15	DAVAN	ITI	6 mm	
4.						
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	11/02/2021	Inspec	tion Date	16/02/2021	
	Survey held at	COMFORTDELGRO ENGINEERING PTE LTD				
		59 LOYANG DRIVE SINGAPORE 508969				
5a.	. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days					