

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III21002250/GQD3E2

Date: 03/09/2021

REFERENCE

Insured/Claimant:	CHNG SOH KIM	Policy No:	D20MPC0006416		
Date of Loss:	10/02/2021	Nature of Claim:	OD	Claim No:	MPC2021D0000695

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKU977R		
Make & Model:	HYUNDAI VELOSTER, 1.6 (A)	Engine No:	G4FJGU495759
Reg. Date:	26/04/2016 (Man. Year: 2016)	Chassis No:	KMHTC61EVGU290673
Colour:	Red	Odometer:	82935 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$61,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40Z R18	Rear Tyre Size:	225/40Z R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,282.80	7,984.24	18,298.56	69.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,600.00	1,530.00	5,070.00	76.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,882.80	9,514.24	23,368.56	71.07
Approved Total (Overridden) (S\$)		7,600.00		
- Excess (S\$)	1,100.00	1,100.00	0.00	0.00
(S\$)	31,782.80	6,500.00	25,282.80	79.55
+ GST 7.00/7.00% (S\$)	2,224.80	455.00	1,769.80	79.55
Nett Amount (S\$)	34,007.60	6,955.00	27,052.60	79.55

INSPECTION

Date of Assignment:	17/02/2021		
Date Inspected:	19/02/2021	Inspected At:	56 Loyang Way #04-04
Estimated Period of Repair:	5.0 days		Repairer : AP Automotive Services Pte Ltd (HQ)

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Sep 2021)
Parts:	M1-COUPE	HYUNDAI VELOSTER 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKU977R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Buckled	580.00 F	*580.00 FL
2	1		*BONNET LOCK	Bent	150.00 F	*150.00 FL
3	2		*SET BONNET HINGE	Not Necessary	48.00 F	*- FL
4	2		*BONNET DAMPER L+R	Not Necessary	135.00 F	*- FL
5	1		*BONNET INSULATOR	Not Necessary	130.00 F	*- FL
6	2		*HEADLAMP L+R	Broken	12,000.00 F	*4,468.00 FL
7	1		*FRONT BUMPER	Deformed	680.00 F	*587.00 FL
8	2		*FRONT BUMPER FOG LAMP L+R	Cracked	450.00 F	*450.00 FL
9	2		*FRONT BUMPER FOG LAMP GARNISH L+R	Not Necessary	85.00 F	*- FL
10	1		*FRONT BUMPER LOWER LIP	Not Necessary	480.00 F	*- FL
11	2		*FRONT BUMPER RETAINER L+R	Not Necessary	28.00 F	*- FL
12	1		*FRONT BUMPER REINFORCEMENT BAR	Bent	480.00 F	*480.00 FL
13	1		*FRONT BUMPER SPONGE	Cracked	120.00 F	*120.00 FL
14	1		*FRONT BUMPER UNDERCOVER	Not Necessary	145.00 F	*- FL
15	1		*FRONT FENDER L+R	N/S Buckled / O/S Repair	560.00 F	*280.00 FL
16	2		*FRONT FENDER COWLING L+R	Not Necessary	70.00 F	*- FL
17	1		*FRONT SUPPORT PANEL	Bent	450.00 F	*450.00 FL
18	1		*FRONT SUPPORT PANEL TOP GARNISH (NPA)	Cracked	0.00 F	*- FL
19	1		*FRONT HORN L+R (2PCS)	Cracked(1Pc Only)	340.00 F	*72.80 FL
20	1		*AIRCON CONDENSOR	Bent	560.00 F	*560.00 FL
21	1		*AIRCON CONDENSOR AIRGUIDE L+R	N/S Not Necessary/O/S Deformed	96.00 F	*48.00 FL
22	1		*HIGH PRESSURE HOSE	Not Necessary	280.00 F	*- FL
23	1		*LOW PRESSURE HOSE	Not Necessary	265.00 F	*- FL
24	1		*RADIATOR	Cut	580.00 F	*580.00 FL
25	1		*SUCTION PIPE (NPA)	Not Necessary	0.00 F	*- FL
26	1		*DISCHARGE PIPE (NPA)	Not Necessary	0.00 F	*- FL
27	1		*RADIATOR SPARE TANK	Not Necessary	140.00 F	*- FL
28	1		*BATTERY TRAY	Not Necessary	10.80 F	*- FL
29	1		*BATTERY BRACKET	Not Necessary	45.00 F	*- FL
30	1		*WIPER WASHER TANK	Not Necessary	125.00 F	*- FL
31	2		*FRONT DOOR L+R (NPA)	Repair	0.00 F	*- FL
32	1		*BONNET INSULATOR CLIPS	Not Necessary	100.00 FS	*- FS
33	1		*FRONT GRILLE	Cracked	4,000.00 F	*289.00 FL
34	1		*FRONT GRILLE TOP SEAL	Not Necessary	150.00 FS	*- FS
35	1		*FRONT GRILLE EMBLEM - R	Necessary	200.00 F	*48.00 FL
36	1		*FRONT NUMBER PLATE	Cracked	200.00 FS	*20.00 FS
37	1		*FRONT BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
38	2		*SET FRONT BUMPER SIDE CLIPS L+R	Not Necessary	500.00 FS	*- FS
39	2		*FRONT FENDER COWLING CLIPS	Not Necessary	200.00 FS	*- FS
40	1		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	100.00 FS	*- FS
41	1		*RADIATOR COOLANT	Necessary	120.00 FS	*40.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*BATTERY	Not Necessary	450.00 FS	*- FS
43	1		*FRONT NUMBER PLATE FRAME CARBON FIBRE	Cut	450.00 FS	*20.00 FS
44	1		*RADIATOR FAN COWLING }	Deformed	680.00 F	*680.00 FL
45	1		*RADIATOR FAN MOTOR }		0.00 F	*- FL
46	1		*RADIATOR FAN BLADE }		0.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

	Sub Total (\$\$)	26,282.80	9,952.80
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00		1,968.56
	Total Parts (\$\$)	26,282.80	7,984.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON AFFECTED AREAS	New	1,800.00	600.00
2	TO CHECK WIRING AND HEADLAMP FOCUS }	New	150.00	30.00
3	TO CHECK WIRING AND FOG LAMP FUNCTION }	New	150.00	0.00
4	TO RNR INNER TRIM AND UPHOLSTERY	New	300.00	0.00
5	TO CHECK WATER LEAK	New	150.00	0.00
6	TO RNR FRONT AIR CON CONDENSOR AND TOP UP GAS }	New	300.00	100.00
7	TO RNR FRONT RADIATOR }	New	250.00	0.00
8	TO PERFORM RUST PROOFING	New	400.00	0.00
9	TO RNR FRONT DOOR MECHANISM	New	600.00	0.00
10	TO RNR HORN AND TEST FUNCTION	New	100.00	0.00
11	SPRAY PAINT ON AFFECTED AREAS	New	1,800.00	800.00
12	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	New	600.00	0.00
Gross Labour Cost (\$)			6,600.00	1,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >