

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 1812S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER COVER	DEFORMED	1,106.00	1,106.00
2	REAR BUMPER BRACKET SIDE LH/RH @\$35.60	NOT NECESSARY	71.20	-
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	REAR BUMPER REFLECTOR/LH	CUT	32.00	32.00
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	428.40	-
1	REAR BUMPER UNDER COVER	DEFORMED	228.00	228.00
1	BOOTLID MOULDING	NOT NECESSARY	85.00	-
1	BOOT LID LAMP/LH	NOT NECESSARY	565.60	-
1	TAIL LAMP/LH	CUT	697.80	697.80
1	BOOTLID EMBLEM CRDI	NECESSARY	52.40	52.40
1	BOOTLID EMBLEM 140	NECESSARY	52.40	52.40
	LESS 20% DISCOUNT		-668.16	-438.12
			2,672.64	1,752.48
	SPECIAL NETT ITEMS			
1	BOOTLID COMFORT & TEL NUMBER STICKER (SN)	NECESSARY	60.00	60.00
1	REAR BUMPER MAT (SN)	NECESSARY	50.00	50.00
1	REVERSE SENSOR (SN)	NOT NECESSARY	135.70	-
			245.70	110.00
	<u>LABOUR</u>			
	PANEL BEATING.		700.00	420.00
	SPRAY PAINTING CHARGE.		800.00	500.00
	REMOVE/REFIX REVERSE SENSOR.		60.00	30.00
	CHECK LIGHTING.		60.00	30.00
	TUFF KOTE.	NOT NECESSARY	90.00	-
			1,710.00	980.00
	GRAND TOTAL		4,628.34	2,842.48





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		2,250.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. NS/INC21002251/T1tf3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser