AFORTDELGRO PTE LTD

PAIR ESTIMATE*

SHA1812S VEHICLE NO

10/02/21

MAKE

HYU-140

CHIANG/ NTUC

MODEL	HYU- 140		CHIANG/ NTOC		
Qty	Parts Description/ Labour	Туре	Unit Price	Amount	10 -
	REAR BUMPER COVER			\$1,106.00	1112
2	REAR BUMPER BRACKET SIDE LH/RH		\$35.60	<i>RHX</i> ⁰ \$71.20 \$22.00	MAV
10	REAR BUMPER CLIPS	1	\$2.20	\$22.00	reco
1	REAR BUMPER REFLECTOR / LH			\$32.00	out-
1	REAR BUMPER REINFORCEMENT			\$428.40	
1	REAR BUMPER UNDER COVER			\$228.00	de/
1	BOOTLID MOULDING			\$85.00	4
1	BOOT LID LAMP /LH			\$228.00 \$85.00 \$565.60	* NA
	TAIL LAMP /LH			\$697.80 l	wo
	BOOTLID EMBLEM CRDI			\$52.40	nle -
1	BOOTLID EMBLEM 140			\$52.40	
			2190.60	\$3,340.80	
	20.00%		2190.60	\$668.16	
	DISCOUNTED TOTAL		(17)2 B	\$2,672.64	
			h 1		
1	BOOTID COMFORT & TEL NUMBER STICKER			\$60.00	nce/
	REAR BUMPER MAT			\$50.00	rec/
	REVERSE SENSOR			\$135.70	Kun.
			110.	\$226.13	<i>,</i> .
	Labour Charge				
	Panel Beating			\$700.00	420
	Spray Painting Charge			\$800.00	500
	Remove/refix reverse sensor		980	\$60.00	1
	Check lighting		(0 0	\$60.00	_
	Tuff Kote				Į.
	TOTAL LABOUR			\$90.00	1
	TOTAL LABOUR		0040 160	\$1,710.00	
	CCTINANTE TOTAL		2842.48		
	ESTIMATE TOTAL		2842.48 4s\$2250	\$4,608.77	
			L L		
			# Zelays		
ľ	This is an initial estimate based on a visual inspection of th	e above ve	hicle. The final repair q	uantum will	
	pe prepared after the vehicle is surveyed by a motor Surve	yor appoir	nted by the insurance co	ompany.	

Tanfin 9749 749 WP' 11/2/20 R SSOp-US Resum 18for report tanfini ether anto and.

Howkoop

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company