

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315



AUTOMOBILE INSPECTION REPORT



| NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC21002252/T1qf3e2 | | | | | |
|--|---|-------------------------------------|---------|------------|------------|
| 73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556 | | | Date: | 16-03-2021 | |
| | | | Code: | INC4 | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | | |
| | Insured Veh. | SKA 1466Y | Veh. Ir | nspected | SHD 3196H |
| | Policy No. | 5120903929 | Cover | age (\$) | 0.00 |
| | Claim No. | MT/1123821-001 | Exces | s (\$) | 0.00 |
| | Assign From | | Assig | n Date | 16/02/2021 |
| 2. Vehicle Particulars & Condition | | | | | |
| | Make & Model | HYUNDAI I40 | c.c | | 1685 |
| | Engine No. | HIDDEN | Year o | f Reg. | 2016 |
| | Chassis No. | KMHLB41UMGU091851 | Colou | r | BLUE |
| | Odometer | 650537 | Steeri | ng | IN ORDER |
| | Brakes | IN ORDER | Modifi | cation | SPORTS RIM |
| | General | GOOD | | | |
| 3. Conditions of Tyres | | | | | |
| | | Size | Make | | Balance |
| | R/H Front Tyre | 205/60 R16 | WEST | LAKE | 6 mm |
| | L/H Front Tyre | 205/60 R16 | WEST | LAKE | 6 mm |
| | R/H Rear Tyre | 205/60 R16 | WEST | LAKE | 6 mm |
| | L/H Rear Tyre | 205/60 R16 | WEST | LAKE | 6 mm |
| 4. Description of Damages | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. | | | | |
| | DAMAGES SEE DETAILS. | | | | |
| 5. | General Information | | | | |
| | Accident Date | 12/02/2021 | Inspec | tion Date | 16/02/2021 |
| | Survey held at | COMFORTDELGRO ENGINEERING PTE LTD | | | |
| | | 59 LOYANG DRIVE SINGAPORE 508969 | | | |
| 5a. | Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days | | | | |