

ASS. REC. BY:

REF:

CS3/LPC21002253/R10f3

778R

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBJ 7440R

at Workshop m/s THIAM HENH AUTO

of 7A, 3LN PAPER

Insured: LPC

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 67K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: GBJ 7440R

Yr Regn: 2019/04/25

Type: M.Car / M.Cycle / Bus Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NISSAN NU350 P-V.25 c.c 2488

Colour: Grey

A/C: Insured / Std / NI / NA

Sp. Reading: 47702

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JNIMC2E26200031385

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NII / S/Rim / STD A/Rim or

Tyre Size: F: 195/55R15

R: 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

MIRAGE

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 17/02/2021

D.O.I. 17/02/2021

Survey held at

THIAM HENH

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair limit - 48K

ESTIMATE RANGE OF REPAIR / NO. OF DAYS - (3K - 4K) / 5 days

Date/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

2) 18/2/21-Typist

Days Of Repair: 5

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)

Photos