

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURAI	NCE BHD	R	Ref:	CS3/LPC21002253/R1vf3e2	
	300 BEACH ROAD CONCOURSESING		D	ate:	22/02/2021	
			С	ode:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	YM 635D	Veh. Inspected		GBJ 7440R	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	21/21/21/VC05/024219	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		09/02/2021	
2. Vehicle Particulars & Condition						
	Make & Model	NISSAN NV350 PANEL VAN 2.5	c.c		2488	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	JN1MC2E26Z0031385	Colour		GREY	
	Odometer	46702 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195 R15C	MIRAGE		6 mm	
	L/H Front Tyre	195 R15C	MIRAGE		6 mm	
	R/H Rear Tyre	195 R15C	MIRAGE		6 mm	
	L/H Rear Tyre	195 R15C	MIRAGE		6 mm	
4.	4. Description of Damages					
	THE VEHICLE SUS	STAINED DAMAGES AT THE REAR O/S PORTION.				
5.	•	General Information				
	Accident Date	07/02/2021	Inspect Date / Ti	me	17/02/2021 (04:43 PM)	
	Survey held at	at 7A JALAN PAPAN S619408				
	Repairer	THIAM HENG AUTO (S) PTE LTD				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC21002253/R1vf3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser