

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21002257/URS3Q2**Date:** 15/02/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900081072-01
Claimant Vehicle No :	SKX607T	Insured Vehicle No :	GQ4359S
Date of Loss:	09/02/2021	Nature of Claim:	TP
		Claim No:	9790101778SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKX607T	Engine No:	L15B4024882
Make & Model:	HONDA VEZEL, 1.5 X (A)	Chassis No:	RU11104879
Reg. Date:	25/11/2015 (Man. Year: 2015)	Odometer:	113327 km
Colour:	Maroon		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 7 mm	Rear Left Side:	Dunlop 7 mm
Front Right Side:	Dunlop 7 mm	Rear Right Side:	Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,575.70	3,306.08	4,269.62	56.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,900.00	900.00	1,000.00	52.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,475.70	4,206.08	5,269.62	55.61
Approved Total (Overridden) (S\$)		3,350.00		
(S\$)	9,475.70	3,350.00	6,125.70	64.65
+ GST 7.00/7.00% (S\$)	663.30	234.50	428.80	64.65
Nett Amount (S\$)	10,139.00	3,584.50	6,554.50	64.65
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	17/02/2021		
Date Inspected:	17/02/2021	Inspected At:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA**Manager:** Jaslin Kok Chin Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deep Cut	963.20 F	*762.30 FL
2	1		*FRONT BUMPER LOWER SPOILER	Deformed / Cut	650.00 F	*480.00 FL
3	1		*FRONT BUMPER SIDE RETAINER N/S	Bent	66.50 F	*66.50 FL
4	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
5	1		*FRONT FENDER N/S	Badly Dented	625.20 F	*485.20 FL
6	1		*FRONT FENDER OUTER PROTECTOR N/S	Torn	366.50 F	*180.30 FL
7	1		*FRONT FENDER INNER SHIELD N/S	Torn	288.20 F	*199.20 FL
8	1		*SET FRONT FENDER INNER SHIELD CLIPS N/S	Necessary	50.00 F	*50.00 FL
9	1		*FRONT FENDER INNER PANEL N/S	Repair	615.20 F	*- FL
10	1		*HEADLAMP N/S	Cracked	1,950.00 F	*1,859.10 FL
11	1		*ROCKER PANEL OUTER GARNISH N/S	Not Necessary	645.10 F	*- FL
12	1		*FRONT SHOCK ABSORBER N/S	Not Necessary	455.80 F	*- FL
13	1		*FRONT SPORT RIM N/S (CUT)	Not Consistent With The Impact	850.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	7,575.70	4,132.60
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	826.52
Total Parts (\$\$)	7,575.70	3,306.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO CONDUCT WHEEL ALIGNMENT	New	120.00	0.00
3	TO DISMANTLE & REFIX FRT UNDER CARRIAGE	New	150.00	0.00
4	TO SPRAY RUST PROOFING	New	50.00	30.00
5	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	680.00	300.00
6	TO PUTTY & SPRAY PAINTING	New	850.00	550.00
			Gross Labour Cost (\$)	1,900.00
				900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >