

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

**AUTOMOBILE INSPECTION REPORT** 



| NITLIC   | NICOME INICIID  | NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC21002259/T1td3e2 |         |                    |            |  |  |
|--|---|--|---------|--------------------|------------|--|--|
| NIUC   | J INCOME INSUR  | ANCE CO-OPERATIVE LTD  | Rei:    | NS/INC21002259/1   | 110362     |  |  |
| 73 BRAS BASAH ROAD<br>#05-01 NTUC TRADE UNION HOUSESINGAPORE<br>189556 |   |  | Date:   | 09-03-2021<br>INC4 |            |  |  |
| 1. Policy Particulars :- THIRD PARTY CLAIM                             |   |  |         |                    |            |  |  |
|  | Insured Veh.  | SJV 7364U  | 1       | nspected           | SHD 3893D  |  |  |
|  | Policy No.  | 5114213941-01  |         | <br>age (\$)       | 0.00       |  |  |
|  | Claim No.   | MT/1121271-002   | Exces   |                    | 0.00       |  |  |
|  | Assign From   |  | Assign  | n Date             | 16/02/2021 |  |  |
| 2. Vehicle Particulars & Condition                                     |   |  |         |                    |            |  |  |
|  | Make & Model  | HYUNDAI IONIQ  | c.c     |                    | 1580       |  |  |
|  | Engine No.  | HIDDEN   | Year o  | f Reg.             | 2017       |  |  |
|  | Chassis No.   | KMHC851CVHU022780  | Colou   |                    | BLUE       |  |  |
|  | Odometer  | 445512   | Steerii | ng                 | IN ORDER   |  |  |
|  | Brakes  | IN ORDER   | Modifi  | cation             | SPORTS RIM |  |  |
|  | General   | GOOD   |         |                    |            |  |  |
| 3. Conditions of Tyres   |   |  |         |                    |            |  |  |
|  |   | Size   | Make    |                    | Balance    |  |  |
|  | R/H Front Tyre  | 195/65 R15   | WEST    | LAKE               | 6 mm       |  |  |
|  | L/H Front Tyre  | 195/65 R15   | WEST    | LAKE               | 6 mm       |  |  |
|  | R/H Rear Tyre   | 195/65 R15   | WEST    |                    | 6 mm       |  |  |
|  | L/H Rear Tyre   | 195/65 R15   | WEST    | _AKE               | 6 mm       |  |  |
| 4.   |   |  |         |                    |            |  |  |
|  | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  |  |         |                    |            |  |  |
|  | DAMAGES SEE DETAILS.  |  |         |                    |            |  |  |
| 5.   | General Information   |  |         |                    |            |  |  |
|  | Accident Date   | 15/02/2021   | Inspec  | tion Date          | 16/02/2021 |  |  |
|  | Survey held at  |  |         |                    |            |  |  |
|  |   | 59 LOYANG DRIVE<br>SINGAPORE 508969                                |         |                    |            |  |  |
| 5a.  | Remarks   |  |         |                    |            |  |  |
|  | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |         |                    |            |  |  |
| 5b.  | 5b. Estimate Days of Repair   |  |         |                    |            |  |  |
|  | ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days  |  |         |                    |            |  |  |