

Our Job Ref No : 305453934

Date : 21.02.21

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr TAUFIKH

Vehicle Reg No. : SHD3893D CTPL

15.02.21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: **NTUC** --- **SJV7364U**

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

20%

\$1,650.00

Final Lumpsum Repair cost

\$1,650.00

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and
finalized amount

Signature : 

Name : LIM KWOK ENG

Tel : 62148316

Fax : 65468156

Signature : 

Name : Taufikh

Date : 23/2/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

[illegible]

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 16.02.2021

Time: 14:42:51

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

Jike
 NTUC

JOB NO : 305453934
 REGN NO : SHD3893D
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ
 DATE OF REGN : 24.02.2017
 DATE/TIME IN : 16.02.2021 08:25
 ACCIDENT DATE : 15.02.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G COVER-RR BUMPER#	1 L	459.40	20.00	367.52	ana	
0002 04-01-0104-2288-G BEAM-RR BUMPER	1 L	394.80	20.00	315.84	crat ✓	? part taken - photo
0003 04-01-0101-0111-G BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	nh	
0004 04-01-0104-2533-G MOULDING ASSY-RR BUMPER C	1 L	451.25	20.00	361.00	dl + ? & Supple	1,017.95 - 532.90
0005 09-01-9999-0068-A REVERSE SENSOR ASSY*	1 N	180.00	10.00	162.00	mw	235 - 10% = 211.50
0006 FNPS NUMBER PLATE WITH TRIM CO	1 N	55.00	10.00	49.50	bt	211.50
0007 04-01-0104-2226-G LAMP ASSY-LICENSE PLATE	1 L	85.30	20.00	68.24	mw	1,240.68
Suppl. Rear Bumper Stay Rh - #138.10					part taken - photo	+ Net 211.50
					SUB-TOTAL :	1,341.70

J. NATURE

0000 L	PANEL BEATING	400.00	350	630
0001 23-502	SPRAYPAINT ON AFFECTED AREA	300.00	250	2,082.18
0002 20-22	REMOVE/REFIX REVERSE SENSOR	120.00	30	-202
SUB-TOTAL : 820.00				

Tanpin 17495749

UP 16/2/2020 upm

2 days 4/5 Resum affixed #1,650/-

tanpin@thelands.com