

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21002260/R1BS3Q2
Date: 18/05/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SKT7977A	Insured Vehicle No :	SML2569X
Date of Loss:	06/02/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0000766

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKT7977A		
Make & Model:	KIA FORTE K3, 1.6 SX S/R HID (A)	Engine No:	G4FGFH770876
Reg. Date:	24/06/2015 (Man. Year: 2015)	Chassis No:	KNAFZ411MF5417252
Colour:	Grey	Odometer:	138370 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45Z R17	Rear Tyre Size:	225/45Z R17
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,425.30	4,178.70	246.60	5.57
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,620.00	1,360.00	260.00	16.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,056.30	5,549.70	506.60	8.36
Approved Total (Overridden) (S\$)		4,400.00		

(S\$)	6,056.30	4,400.00	1,656.30	27.35
+ GST 7.00/7.00% (S\$)	423.94	308.00	115.94	27.35
Nett Amount (S\$)	6,480.24	4,708.00	1,772.24	27.35
+ Car Rental (5.0 x S\$120.00/day + 7.00% GST) (S\$)		642.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		5,357.49		
Global Sum Settlement (S\$)		5,300.00		

INSPECTION

Date of Assignment:	17/02/2021	Present Location:	Mova Automotive Pte Ltd (Bukit Merah)
Date Inspected:	03/03/2021	Inspected At:	Mova Automotive Pte Ltd (Bukit Merah) Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3 Singapore 159722
Estimated Period of Repair:	6.0 days		

Adjuster: MOHD RASUL**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 May 2021)
Parts:	143	KIA FORTE K3 1.6 SX S/R HID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKT7977A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Bent	1,365.00 FL	*1,365.00 FL
2	1		*REAR BOOT LOGO	Necessary	82.00 FL	*82.00 FL
3	1		*REAR BOOT EMBLEM FORTE	Necessary	86.00 FL	*86.00 FL
4	1		*REAR BOOT EMBLEM K3	Necessary	75.00 FL	*75.00 FL
5	1		*REAR BOOT EMBLEM C&C	Necessary	40.00 FL	*40.00 FL
6	1		*REAR BOOT LOCK	Not Necessary	100.00 FL	*- FL
7	2		*REAR BOOT HINGE L+R	Not Necessary	130.00 FL	*- FL
8	1		*REAR BOOT RUBBER	Necessary	98.00 FL	*98.00 FL
9	1		*REAR PANEL	Bent	291.00 FL	*291.00 FL
10	1		*REAR PANEL TRIM	Cracked	95.00 FL	*95.00 FL
11	6		*REAR PANEL TRIM CLIPS	Necessary	27.00 FL	*27.00 FL
12	1		*REAR BUMPER TOP	Deformed	690.00 FL	*690.00 FL
13	1		*REAR BUMPER LOWER	Deformed	292.00 FL	*292.00 FL
14	1		*REAR BUMPER REFLECTOR	N/S Not Necessary/ O/S Cracked	88.00 FL	*44.00 FL
15	2		*REAR BUMPER SENSOR	Not Working	518.00 FL	*518.00 FL
16	1		*REAR BUMPER SENSOR WIRE	Cut	265.00 FL	*265.00 FL
17	1		*REAR BUMPER REINFORCEMENT	Bent	296.00 FL	*296.00 FL
18	2		*REAR BUMPER BRACKET L+R	Bent	136.00 FL	*136.00 FL
19	10		*REAR BUMPER CLIPS	Necessary	48.00 FL	*48.00 FL
20	1		*REAR KEYLESS SENSOR	Cut	195.00 FL	*195.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	4,917.00	4,643.00
- List Item Discount on L Items 10.00/10.00% (S\$)	491.70	464.30
Total Parts (S\$)	4,425.30	4,178.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (S\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CUT & WELD REAR PANEL, REAR LAMP PAMEL. TO REPAIR REAR FENDER L+R, REAR FLOOR PANEL, TO REMOVE & REFIX DAMAGED PART, STRAIGHTEN & REALIGN AFFECTED AREAS	New	700.00	600.00
2	TO SPRAY AFFECTED AREAS	New	750.00	650.00
3	TO REMOVE & REFIX REAR LAGGAGE COMPARTMENT SIDE COVER,SIDE GARNISH, SIDE TRIM BOARD CARPET & OTHER ATTACHMENT PARTS	New	60.00	40.00
4	TO INSTALL REVERSE SENSOR & CHECK WATER SEEPAGE	New	50.00	30.00
5	TO RUST PROOF AFFECTED AREAS	New	60.00	40.00
Gross Labour Cost (S\$)			1,620.00	1,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >