

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 6337J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED	459.40	459.40
2	REAR BUMPER SIDE BRACKET RH/LH @\$55.80	NOT NECESSARY	111.60	-
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER REINFORCEMENT	BENT	394.80	394.80
2	REAR BUMPER REINFORCEMENT BRACKET LH/RH @ \$138.10	NOT NECESSARY	276.20	-
1	BOOTLID	BENT	2,480.40	2,480.40
1	BOOTLID LOCK UPPER	BENT	224.00	224.00
1	BOOTLID H EMBLEM	NECESSARY	28.00	28.00
1	BOOTLID HYBRID	NECESSARY	24.30	24.30
1	BOOTLID IONIQ	NECESSARY	31.30	31.30
2	BOOTLID LAMP LH/RH @\$794.40	CUT	1,588.80	1,588.80
1	BOOTLID UPPER GLASS	NOT NECESSARY	907.20	-
1	BOOTLID LOWER GLASS	CRACKED	584.90	584.90
2	TAIL LAMP LH/RH @\$870.40	NOT NECESSARY	1,740.80	-
1	REAR BUMPER CENTRE MOULDING	DEFORMED	451.25	451.25
1	REAR BUMPER LOWER MOULDING	TO REPAIR SEE LABOUR	155.00	-
1	REAR BUMPER FOG LAMP	CRACKED	201.50	201.50
2	NUMBER PLATE LAMP LH/RH @\$85.30	NOT NECESSARY	170.60	-
1	REAR BUMPER CENTRE UNDER COVER	NOT NECESSARY	123.85	-
1	REAR END PANEL	BENT	532.00	532.00
1	REAR PANEL GARNISH	NOT NECESSARY	346.80	-
2	REAR BUMPER REFLECTOR LH/RH @\$41.45	N/S CUT / O/S NOT NECESSARY	82.90	41.45
1	ANTENNA ASSY-SMART	NOT NECESSARY	40.50	-
1	REAR BUMPER TOW COVER	TO REPAIR SEE LABOUR	98.80	-
	LESS 20% DISCOUNT		-2,215.38	-1,412.82
			8,861.52	5,651.28

Report Ref No. NS/INC21002262/T1qd3n2



## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	NETT ITEMS			
1	REAR NUMBER PLATE/W HOLDER (N)	CRACKED	55.00	55.00
1	REAR REVERSE SENSOR (N)	NOT WORKING	180.00	180.00
1	BOOTLID APP LOGO STICKER (N)	NECESSARY	40.00	40.00
2	BOOTLID COMFORT LOGO/TEL NO.STICKER (N)	NECESSARY	60.00	60.00
	LESS 10% DISCOUNT		-33.50	-33.50
			301.50	301.50
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BUMPER LOWER MOULDING AND REAR BUMPER TOW COVER.		1,400.00	1,050.00
	SPRAY PAINTING CHARGE.		800.00	750.00
	CHECK WIRING.		60.00	30.00
	DIAGNOSE/RESET FAULT CODE.		240.00	120.00
	TUFF KOTE.		120.00	30.00
	REMOVE/REFIX REVERSE SENSOR.		60.00	30.00
			2,680.00	2,010.00
	GRAND TOTAL		11,843.02	7,962.78

RECOMMENDED COST OF LUMP SUM REPAIRS		6,350.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. NS/INC21002262/T1qd3n2

**MOHAMAD TAUFIKH** 

M.MATAI, AMSAE-A

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser** 

**Automotive Assessor** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.