

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/III21002264/KPS3Q2**Date:** 17/11/2021REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MFL0006372
Claimant Vehicle No :	SLH7860D	Insured Vehicle No :	SHD2456P
Date of Loss:	14/02/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0000730

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH7860D	Engine No:	3ZRB389681
Make & Model:	TOYOTA HARRIER, 2.0 Premium (A)	Chassis No:	ZSU600015944
Reg. Date:	05/09/2014 (Man. Year: 2014)	Odometer:	117609 km
Colour:	Metallic Black		
Engine Capacity:	1986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	9 mm	Rear Left Side:	7 mm
Front Right Side:	9 mm	Rear Right Side:	7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,707.25	1,357.50	2,349.75	63.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,600.00	1,620.00	1,980.00	55.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,307.25	2,977.50	4,329.75	59.25
Approved Total (Overridden) (S\$)		2,300.00		
(S\$)	7,307.25	2,300.00	5,007.25	68.52
+ GST 7.00/7.00% (S\$)	511.51	161.00	350.51	68.52
Nett Amount (S\$)	7,818.76	2,461.00	5,357.76	68.52
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
(S\$)		2,861.00		
Liable Amount (50.00%) (S\$)		1,430.50		
Global Sum Settlement (S\$)		1,400.00		

INSPECTION

Date of Assignment:	17/02/2021		
Date Inspected:	17/02/2021	Inspected At:	Goldbell Engineering Pte Ltd (Tuas) 10 Tuas Ave 18 Singapore 638894
Estimated Period of Repair:	4.0 days		

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Oct 2021)
Parts:	M1-SUV	TOYOTA HARRIER 2.0 Premium (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLH7860D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP LH	Serviceable	2,150.00 FL	*- FL
2	1		*FRONT FENDER LH	Buckled	980.00 FL	*980.00 FL
3	1		*FRONT BUMPER	Buckled	755.00 FL	*755.00 FL
4	1		*FRONT BUMPER RETAINER LH	Distorted	35.00 FL	*35.00 FL
5	1		*FRONT BUMPER TOW COVER	Serviceable	65.00 FL	*- FL
6	1		*FRONT BUMPER LOWER GRILLE	Serviceable	312.00 FL	*- FL
7	1		*FRONT FOG LAMP COVER LH	Serviceable	128.00 FL	*- FL
8	1		*FRONT FOG LAMP	Serviceable	198.00 FL	*- FL
9	1		*HEADLAMP SUPPORT PANEL LH	Repair	280.00 FL	*- FL
10	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,933.00	1,800.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,225.75	442.50
Total Parts (\$\$)	3,707.25	1,357.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REFIX & REPAIR AFFECTED DAMAGED PARTS INCLUDING KNOCK OUT WELD AND STRAIGHTEN ON THE AFFECTED PARTS	New	1,800.00	900.00
2	TO REPAIR AND ALIGN LH FRONT DOOR	New	300.00	0.00
3	TO CHECK AND RECONNECT ALL NECESSARY WIRING	New	100.00	20.00
4	TO PUTTY ,CLEAN ,SPRAY PAINT AND POLISH ETC	New	1,400.00	700.00
Gross Labour Cost (\$)			3,600.00	1,620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >