

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJT 4181K

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (CONSISTENT)	BUCKLED / DENTED	3,180.08	2,322.00
2	REAR BUMPER BRACKETS (CONSISTENT)	SERVICEABLE	109.45	-
2	REAR BUMPER REFLECTOR (CONSISTENT)	SERVICEABLE	102.36	-
1	REAR BUMPER DIFFUSER (CONSISTENT)	CRACKED	2,675.00	2,675.00
4	REAR SENSOR (CONSISTENT)	SHORTED (1 PCS ONLY)	1,225.80	281.45
1	REAR REINFORCEMENT (CONSISTENT)	TO REPAIR SEE LABOUR	1,125.22	-
	LESS 5% DISCOUNT		-420.90	-263.92
			7,997.01	5,014.53
	SPECIAL NETT ITEMS			
1	REAR BUMPER PAINT PROTECTIVE FILM (SN) (CONSISTENT)	NECESSARY	500.00	300.00
			500.00	300.00
	<u>LABOUR</u>			
	TO CHECK LIGHTINGS AND WIRINGS.		380.00	15.00
	LABOUR TO APPLY PRF FILM ON REAR BUMPER .		380.00	300.00
	LABOUR TO DISMANTLE ,REPAIR ,AND ALIGN THE ABOVE PARTS.INCLUSIVE OF THE REPAIR OF REAR REINFORCEMENT .		800.00	250.00
	TO PUTTY,PRIMER ,SPRAY PAINT REAR BUMPER & REAR BUMPER DIFFUSER .		1,000.00	400.00
	ANTI RUST PROOFING AND GALVANISING AFFECTED & REPLACEMENT PARTS.	NOT NECESSARY	380.00	-
	PROGRAMMING AND CALIBRATION RESET .	NOT NECESSARY	280.00	-
			3,220.00	965.00
	GRAND TOTAL		11,717.01	6,279.53

RECOMMENDED COST OF REPAIRS		6,279.53

Report Ref No. CC4/ASM21002267/Kba3q2

KONG SENG CHEONG

**Licensed Appraiser**