

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21002268/T1VD3Q2**Date:** 19/03/2021REFERENCE

Insured/Claimant: LIM MENG HWA HELEN Policy No: 2100389602
Date of Loss: 16/02/2021 Nature of Claim: OD Claim No: 2814918224SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKP9079A**
Make & Model: KIA FORTE K3, 1.6 (A) Engine No: G4FGEH708584
Reg. Date: 21/10/2014 (Man. Year: 2014) Chassis No: KNAFZ411ME5243645
Colour: Grey Odometer: 125686 km
Engine Capacity: 1591 cc
Market Value/New Car Price: S\$39,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45R17 Rear Tyre Size: 215/45R17
Front Left Side: Roadstone 6 mm Rear Left Side: Roadstone 6 mm
Front Right Side: Roadstone 6 mm Rear Right Side: Roadstone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,703.60	2,418.40	2,285.20	48.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,700.00	4,940.00	760.00	13.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,403.60	7,358.40	3,045.20	29.27
+ GST 7.00/7.00% (S\$)	728.25	515.09	213.16	29.27
Nett Amount (S\$)	11,131.85	7,873.49	3,258.36	29.27

INSPECTION

Date of Assignment: 17/02/2021

Date Inspected: 17/02/2021 Inspected At:

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 12.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PNL ASSY-RR FLOOR RR COMPLETE	Buckled	602.00 FL	*602.00 FL
2	1		*PANEL ASSY-BACK	Bent	372.00 FL	*372.00 FL
3	1		*MAT ASSY-LUGGAGE COVERING	Not Necessary	159.00 FL	*- FL
4	1		*TRIM-TRANSVERSE RR	Not Necessary	58.00 FL	*- FL
5	1		*PANEL ASSY-TRUNK LID	Repair	1,570.00 FL	*- FL
6	1		*LOGO ASSY-KIA SUB	Necessary	37.00 FL	*37.00 FL
7	1		*EMBLEM-CERATO	Necessary	35.00 FL	*35.00 FL
8	1		*BRACKET-RR BUMPER SIDE MTG,LH	Not Necessary	33.00 FL	*- FL
9	1		*BRACKET-RR BUMPER SIDE MTG,RH	Not Necessary	33.00 FL	*- FL
10	1		*GUARD-BUMPER REAR,RH	Not Necessary	17.00 FL	*- FL
11	1		*STAY-RR BUMPER LH	Bent	75.00 FL	*75.00 FL
12	1		*STAY-RR BUMPER RH	Not Necessary	75.00 FL	*- FL
13	1		*BRACKET-RR RAIL UPR MTG,LH	Not Necessary	4.00 FL	*- FL
14	1		*BRACKET-RR RAIL UPR MTG,RH	Not Necessary	4.00 FL	*- FL
15	1		*ANTENNA ASSY-SMARTKEY	Not Necessary	69.00 FL	*- FL
16	1		*BEAM-RR BUMPER	Cut	365.00 FL	*365.00 FL
17	1		*BRACKET-RR BEAM LWR MTG (2pcs)	Bent	10.00 FL	*5.00 FL
18	1		*BRACKET-RR BEAM LWR CTR	Bent	5.00 FL	*5.00 FL
19	1		*WIRING HARNESS-BWS EXT	Not Necessary	173.00 FL	*- FL
20	2		*GROMMET ASSY-SCREW	Not Necessary	4.00 FL	-
21	1		*COVER-RR BUMPER	Deformed	791.00 FL	*791.00 FL
22	1		*COVER-RR BUMPER,UPR	Deformed	245.00 FL	*245.00 FL
23	1		*ULTRASONIC SENSOR ASSY-FBWS	Missing	187.00 FL	*187.00 FL
24	1		*ULTRASONIC SENSOR ASSY-FBWS	Not Necessary	187.00 FL	*- FL
25	1		*ULTRASONIC SENSOR ASSY-FBWS	Not Necessary	187.00 FL	*- FL
26	1		*ULTRASONIC SENSOR ASSY-FBWS	Not Necessary	187.00 FL	*- FL
27	1		*COVER-RR BPR UNDER	Deformed	42.00 FL	*42.00 FL
28	4		*RETAINER-BUMPER SIDE MTG	Not Necessary	4.00 FL	*- FL
29	1		*EMBLEM K3	Necessary	15.00 FL	*15.00 FL
30	1		*SILENCER,FLOOR	Necessary	13.00 FL	*13.00 FL
31	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
32	1		*C&C LOGO	Necessary	40.00 FS	*40.00 FS
33	1		*BODY SEALANT	Necessary	120.00 FS	*80.00 FS
34	1		*SILENCER,FLOOR (Supplementary)	Necessary	13.00 FL	*13.00 FL
35	1		*FORTE EMBLEM (Supplementary)	Necesasry	40.00 FL	*40.00 FL
36	1		*CLAMP-SPARE TIRE (Supplementary)	Deformed	6.00 FL	*6.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,827.00	2,988.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,123.40	569.60
Total Parts (\$\$)	4,703.60	2,418.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	RENEW ACCIDENT DAMAGED PARTS ON REAR FLOOR PANEL,REAR END PANEL,REAR BOOT LID,REAR BUMPER,REPAIR LH REAR FENDER,REPAIR REAR LH CHASSIS	New	2,400.00	2,400.00
2	REMOVE AND INSTALL PARKING ASSIST	New	60.00	60.00
3	REMOVE AND INSTALL REAR CABIN TO FACILITATE REPAIR WORK	New	120.00	120.00
4	PAINT WORK SPRAY REAR FLOOR PANEL,REAR END PANEL,REAR BUMPER,REAR BOOT LID,LH REAR FENDER,LH REAR CHASSIS AND AFFECTED PORTION	New	2,450.00	1,750.00
5	PERFORM RUST PREVENTION	New	120.00	60.00
6	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
7	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
8	REMOVE AND INSTALL FUEL FREE TANK TO FACILITATE REPAIR	New	400.00	400.00
Gross Labour Cost (\$\$)			5,700.00	4,940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >