



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address

AIG Asia Pacific Insurance Pte.
Ltd.
MOTOR CLAIM DEPARTMENT
78 SHENTON WAY #09-16
AIG BUILDING
SINGAPORE 079120
Contact No 64191000

Owner Name & Vehicle Info

Cust No/Name /Lim Meng Hwa Helen
Reg No/Reg Date SKP9079A / 21/10/201
Date In/Mileage / 0
Chassis No KNAFZ411ME5243645
Engine No G4FGEH708584
Make/Model KIA/F K3 1.6 A SX 695 BLACK
Colour/Trim MST / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	17/02/2021/ 14:36	QUD	247 / DonBong	29083

Description of Goods / Services

Qty Unit Price Disc% Amount

E PNT88000					✓ 2400.00
RENEW ACCIDENT DAMAGED PARTS ON REAR FLOOR PANEL, REAR END PANEL, REAR BOOT LID, REAR BUMPER, REPAIR LH REAR FENDER REPAIR REAR LH CHASSIS	400				
E PNT88000					✓ 60.00
REMOVE AND INSTALL PARKING ASSIST					
E PNT88000					✓ 120.00
REMOVE AND INSTALL REAR CABIN TO FACILITATE REPAIR WORK					
E PNT98000					1750 2450.00
PAINT WORK SPRAY REAR FLOOR PANEL, REAR END PANEL, REAR BUMPER, REAR BOOT LID, REAR FENDER, LH REAR CHASSIS AND AFFECTED PORTION					
M SUNDRY					80. 120.00
APPLY BODY SEALANT					✓ 40.00
M SUNDRY					60 120.00
SUPPLY C&C LOGO					
M SUNDRY					✓ 30.00
PERFORM RUST PREVENTION					✓ 120.00
A 54900099					✓ 400.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM					20. 50.00
A 10028901					but ✓ 481.60
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST					bt ✓ 297.60
A 13900099					? 127.20
REMOVE AND INSTALL FUEL FREE TANK TO FACILITATE REPAIR					? 46.40
M SUNDRY					Rx 1256.00
SUNDRIES					✓ 29.60
M PNL ASSY-RR FLOOR RR COMPLETE	1.00	602.00	20.00		
M PANEL ASSY-BACK	1.00	372.00	20.00		
M MAT ASSY-LUGGAGE COVERING	1.00	159.00	20.00		
M TRIM-TRANSVERSE RR	1.00	58.00	20.00		
M PANEL ASSY-TRUNK LID	1.00	1570.00	20.00		
M LOGO ASSY-KIA SUB	1.00	37.00	20.00		

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 ATG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /Lim Meng Hwa Helen Reg No/Reg Date SKP9079A / 21/10/201 Date In/Mileage / 0 Chassis No KNAFZ411ME5243645 Engine No G4FGEH708584 Make/Model KIA/F K3 1.6 A SX 695 BLACK Colour/Trim MST / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	17/02/2021/ 16:01	QUD	247 / DonBong	29083

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M EMBLEM-CERATO	1.00	35.00	20.00	28.00
M BRACKET-RR BUMPER SIDE MTG,LH	1.00	33.00	20.00	26.40
M BRACKET-RR BUMPER SIDE MTG,RH	1.00	33.00	20.00	26.40
M GUARD-BUMPER REAR,RH	1.00	17.00	20.00	13.60
M STAY-RR BUMPER LH	1.00	75.00	20.00	60.00
M STAY-RR BUMPER RH	1.00	75.00	20.00	60.00
M BRACKET-RR RAIL UPR MTG,LH	1.00	4.00	20.00	3.20
M BRACKET-RR RAIL UPR MTG,RH	1.00	4.00	20.00	3.20
M ANTENNA ASSY-SMARTKEY	1.00	69.00	20.00	55.20
M BEAM-RR BUMPER	1.00	365.00	20.00	292.00
M BRACKET-RR BEAM LWR MTG	2.00	5.00	20.00	8.00
M BRACKET-RR BEAM LWR,CTR	1.00	5.00	20.00	4.00
M WIRING HARNESS-BWS EXT	1.00	173.00	20.00	138.40
M GROMMET ASSY-SCREW	2.00	2.00	20.00	3.20
M COVER-RR BUMPER	1.00	791.00	20.00	632.80
M COVER-RR BUMPER,UPR	1.00	245.00	20.00	196.00
M ULTRASONIC SENSOR ASSY-FBWS	1.00	187.00	20.00	149.60
M ULTRASONIC SENSOR ASSY-FBWS	1.00	187.00	20.00	149.60
M ULTRASONIC SENSOR ASSY-FBWS	1.00	187.00	20.00	149.60
M ULTRASONIC SENSOR ASSY-FBWS	1.00	187.00	20.00	149.60
M COVER-RR BPR UNDER	1.00	42.00	20.00	33.60
M RETAINER-BUMPER SIDE MTG	4.00	1.00	20.00	3.20
M EMBLEM K3	1.00	15.00	20.00	12.00
M SILENCER,FLOOR	1.00	13.00	25.00	10.01

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR NAME: Tanfui 97495747

SURVEYOR SIGNATURE: *Tanfui*

DATE: 17/2/2020 350

REMARKS: Not at house, Ex: Hbq
Resurvey before paint 12 days

Confirm & accepted by

Tanfui & [Signature]

7% GST on 10356.01 724.92

Total Payable 11,080.93

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.