Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21002269/APA3Q2

Date: 27/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070174960

Claimant Vehicle No: SLT1509X Insured Vehicle No: SMX2722G

Date of Loss: 08/02/2021 Nature of Claim: TP Claim No: 5654969169SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLT1509X

Make & Model: AUDI A3, 999cc TFSI S TRONIC (LED) (A) Engine No: CHZ551385

Reg. Date: 19/10/2017 (Man. Year: 2017) Chassis No: WAUZZZ8V7J1016626

Colour: White Odometer: 66708 km

Engine Capacity: 999 cc Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40 R18 Rear Tyre Size: 225/40 R18
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		3,436.40	2,451.00	985.40	28.68
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,440.00	580.00	860.00	59.72
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	4,876.40	3,031.00	1,845.40	37.84
	Approved Total (Overridden) (S\$)		2,400.00		
	(S\$)	4,876.40	2,400.00	2,476.40	50.78
	+ GST 7.00/7.00% (S\$)	341.35	168.00	173.35	50.78
	Nett Amount (S\$)	5,217.75	2,568.00	2,649.75	50.78
	+ Car Rental (2.5 x S\$100.00/day + 7.	00% GST) (S\$)	267.50		
	+ Doc/S	earch Fee (S\$)	2.00		
	Ne	tt Liability (S\$)	2,837.50		
	Global Sum Settlement (S\$)		2,820.00		

INSPECTION

Date of Assignment: 17/02/2021

Date Inspected: 17/02/2021 Inspected At: Sk Automobile Pte Ltd

8 Kaki Bukit Ave 4, #08-46 Premier @

Kaki Bukit

Singapore 415875

Estimated Period of Repair: 2.0 days

Adjuster Report Page 2 of 4

Adjuster: ADRIAN LING Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,984.00 FL	*1,984.00 FL
2	1		*REAR BUMPER LOWER SPOILER	Cut	261.00 FL	*261.00 FL
3	1		*REAR BUMPER TOWING COVER	Not Necessary	56.00 FL	*- FL
4	2		*REAR BUMPER REFLECTOR LH/RH	Not Necessary	96.00 FL	*- FL
5	4		*REVERSE SENSOR	Damaged (2 PCS ONLY)	890.00 FL	*445.00 FL
6	1		*REAR BOOT LOCK	Not Necessary	210.00 FL	*- FL
7	1		*REAR BOOT LOCK COVER	Not Necessary	15.00 FL	*- FL
8	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
9	1		*SET REAR RH TAILLAMP CLIP	Not Necessary	50.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
				Sub Total (S\$)	3,612.00	2,720.00
- List Item Discount on L Items 5.00/10.00% (S\$)					175.60	269.00
				Total Parts (S\$)	3,436.40	2,451.00
Report was unsubmitted during this print-out.						

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount			
Lab	<u>Labour Items</u>						
1	LABOUR CHARGE TO PANEL BEAT & STRAIGHTEN AFFECTED PANELS AND REPLACE ABOVE MENTIONED PARTS	New)	560.00	250.00			
2	TO SPRAY PAINT REAR BUMPER ,REVERSE PARKING SENSOR & TOUCH UP AFFECTED AREAS	New	560.00	250.00			
3	TO PERFORM REAR ELECTRICAL WIRING CHECKS AND FUNCTIONALITY CHECKS	N ew	160.00	30.00			
4	INSTALLATION AND CALIBRATION /SETTING FOR REVERSE SENSOR	New	160.00	50.00			
	Gross Labor	ur Cost (S\$)	1,440.00	580.00			

< END OF ESTIMATES >

Report was unsubmitted during this print-out.