



1 Kaki Bukit Ave 6, # 02-22/21/20 @ Autobay Blk D Singapore 417883  
 Company GST Registration No : 201828067M

## VEHICLE INSPECTION ESTIMATE

M/S : AXA Insurance  
 (MOTOR CLAIM DEPARTMENT)

Email : motor.survey@axa.com.sg

*Jasper*

Parts - (%)	
SN	
Labour	
Lump sum	
ERV	

Vehicle No: SKZ6247Z

Date: 15.02.2021

Veh Model : TOYOTA HARRIER

Reg Date : 28.01.2016

Chassis No : ZSU60-0060432

D.O.A : 10.02.2021

1	Tail Gate <i>Disturbed</i>	1	<i>1712</i>	<i>✓</i> 2,378.00
2	Tail Gate Lamps <i>cut</i>	2	533.10	<i>✓</i> 1,066.20
3	Tail Gate 3rd Brake Lamp Assy <i>new</i>	1		+ 293.80
4	Tail Gate Spoiler <i>new</i>	1		+ 5,025.30
5	Tail Gate Lock <i>Damaged</i>	1	561	<i>✓</i> 974.00
6	Tail Gate Lock Cover <i>Damaged</i>	1		- 51.50
7	Tail Gate Latch <i>new</i>	1		+ 81.00
8	Tail Gate "Harrier" Emblem <i>new</i>	1		<i>✓</i> 93.70
9	Tail Gate Toyota Logo <i>new</i>	1		<i>✓</i> 96.20
10	Tail Gate Logo W Plate Light Garnish <i>disturbed</i>	1	<i>981</i>	<del>1,382.40</del>
11	Tail Gate Side Mouldings <i>new</i>	2	1350.50	+ 2,701.00
12	Tail Gate Dampers <i>new</i>	2	1182.40	+ 2,364.80
13	Tail Gate Stoppers <i>new</i>	2	47.80	+ 95.60
14	Tail Gate Glass Moulding <i>new</i>	1		<i>✓</i> 95.20
15	Tail Gate Weatherstrip <i>cut</i>	1		<i>✓</i> 441.30
16	Tail Gate Inner Top Garnish <i>new</i>	1	243.20	+ 243.20
17	Tail Gate Inner Bottom Garnish <i>Damaged</i>	1	578.50	<i>✓</i> 578.50
18	Tail Gate Inner LH Garnish <i>new</i>	1		+ 239.20
19	Tail Gate Inner RH Garnish <i>new</i>	1		- 239.20
				18,440.10

**C/F 18,440.10**



1 Kaki Bukit Ave 6, # 02-22/21/20 @ Autobay Blk D Singapore 417883  
 Company GST Registration No : 201828067M

**VEHICLE INSPECTION ESTIMATE**

B/F 18,440.10

20	Tail Gate Pull Pocket	1		x 109.50
21	Tail Gate Wiper Motor	1		+ 798.90
22	Tail Lamps	2	552.50	2 1,105.00
23	Tail Lamps Brackets	2	85.80	2 171.60
24	Tail Lamps Panel RH	1		+ 345.80
25	Rear Bumper	1	1381	✓ 1,453.00
26	Rear Bumper Lower	1	407	✓ 522.90
27	Rear Bumper Reflector	2	87.50	87.50 175.00 ✓
28	Rear Bumper Side Retainer	2	82.70	✓ 165.40
29	Rear Reinforcement Sponge	1		2 172.60
30	End Panel	1	781	✓ 821.10
31	End Panel Top Garnish	1		✓ 438.30
32	End Panel Smartkey Antenna	1		2 152.00
33	Spare Tyre Panel	1		✓ 818.10
34	Spare Tyre Retainer	1		✓ 70.80
35	Spare Tyre Tool Tray Front	1	405	✓ 782.20
36	Spare Tyre Tool Tray Rear	1	614	2 944.30
37	Spare Tyre Tool Tray Sponge	1		2 339.40
38	Spare Tyre Tool Tray LH	1	367	2 640.50
39	Spare Tyre Tool Tray Cover LH	1		+ 98.20
40	Spare Tyre Tool Tray RH	1	312	2 494.20
41	Spare Tyre Tool Tray Cover RH	1		+ 98.20
42	Spare Tyre Top Board Front	1		+ 885.50
43	Spare Tyre Top Board Rear	1	541	2 692.90
44	Rear Fender	2	1351.10	x 2,702.20
45	Rear Fender Cowling	2	249.80	249.80 499.60
46	Rear Fender Inner Trim	2	128.70	2 257.40
47	Exhaust Pipe Front	1		+ 2,991.80
				37,186.50

C/F 37,186.50



1 Kaki Bukit Ave 6, # 02-22/21/20 @ Autobay Blk D Singapore 417883  
 Company GST Registration No : 201828067M

**VEHICLE INSPECTION ESTIMATE**

B/F

37,186.50

48	Exhaust Pipe Center <i>Bent</i>	1	2585	<del>3,321.60</del>
49	Exhaust Pipe Rear <i>Bent</i>	1		<del>760.60</del>
50	Exhaust Pipe Mounting <i>torn</i>	3	68.70	<del>206.10</del>
51	Rear Shock Absorber RH <i>new</i>	1		<del>167.20</del>
52	Rear Lower Arm RH <i>Bent</i>	1		<del>439.30</del>
53	Rear Stabilizer Link RH <i>?</i>	1		<del>179.30</del>
54	Rear Stabilizer Bar <i>new</i>	1		<del>349.50</del>
55	Rear Stabilizer Bush	2	45.40	<del>90.80</del>
56	Rear Wheel Bearing RH <i>new</i>	1		<del>483.20</del>

43,184.10

18066.10

Less 25%

10,796.03

-13549.57

32,388.08

**Special nett item**

1	Rear Bumper Clips <i>new</i>	1set		<del>30.00</del>
2	Rear Bumper Lower Clips <i>new</i>	1set		<del>30.00</del>
3	Rear Num Plate With Casing <i>Bent</i>	1set		<del>50.70.00</del>
4	End Panel Top Garnish Clips <i>new</i>	1set		<del>20.30.00</del>
5	Rear Fender Cowling Clips <i>new</i>	1set		<del>20.30.00</del>
6	Rear Fender Inner Trim Clips <i>new</i>	1set		<del>2.30.00</del>
7	Tail Lamp Clips <i>new</i>	2		<del>20.60.00</del>
8	Spare Tyre Panel Sealant <i>new</i>	1		<del>60.100.00</del>
9	Tailgate Glass Sealant <i>new</i>	1		<del>60.100.00</del>
10	Windscreen Primer <i>new</i>	1		<del>60.00</del>
11	Windscreen Cleaner <i>new</i>	1		<del>60.00</del>
12	Reverse Sensor <i>Damaged</i>	1set		<del>20.380.00</del>

980.00

580

C/F

33,368.08



1 Kaki Bukit Ave 6, # 02-22/21/20 @ Autobay Blk D Singapore 417883  
 Company GST Registration No : 201828067M

**VEHICLE INSPECTION ESTIMATE**

**B/F**

**33,368.08**

To panel beat/straighten/realign accident affected portion.	<del>1400</del> 2,500.00
To respray accident affected portion.	<del>1000</del> 1,500.00
To tuff coat affected areas.	<del>100</del> 150.00
To remove and refit tailgate glass	<del>120</del> 200.00
To replace/transfer tailgate mechanisms	<del>80</del> 120.00
To remove/refit/replace exhaust pipe	<del>160</del> 250.00
To check/repair wiring	<del>30</del> 120.00
To conduct water leak test.	* 100.00
To remove/refit/replace rear reverse sensor and distance setting	<del>50</del> 150.00
To remove and refit rear interior upholstery.	<del>80</del> 120.00
To conduct wheel alignment	<del>80</del> 120.00
To replace rear RH Undercarriage parts	<del>100</del> 250.00
	<b>38,948.08</b>

3WD

Adrian Lij  
 2/s. 17/02/21.

10 Days.

total: 17329.57  
 w/s: 13.8K

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

14.8k