

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21002277/AEA3Q2**Date:** 19/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993766
Claimant Vehicle No :	SMM7691L	Insured Vehicle No :	SLJ9502P
Date of Loss:	10/02/2021	Nature of Claim:	TP
		Claim No:	6858555735SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM7691L	Engine No:	1ZRY243844
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CVT (A)	Chassis No:	MR053REH104543622
Reg. Date:	13/01/2016 (Man. Year: 2015)	Odometer:	165130 km
Colour:	Black		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,747.30	1,924.95	1,822.35	48.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,940.00	1,280.00	660.00	34.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,687.30	3,204.95	2,482.35	43.65
Approved Total (Overridden) (S\$)		2,500.00		
(S\$)	5,687.30	2,500.00	3,187.30	56.04
+ GST 7.00/7.00% (S\$)	398.11	175.00	223.11	56.04
Nett Amount (S\$)	6,085.41	2,675.00	3,410.41	56.04
+ Loss of Use (7.0 x S\$80.00/day) (S\$)		560.00		
(S\$)		3,235.00		
Liabe Amount (50.00%) (S\$)		1,617.50		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,624.95		
Global Sum Settlement (S\$)		1,650.00		

INSPECTION

Date of Assignment:	17/02/2021		
Date Inspected:	19/02/2021	Inspected At:	KAI MOTOR TRADING (HQ) BLK 3007 UBI ROAD 1, #01-440 Singapore 408701
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR RH	Dented	1,190.10 FL	*1,190.10 FL
2	1		*REAR DOOR INNER RUBBER	Not Necessary	275.40 FL	*- FL
3	1		*REAR FENDER RH	Repair	1,129.30 FL	*- FL
4	1		*REAR BUMPER	Deformed	499.50 FL	*499.50 FL
5	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
6	1		*REAR BUMPER SIDE RETAINER RH	Necessary	131.10 FL	*131.10 FL
7	1		*REAR BUMPER SIDE GARNISH RH	Cut	75.90 FL	*75.90 FL
8	1		*SPORT RIM	Cut	1,233.83 FS	*480.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,585.13	2,406.60
- List Item Discount on L Items 25.00/25.00% (S\$)	837.83	481.65
Total Parts (S\$)	3,747.30	1,924.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE DAMAGE PARTS ,PANEL BEAT WHERE NECESSARY	New	850.00	600.00
2	TO PUTTY ,APPLY PRIMER & SPRAY PAINT ON THE AFFECTED PORTION	New	850.00	600.00
3	TO REMOVE UPHDSTERY	New	80.00	0.00
4	TO CHECK WIRING FUNCTIONS	New	80.00	30.00
5	TO REMOVE REVERSE SENSOR	New	80.00	50.00
Gross Labour Cost (\$\$)			1,940.00	1,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >