

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21002280/KVF3Q2
Date: 10/03/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00087152002
Claimant Vehicle No :	SMV6310X	Insured Vehicle No :	GBE2284J
Date of Loss:	07/02/2021	Nature of Claim:	TP
		Claim No:	SNM21D200782/C03/LOWCT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMV6310X	Engine No:	L15B4022375
Make & Model:	HONDA VEZEL, 1.5 1.5X CVT (A)	Chassis No:	RU11102374
Reg. Date:	31/10/2015 (Man. Year: 2015)	Odometer:	93813 km
Colour:	Metallic Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Dunlop 3 mm	Rear Left Side:	KAPSEN 9 mm
Front Right Side:	Dunlop 3 mm	Rear Right Side:	KAPSEN 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,823.40	4,659.88	3,163.52	40.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,830.00	1,750.00	2,080.00	54.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,653.40	6,409.88	5,243.52	45.00
Approved Total (Overridden) (S\$)		5,100.00		
(S\$)	11,653.40	5,100.00	6,553.40	56.24
+ GST 7.00/7.00% (S\$)	815.74	357.00	458.74	56.24
Nett Amount (S\$)	12,469.14	5,457.00	7,012.14	56.24

INSPECTION

Date of Assignment:	17/02/2021	
Date Inspected:	18/02/2021	Inspected At: 160 Sin Ming Auto City, #08-13 Singapore 575722 Repairer: AERO GARAGE PTE LTD
Estimated Period of Repair:	8.0 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Mar 2021)
Parts:	M1-SUV	HONDA VEZEL 1.5 1.5X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMV6310X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	864.20 F	*495.80 FL
2	2		*FRONT BUMPER RETAINERS	Serviceable	39.00 F	*- FL
3	2		*FRONT BUMPER BRACKETS	Repair	89.80 F	*- FL
4	1		*FRONT BUMPER REINFORCEMENT	Bent	341.30 F	*341.30 FL
5	1		*FRONT BUMPER LOWER AIR GRILLE	Distorted	360.30 F	*351.00 FL
6	1		*SET FRONT BUMPER CLIPS	Necessary	40.00 F	*40.00 FL
7	1		*FRONT GRILLE	Cracked	380.30 F	*380.30 FL
8	1		*FRONT EMBLEM	Necessary	25.40 F	*25.40 FL
9	1		*HEAD LAMP RH	Mtg Cracked	1,923.50 F	*1,715.20 FL
10	1		*REAR BUMPER RH	Bent	173.40 F	*173.40 FL
11	1		*REAR BUMPER (CENTRE)	Dented/Cut	762.70 F	*508.50 FL
12	1		*REAR BUMPER REFLECTOR RH	Serviceable	148.10 F	*- FL
13	1		*REAR BUMPER RETAINERS	O/s Cracked	87.80 F	*43.90 FL
14	1		*SET REAR BUMPER CLIPS	Necessary	40.00 F	*40.00 FL
15	1		*REAR FENDER RH	Bent	1,024.90 F	*931.00 FL
16	1		*REAR FENDER INNER SHIELD RH	Cracked	103.50 F	*103.50 FL
17	1		*REAR FENDER MOULDING RH	Missing	219.30 F	*172.10 FL
18	1		*REAR FENDER INNER SIDE TRIM RH	Serviceable	316.40 F	*- FL
19	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	40.00 F	*- FL
20	1		*TAIL LAMP RH	Cracked	447.20 F	*447.20 FL
21	1		*TAIL LAMP PANEL RH	Repair	136.30 F	*- FL
22	1		*FRONT NUMBER PLATE	Cracked	60.00 FS	*45.00 FS
23	1		*REVERSE SENSOR RH	Serviceable	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,823.40	5,813.60
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	1,153.72
Total Parts (\$)	7,823.40	4,659.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGE TO REMOVE,CUT OUT DAMAGE PORTION,JACK OUT,STRAIGHTEN,PANEL BEATING,WELDING,ALIGN AND RENEW REPLACED PARTS	New	1,800.00	800.00
2	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREAS	New	1,500.00	750.00
3	TO REMOVE,REPLACE FRONT BONNET AND REAR TAILGATE AND FENDER FITTINGS TO FACILITATE REPAIR	New	350.00	120.00
4	TO REMOVE,REPLACE REVERSE SENSOR	New	100.00	50.00
5	TO CHECK WIRING AND LIGHTINGS	New	80.00	30.00
Gross Labour Cost (\$\$)			3,830.00	1,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >