

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21002283/R1VF3Q2

Date: 15/03/2021

REFERENCE

Insured/Claimant:	LAW YONG KHIANG	Policy No:	1800104618	
Date of Loss:	16/02/2021	Nature of Claim:	OD	Claim No: 9501695706SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD8668X			
Make & Model:	MITSUBISHI OUTLANDER, 2.0 (A)	Engine No:	4J11YP6169	
Reg. Date:	05/09/2018 (Man. Year: 2018)	Chassis No:	GF7W0402021	
Colour:	White	Odometer:	35298 km	
Engine Capacity:	1998 cc			
Market Value/New Car Price:	S\$92,000.00			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R18	Rear Tyre Size:	225/55R18
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,032.00	8,134.26	6,897.74	45.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,670.00	4,990.00	1,680.00	25.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,702.00	13,124.26	8,577.74	39.53
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	21,102.00	12,524.26	8,577.74	40.65
+ GST 7.00/7.00% (S\$)	1,477.14	876.70	600.44	40.65
Nett Amount (S\$)	22,579.14	13,400.96	9,178.18	40.65

INSPECTION

Date of Assignment: 17/02/2021

Date Inspected: 18/02/2021 Inspected At:

Cycle & Carriage Automotive Pte Ltd
(Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 9.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACE,FR BUMPER	Deformed	1,133.00 F	*1,133.00 FL
2	1		*BRACKET,FR BUMPER SIDE,LH	Serviceable	18.00 F	*- FL
3	1		*BRACKET,FR BUMPER SIDE,RH	Serviceable	18.00 F	*- FL
4	1		*GARNISH,FR BUMPER,LH	Serviceable	75.00 F	*- FL
5	1		*GARNISH,FR BUMPER,RH	Serviceable	75.00 F	*- FL
6	1		*EXTENSION,FR BUMPER	Serviceable	426.00 F	*- FL
7	1		*BRKT,FR BUMPER SIDE,LWR LH	Serviceable	6.00 F	*- FL
8	1		*BRKT,FR BUMPER SIDE,LWR RH	Serviceable	6.00 F	*- FL
9	1		*GARNISH,FR BUMPER SIDE	Serviceable	48.00 F	*- FL
10	1		*GARNISH,FR BUMPER SIDE	Serviceable	48.00 F	*- FL
11	1		*GARNISH,FR BUMPER SIDE	Cracked	220.00 F	*220.00 FL
12	1		*GARNISH,FR BUMPER SIDE	Cracked	220.00 F	*220.00 FL
13	1		*GARNISH,FR BUMPER SIDE	Serviceable	112.00 F	*- FL
14	1		*GARNISH,FR BUMPER SIDE	Serviceable	112.00 F	*- FL
15	1		*MOULDING,FR BUMPER,RH	Serviceable	116.00 F	*- FL
16	1		*MOULDING,FR BUMPER,LH	Serviceable	116.00 F	*- FL
17	1		*MOULDING,FR WHEEL ARCH,RH	Necessary	160.00 F	*160.00 FL
18	1		*MOULDING,FR WHEEL ARCH,LH	Necessary	160.00 F	*160.00 FL
19	1		*REINFORCEMENT,FR BUMPER	Bent	505.00 F	*505.00 FL
20	1		*REINFORCEMENT,FR BUMPER	Bent	135.00 F	*135.00 FL
21	1		*REINF,FR BUMPER SIDE,RH	Bent	69.00 F	*69.00 FL
22	1		*REINFORCEMENT,FR BMPR SIDE	Serviceable	22.00 F	*- FL
23	1		*REINF,FR BUMPER SIDE,LH	Bent	60.00 F	*60.00 FL
24	1		*COVER,FR BUMPER	Serviceable	25.00 F	*- FL
25	1		*COVER,HEADLAMP SUPT PANEL	Deformed	50.00 F	*50.00 FL
26	1		*GRILLE ASSY,RADIATOR	Scratched	572.00 F	*572.00 FL
27	1		*BRACKET,RADIATOR GRILLE,LH	Deformed	13.00 F	*13.00 FL
28	1		*BRACKET,RADIATOR GRILLE,RH	Deformed	17.00 F	*17.00 FL
29	1		*HOOD	Buckled	980.00 F	*980.00 FL
30	1		*HINGE,HOOD,LH	Serviceable	68.00 F	*- FL
31	1		*HINGE,HOOD,RH	Serviceable	68.00 F	*- FL
32	1		*INSULATOR,HOOD	Serviceable	133.00 F	*- FL
33	1		*WEATHERSTRIP,HOOD	Necessary	40.00 F	*40.00 FL
34	1		*WEATHERSTRIP,HOOD	Serviceable	41.00 F	*- FL
35	1		*LATCH,HOOD	Serviceable	76.00 F	*- FL
36	1		*FENDER,FR LH	Buckled	688.00 F	*688.00 FL
37	1		*FENDER,FR RH	Buckled	688.00 F	*688.00 FL
38	1		*SHIELD,FR WHEELHOUSE,LH	Serviceable	164.00 F	*- FL
39	1		*SHIELD,FR WHEELHOUSE,RH	Serviceable	164.00 F	*- FL
40	1		*PANEL,HEADLAMP SUPPORT,UPR	Bent	183.00 F	*183.00 FL
41	1		*PNL,HEADLAMP SUPT,UPR RH	Serviceable	58.00 F	*- FL
42	1		*PNL,HEADLAMP SUPT,UPR LH	Serviceable	58.00 F	*- FL
43	1		*HEADLAMP ASSY,LH	Cracked	2,135.00 F	*2,135.00 FL
44	1		*HEADLAMP ASSY,RH	Cracked	2,135.00 F	*2,135.00 FL
45	1		*LAMP ASSY,FOG,FR LH	Serviceable	348.00 F	*- FL
46	1		*LAMP ASSY,FOG,FR RH	Serviceable	348.00 F	*- FL
47	1		*HARNESS,FOG LAMP	Serviceable	130.00 F	*- FL
48	1		*CONDENSER ASSY,A/C REFRIGE	Serviceable	857.00 F	*- FL
49	1		*HOSE,A/C COMPR DISCHARGE	Serviceable	191.00 F	*- FL
50	1		*PIPE,A/C CONDENSER OUTLET	Serviceable	262.00 F	*- FL
51	1		*HOSE,A/C COMPR SUCTION	Serviceable	235.00 F	*- FL
52	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
53	1		*NUMBER PLATE WITH FRAME	Not Necessary	50.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	1		*COVER, FR BUMPER (Supplementary)	Scratched	295.00 F	*295.00 FL
55	10		*CLIP,ENG ROOM COVER (Supplementary)	Necessary	20.00 F	*20.00 FL
56	6		*RIVET, FR BUMPER (Supplementary)	Necessary	30.00 F	*30.00 FL
57	10		*CLIP, RR BUMPER (Supplementary)	Necessary	30.00 F	*30.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	15,032.00	10,558.00
- List Item Discount on L Items 0.00/23.00% (S\$)	0.00	2,423.74
Total Parts (S\$)	15,032.00	8,134.26

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	*OD/TP Case (Insurer)	-	0.00
Sub Total (\$\$)			0.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT BUMPER,BONNET,FRT FENDER RH & LH,FRT SUPPORT PANEL.REPAIR FRT DOOR RH & LH	New	2,250.00	1,800.00
2	REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR	New	100.00	0.00
3	TOP UP AIRCON GAS	New	80.00	0.00
4	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
6	REMOVE & INSTALL FRT AIRDAM	New	100.00	100.00
7	SPRAY PAINT FOR FRT AIRDAM,FRT BUMPER,BONNET,FRT SUPPORT PANEL,FRT FENDER RH & LH,FRT DOOR RH & LH	New	3,150.00	2,100.00
8	APPLY SEALANT FOR ACCIDENT PORTION	New	40.00	40.00
9	RENEW FRONT SUPPORT CTR, REPAIR FRONT SUPPORT PANEL RH & LH (Supplementary)	New	450.00	450.00
10	SPRAY PAINT FRONT SUPPORT PANEL RH & LH (Supplementary)	New	350.00	350.00
Gross Labour Cost (\$\$)			6,670.00	4,990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >