



TRANS EUROKARS PTE LTD

ESTIMATE COST OF REPAIRS

LKK - Arabian Link
@ 19 Feb 2021 2 PM
EUROKARS GROUP

CHINA TAIPING INSURANCE P/L		NAME : Ms Wang Wen		WIP : 47851	
3 ANSON ROAD		ADDRESS : Blk 91 Tampines Avenue 1		EXCESS :	
#16-00 SPRINGLEAF TOWER		#04-40		DATE: 16-Feb-21	
SINGAPORE 079909		Singapore 528690			
ATTN. : MOTOR CLAIMS		TEL : 91465858			
FAX :					
VEH NO :	SGW8845Y	DATE IN :		CONTACT PERSON :	RONALD
CHASSIS NO :	JM6CW1071G0125100	MILEAGE :	85011 @ 24 Feb 17	TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA 5	DATE REG.:	24-Feb-17	POLICY NO. :	

NATURE OF WORKS

Parts Description

NO	DESCRIPTION	PARTS NO	QTY	1st	Supp	REVISED	PRICES
1	FRONT BUMPER <i>Defect</i>	MC513-50-031B8B	1				✓ 1,108.20
2	BUMPER RETAINER NO.1 <i>Defect</i>	MC513-50-0T1B	1				✓ 21.60
3	BUMPER RETAINER NO.2 <i>Defect</i>	MC513-50-0U1B	1				+ 21.60
4	FRONT BUMPER BRACKET RH <i>Missing</i>	MC513-50-151A	1				✓ 42.30
5	FRONT BUMPER BRACKET LH <i>Defect</i>	MC513-50-161B	1				+ 41.90
6	GRILLE MESH, FRONT BUMPER <i>Defect</i>	MC514-50-1T0E	1				+ 702.30
7	BUMPER REINFORCEMENT (FOAM) <i>New</i>	MC513-50-111	1				+ 79.20
8	GRILLE MESH, FRONT BUMPER (UPPER) <i>New</i>	MC513-50-7M1E	1				+ 161.70
9	FRONT BUMPER REINFORCEMENT <i>New</i>	MC513-50-070A	1				+ 531.60
10	FOG LAMP COVER(R), HOLE-LAMP <i>New</i>	MC513-50-C11	1				+ 78.20
11	AIR DUCT RHS <i>New</i>	MC597-50-A22	1				+ 33.10
12	MASCOT, LOGO <i>New</i>	MC291-51-731	1				✓ 45.60
13	RIVET, FRONT BUMPER <i>New</i>	MS51S-51-833	3				✓ 12.00
14	PLATE SEAL RHS <i>Not in</i>	MC513-50-1U1	1				+ 34.20
15	FASTENER, FRONT BUMPER <i>New</i>	MFD01-68-AC3	2				✓ 12.40
16	GROMMET, FRONT BUMPER <i>New</i>	MC513-50-0T5A	1				✓ 16.20
17	GROMMET FRONT BUMPER <i>New</i>	MC513-50-0U5A	1				✓ 16.20
18	RIVET, FRONT BUMPER (UPPER) <i>New</i>	MEA01-50-037	4				✓ 32.00
19	FASTENER, FRONT BUMPER (UPPER) <i>New</i>	MGD7A-50-EA1	4				✓ 12.80
20	CLIP, FRONT BUMPER <i>New</i>	MC274-50-133	10				✓ 37.00
21	RIVET, FRONT BUMPER <i>New</i>	MBN8F-50-355	4				✓ 22.80
22	HEADLAMP RHS <i>Defect</i>	MC513-51-0K0F	1				? 1,482.00
23	GUARD MUD RHS <i>Defect</i>	MC513-56-130B	1				✓ 210.50
24	FENDER RHS <i>Defect</i>	MCG37-52-111	1				✓ 322.40
25	STAY(R), FENDER <i>Defect</i>	MC513-52-140	1				✓ 32.10
26	FOG LAMP RHS <i>New</i>	MC597-51-680A	1				+ 340.00
27	TANK, WASHER <i>Defect</i>	MBBN9-67-480A	1				✓ 228.70
28	GARNISH*, D/MIRROR (TRIANGLE) <i>New</i>	MC513-69-15YA	1				+ 76.50
29	HOUSING(R), D/MIRROR <i>New</i>	ML208-69-1A1B13	1				+ 99.60
30	BODY(R), D/MIRROR <i>Not in</i>	MC310-69-121B	1				+ 378.90

31	GLASS & HOLDER(R), D/MIRROR	MCC40-69-1G1	1				+ 60.00
32	LAMP(R),SIDE TURN D/MIRROR	ML208-69-122A	1				x 288.70
33	RHS DOOR	MC5Y3-58-02XE	1				x 1,204.40
34	WEATHERSTRIP(R),DOOR	MC235-58-760G	1				x 80.40
35	CHANNEL(R), DOOR GLASS	MC235-58-605E	1				x 90.80
36	GLASS(R), DOOR VENTILATOR	MCC33-58-661B	1				x 79.00
37	WEATHERSTRIP®, QUARTER GLASS	MC235-58-651B	1				x 41.20
38	HINGE(R),DOOR-UPPER	MC235-58-210C	1				x 47.60
39	CHANNEL, DOOR CENTRE RHS (VERTICAL)	MC235-58-602E	1				x 44.70
40	PROTECTOR(R),CHANNEL	MC235-58-608	1				x 5.20
41	HINGE(R),DOOR-LOWER	MF151-59-210C	1				x 46.50
42	FASTENER, DOOR	MBC1D-58-762	38				x 129.20
43	SIDE SKIRT	MC236-51-P40D13	1				x 935.60
44	BONNET	MC5Y3-52-31X	1				x 1,085.60
45	FASTENER, BONNET	MBBM6-58-762	6				x 19.20
46	RIVET, BONNET	MJ001-56-741	11				x 26.40
47	WHEEL,DISC-ALUMI. CW	M9965-D9-6560	1				x 1,156.00
TOTAL PARTS							11,574.10
TOTAL PARTS COST							11,574.10

SUPPLEMENTARY

NO	DESCRIPTION	PARTS NO	QTY	1st	Supp	REVISED	PRICES
1							
2							
3							
TOTAL PARTS							-
TOTAL PARTS COST							-

Labour Description

1	MZ-BR-FRONT9	TO REPLACE FRONT BUMPER, FRONT BONNET, FRONT FENDER AND FRONT DOOR. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	1320	4,290.00
2	MZ-SP-SFRT09	TO RESPRAY FRONT BUMPER, FRONT FENDER, FRONT BONNET, FRONT DOOR AND SIDE SKIRT.	1260	4,095.00
3	MZ-BR-DOORME	TO TRANSFER THE DOOR MECHANISM.	x	315.00
11	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	250.00
12	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	350.00

14	MZ-BR-WHEALI	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.		X 560.00
16	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.(INCLUDING NEW PARTS AND CAOUTCHOUIC)		X 250.00
19	MZ-BR-SUNDRI	SUNDRIES	NETT	10 100.00

TOTAL LABOUR	-	10,210.00
TOTAL PARTS	-	11,574.10
TOTAL	-	21,784.10
LESS EXCESS	-	-
TOTAL AFTER EXCESS	-	-
GST 7%	-	-
GRAND TOTAL	-	-

SUPPLEMENTARY LABOUR DESCRIPTION

1		#N/A		
2		#N/A		

TOTAL LABOUR	-	-
TOTAL PARTS	-	-
TOTAL	-	-
LESS EXCESS	-	-
TOTAL AFTER EXCESS	-	-
GST 7%	-	-
GRAND TOTAL	-	-

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature

Adrian Lj
P/P 19/02/21
04 Days

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: