

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21002287/KBS3Q2
Date: 09/09/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100409509
Claimant Vehicle No :	SGZ6010L	Insured Vehicle No :	SGX1691P
Date of Loss:	15/02/2021	Nature of Claim:	TP
		Claim No:	6697454400SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGZ6010L	Engine No:	1NZC770619
Make & Model:	TOYOTA COROLLA AXIO, 1.5 X (M)	Chassis No:	NZE1416054630
Reg. Date:	09/11/2007 (Man. Year: 2007)	Odometer:	241725 km
Colour:	Metallic Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Tourador 7 mm	Rear Left Side:	Tourador 7 mm
Front Right Side:	Tourador 7 mm	Rear Right Side:	Tourador 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,440.85	3,559.66	2,881.19	44.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,940.00	1,420.00	520.00	26.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,380.85	4,979.66	3,401.19	40.58
Approved Total (Overridden) (S\$)		3,950.00		

(S\$)	8,380.85	3,950.00	4,430.85	52.87
+ GST 7.00/7.00% (S\$)	586.66	276.50	310.16	52.87
Nett Amount (S\$)	8,967.51	4,226.50	4,741.01	52.87
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,588.50		

INSPECTION

Date of Assignment: 17/02/2021

Date Inspected: 18/02/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Ah Lim Motor Company (AMK)
 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint
 Singapore 568047

Adjuster: KENNETH KONG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Buckled	1,041.60 FL	*972.45 FL
2	2		*FRONT BONNET HINGE LH & RH	Repair	139.40 FL	*- FL
3	10		*FRONT BONNET INSULATOR CLIPS	Not Necessary	41.00 FL	*- FL
4	1		*HEADLAMP RH	Cracked	676.30 FL	*676.30 FL
5	1		*FRONT GRILLE W CHROME MOULDING	Cracked	442.20 FL	*442.20 FL
6	1		*FRONT GRILLE CLIPS	Necessary	4.20 FL	*4.20 FL
7	1		*FRONT BUMPER	Cracked	551.40 FL	*478.80 FL
8	1		*FRONT BUMPER SIDE RETAINER LH & RH	O/S Distorted	126.80 FL	*63.40 FL
9	15		*FRONT BUMPER CLIPS	Necessary	63.00 FL	*63.00 FL
10	1		*FRONT BUMPER REINFORCEMENT	Repair	336.20 FL	*- FL
11	1		*FRONT FENDER RH	Buckled	388.50 FL	*388.50 FL
12	1		*RADIATOR SUPPORT PANEL	Repair	876.30 FL	*- FL
13	1		*AIR CON CONDENSER	Bent	1,801.70 FL	*1,474.50 FL
14	1		*RADIATOR	Serviceable	1,916.33 FL	*- FL
15	1		*RADIATOR TOP GARNISH	Cracked	96.20 FL	*96.20 FL
16	1		*RADIATOR COOLANT	Necessary	30.00 FS	*30.00 FS
17	1		*NUMBER PLATE	Cracked	35.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	8,566.13	4,724.55
- List Item Discount on L Items 25.00/25.00% (S\$)	2,125.28	1,164.89
Total Parts (S\$)	6,440.85	3,559.66

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING ,WIRE SOCKETS AND ETC .TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS ,TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	20.00
2	TO RE-CHARGE AIRCON GAS & ETC	New	100.00	100.00
3	TO DISMANTLE ALL DAMAGED PARTS TO CUT & WELD RADIATOR SUPPORT PANEL TO KNOCK & REPAIR FRONT DOOR RH INNER PANELS AND AFFECTED AREAS .TO REFIT LISTED PARTS BACK SAME	New	900.00	500.00
4	TO SPRAY FRONT BONNET ,FRONT BUMPER ,FRONT FENDER LH & RH ,RADIATOR SUPPORT PANEL ,FRONT DOOR RH	New	900.00	800.00
Gross Labour Cost (S\$)			1,940.00	1,420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >