

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/ICS21002289/AVF3E2

**Date:** 28/04/2021

### REFERENCE

Handling Insurer: ECICS Limited Policy No: MPC20A00037700  
Claimant Vehicle No : SMQ6168S Insured Vehicle No : SMP7556D  
Date of Loss: 17/02/2021 Nature of Claim: TP Claim No: DMPC2100055H

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMQ6168S**  
Make & Model: MERCEDES-BENZ GLA180 URBAN (R18 LED), 1.6 (A) Engine No: 27091031911380  
Reg. Date: 27/11/2019 (Man. Year: 2019) Chassis No: WDC1569422J659558  
Colour: Black Odometer: 19686 km  
Engine Capacity: 1595 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 235/50 R18 Rear Tyre Size: 235/50 R18  
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm  
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,373.23	5,868.60	6,504.63	52.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,380.00	730.00	1,650.00	69.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>14,753.23</b>	<b>6,598.60</b>	<b>8,154.63</b>	<b>55.27</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,032.73</b>	<b>461.90</b>	<b>570.83</b>	<b>55.27</b>
<b>Nett Amount (S\$)</b>	<b>15,785.96</b>	<b>7,060.50</b>	<b>8,725.46</b>	<b>55.27</b>

### INSPECTION

Date of Assignment: 17/02/2021  
Date Inspected: 18/02/2021 Inspected At: Ryder Auto Pte Ltd (HQ)  
2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit  
Singapore 417921  
Estimated Period of Repair: 3.0 days

**Adjuster:** ADRIAN LING

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 28 Apr 2021)

**Parts:** M1-SUV MERCEDES-BENZ GLA180 URBAN (R18 LED) 1.6 (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SMQ6168S)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Distorted	1,512.00 FL	*1,385.00 FL
2	1	*REAR BUMPER TOP CHROME GARNISH	Bent	305.50 FL	*305.50 FL
3	1	*REAR BUMPER LOWER DIFFUSER	Deformed	762.00 FL	*525.00 FL
4	1	*REAR BUMPER LOWER DIFFUSER GARNISH	Deformed	1,194.00 FL	*838.00 FL
5	1	*REAR BUMPER O/S & N/S RETAINER	N/S Necessary	320.00 FL	*160.00 FL
6	1	*REAR BUMPER N/S MIDDLE RETAINER	Cracked	160.00 FL	*160.00 FL
7	1	*REAR BUMPER CENTRE RETAINER	Cracked	210.00 FL	*210.00 FL
8	1	*REAR END PANEL	Repair	1,716.00 FL	*- FL
9	1	*REAR N/S TAIL-LAMP	Cracked	981.50 FL	*676.00 FL
10	1	*REAR TAIL GATE N/S REFLECTOR	Not Necessary	728.00 FL	*- FL
11	1	*REAR TAIL GATE EMBLEM	Necessary	143.00 FL	*143.00 FL
12	1	*REAR TAIL GATE GLA 180 EMBLEM	Necessary	123.50 FL	*123.50 FL
13	1	*REAR TAIL GATE C&C EMBLEM	Necessary	65.60 FL	*65.60 FL
14	1	*REAR TAILGATE CHROME MOULDING	Not Necessary	364.60 FL	*- FL
15	1	*REAR N/S WHEEL ARCH GARNISH	Not Necessary	325.00 FL	*- FL
16	1	*REAR EXHAUST MUFFLER	Not Necessary	1,690.00 FL	*- FL
17	2	*REAR EXHAUST MUFFLER MOUNTING	Not Necessary	234.00 FL	*- FL
18	1	*REAR N/S EXHAUST MUFFLER GARNISH CHROME	Cut	600.00 FL	*385.00 FL
19	1	*REAR EXHAUST HEAT SHIELD	Crumpled	365.60 FL	*126.00 FL
20	1	*REAR N/S WHEEL ARCH GARNISH	Deformed	256.40 FL	*256.40 FL
21	10	*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
22	1	*REAR REVERSE SENSOR (3PCS)	Damaged (2Pcs Only)	720.00 FS	*480.00 FS
23	1	*REAR BUMPER ENFORCEMENT	Bent	858.00 FL	*595.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>13,664.70</b>	<b>6,464.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	1,291.47	595.40
<b>Total Parts (\$)</b>	<b>12,373.23</b>	<b>5,868.60</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE DAMAGED PARTS, STRAIGHTEN & WELDING	New	1,000.00	300.00
2	TO SPRAY PAINTING	New	1,000.00	400.00
3	TO RE-SET ELECTRICAL SYSTEM	New	180.00	0.00
4	TO CHECK WIRING	New	100.00	30.00
5	TO RE-SEAL ANTI-RUST	New	100.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,380.00</b>	<b>730.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >