

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	SOMPO INSURAN	ICE SINGAPORE PL	Re	ef:	CS/SMO21002290/EKqf3n2	
	50 RAFFLES PLAC SINGAPORE LANI	CE #03-03 D TOWERSINGAPORE 048623	Da	ate:	09/06/2021	
			Co	ode:	SMO	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJU 132Z	Veh. Inspected		SMJ 7896D	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	CMTD2100526/GPL	Excess (\$)		0.00	
	Assign From	MELVIN YE	Assign Date		17/02/2021	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA SHUTTLE	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	GP72001538	Colour		GREY	
	Odometer	153997 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	185/60 R15	BRIDGESTONE		4 mm	
	L/H Front Tyre	185/60 R15	BRIDGESTONE		4 mm	
	R/H Rear Tyre	185/60 R15	BRIDGESTONE		4 mm	
	L/H Rear Tyre	185/60 R15	BRIDGESTONE		4 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	04/02/2021	Inspection Date		15/03/2021	
	Survey held at	MOVA AUTOMOTIVE PTE LTD				
		BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 . SINGAPORE 159722				
5a.		Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.		Estimate Days of Repair				
	ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				