

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

**Our File No:** CS/MSG21002291/AGTD3Q2  
**Date:** 10/06/2021

REFERENCE

|                              |                                      |                             |            |
|------------------------------|--------------------------------------|-----------------------------|------------|
| Handling Insurer:            | MSIG Insurance (Singapore) Pte. Ltd. | Policy No:                  | 1001450117 |
| <b>Claimant Vehicle No :</b> | SGC8211G                             | <b>Insured Vehicle No :</b> | SJH3920P   |
| Date of Loss:                | 18/12/2020                           | Nature of Claim:            | TP         |
|                              |                                      | Claim No:                   | 253280     |

DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |              |
|-----------------------------|-----------------------------------|-------------|--------------|
| Reg No:                     | <b>SGC8211G</b>                   | Engine No:  | 2ARH544769   |
| Make & Model:               | TOYOTA ALPHARD, 2.4 (A)           | Chassis No: | AGH300009618 |
| Reg. Date:                  | 23/12/2015 (Man. Year: 2015)      | Odometer:   | 110324 km    |
| Colour:                     | Black                             |             |              |
| Engine Capacity:            | 2493 cc                           |             |              |
| Market Value/New Car Price: | N/A                               |             |              |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |              |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |     |                         |     |                          |     |
|--------------------------|-----|-------------------------|-----|--------------------------|-----|
| General Condition:       |     | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification:    | No  | Pre-accident Condition:  |     |

CONDITION OF TYRES

|                   |                  |                  |                  |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size:  | 235/50 R18       | Rear Tyre Size:  | 235/50 R18       |
| Front Left Side:  | Bridgestone 6 mm | Rear Left Side:  | Bridgestone 6 mm |
| Front Right Side: | Bridgestone 6 mm | Rear Right Side: | Bridgestone 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 6,367.55          | 1,274.25          | 5,093.30          | 79.99         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 2,550.00          | 700.00            | 1,850.00          | 72.55         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>8,917.55</b>   | <b>1,974.25</b>   | <b>6,943.30</b>   | <b>77.86</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>1,550.00</b>   |                   |               |

|                               |                 |                 |                 |              |
|-------------------------------|-----------------|-----------------|-----------------|--------------|
| (S\$)                         | 8,917.55        | 1,550.00        | 7,367.55        | 82.62        |
| <b>+ GST 7.00/7.00% (S\$)</b> | 624.23          | 108.50          | 515.73          | 82.62        |
| <b>Nett Amount (S\$)</b>      | <b>9,541.78</b> | <b>1,658.50</b> | <b>7,883.28</b> | <b>82.62</b> |

INSPECTION

Date of Assignment: 18/02/2021

Date Inspected: 18/02/2021

Estimated Period of Repair: 3.0 days

Inspected At: Stk Auto (s) Pte Ltd (HQ)  
8 kaki bukit ave4, #03-21  
Singapore 415875

**Adjuster:** XING GUO QIANG**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                          |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 10 Jun 2021)            |
| <b>Parts:</b>        | M1-MPV                                                                                                                                                                       | TOYOTA ALPHARD 2.4 (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                        |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SGC8211G)                                                                                                                                    |                                                          |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                          |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                          |

### Recommended Parts

| No. | Qty | Part No. | Particulars                        | Condition     | Repairer's  | Amount       |
|-----|-----|----------|------------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *RH REAR FENDER                    | Repair        | 1,521.10 FL | *- FL        |
| 2   | 1   |          | *RH REAR DOOR                      | Not Necessary | 2,078.70 FL | *- FL        |
| 3   | 1   |          | *RH REAR CORNER PANEL GARNISH      | Deformed      | 1,500.00 FL | *377.00 FL   |
| 4   | 1   |          | *REAR BUMPER                       | Deformed      | 1,853.00 FL | *1,217.00 FL |
| 5   | 1   |          | *REAR BUMPER REFLECTOR RH          | Not Necessary | 215.60 FL   | *- FL        |
| 6   | 1   |          | *REAR BUMPER RETAINER RH           | Not Necessary | 65.00 FL    | *- FL        |
| 7   | 1   |          | *REAR BUMPER RETAINER LH           | Necessary     | 65.00 FL    | *65.00 FL    |
| 8   | 1   |          | *TAILGATE EMBLEM                   | Not Necessary | 125.00 FL   | *- FL        |
| 9   | 10  |          | *REAR BUMPER CLIPS                 | Necessary     | 50.00 FS    | *30.00 FS    |
| 10  | 10  |          | *REAR END PANEL TOP GARNISH CLIPS  | Not Necessary | 50.00 FS    | *- FS        |
| 11  | 10  |          | *RH REAR FENDER INNER SHIELD CLIPS | Not Necessary | 50.00 FS    | *- FS        |
| 12  | 1   |          | *REAR BUMPER REVERSE SENSOR        | Not Necessary | 650.00 FS   | *- FS        |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                 |                 |
|------------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>8,223.40</b> | <b>1,689.00</b> |
| <b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b> | 1,855.85        | 414.75          |
| <b>Total Parts (\$\$)</b>                                  | <b>6,367.55</b> | <b>1,274.25</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                                    | Lab.Type | Repairer's      | Amount        |
|--------------------------------|------------------------------------------------|----------|-----------------|---------------|
| <u>Labour Items</u>            |                                                |          |                 |               |
| 1                              | TO STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS    | New      | 1,000.00        | 300.00        |
| 2                              | TO SPRAY PAINT ON ACCIDENT AREAS               | New      | 1,000.00        | 350.00        |
| 3                              | TO REMOVE AND REFIT RH REAR DOOR GLASS         | New      | 150.00          | 0.00          |
| 4                              | TO CONDUCT WIRING AND REMOVE AND REFIT REVERSE | New      | 100.00          | 50.00         |
| 5                              | TO CONDUCT WHEEL ALIGNMENT                     | New      | 150.00          | 0.00          |
| 6                              | TO RUST RPOOFING ACCIDENT AREAS                | New      | 150.00          | 0.00          |
| <b>Gross Labour Cost (S\$)</b> |                                                |          | <b>2,550.00</b> | <b>700.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >