

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Page No.:1 of 1

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT AXA INSURANCE PTE LTD CS3/ASM21002298/R1qf3e2 Ref: 8 SHENTON WAY #24-01 AXA Date: 29/03/2021 **TOWERSINGAPORE 068811** ATTN: YU DOMINIC YISHAN Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. JRM 4005 SHA 6971H Veh. Inspected Policy No. VFX/P2419138 Coverage (\$) 0.00 Claim No. S1M0351H Excess (\$) 0.00 YU DOMINIC YISHAN **Assign Date** 17/02/2021 Assign From **Vehicle Particulars & Condition** 2. YAMAHA Make & Model 0 c.c HIDDEN Engine No. Year of Reg. **MULTI COLOUR** Chassis No. Colour Odometer 74888 KM Steering IN ORDER **IN ORDER** SPORTS RIM **Brakes** Modification **FAIR** General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 70/90-17 MICHELIN 3 mm L/H Front Tyre mm 90/80-17 **MICHELIN** R/H Rear Tyre 3 mm L/H Rear Tyre mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. 5. **General Information** 30/01/2021 24/02/2021 ( 02:43 PM ) Accident Date Inspect Date / Time HUA CHIN (2000) TRADING MOTOR SVC CENTRE Survey held at 50, BUKIT BATOK STREET 23, #02-02 MIDVIEW BUILDING SINGAPORE 659578 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000

Report Ref No. CS3/ASM21002298/R1qf3e2

**Estimate Days of Repair** 

Inspected By

**Automotive Assessor** 

5b.

MOHAMMED RASUL BIN MOHD YUNUS

**ESTIMATED NORMAL PERIOD FOR REPAIR:** 

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

4 Working Days

REGD Auto Consultant-SAE, Licensed Appraiser