

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/GRB21002303/KBS3Q2
Date: 05/05/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	GBB7087U	Insured Vehicle No :	SLN7038E
Date of Loss:	11/02/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0000710

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBB7087U		
Make & Model:	NISSAN URVAN, 3.0 LWB 5DR 4AT ABS A/B (M)	Engine No:	ZD30239699K
Reg. Date:	05/12/2009 (Man. Year: 2009)	Chassis No:	JN1MG4E25Z0793195
Colour:	Silver	Odometer:	225092 km
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185 R15X8	Rear Tyre Size:	185 R15X8
Front Left Side:	OHTSU 8 mm	Rear Left Side:	Sumitomo 8 mm
Front Right Side:	OHTSU 8 mm	Rear Right Side:	Sumitomo 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,562.30	4,583.37	3,978.93	46.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,940.00	1,430.00	1,510.00	51.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,502.30	6,013.37	5,488.93	47.72
Approved Total (Overridden) (S\$)		4,800.00		

Nett Amount (S\$)	11,502.30	4,800.00	6,702.30	58.27
+ Car Rental (13.0 x S\$180.00/day) (S\$)		2,340.00		
Nett Liability (S\$)		7,140.00		
Global Sum Settlement (S\$)		7,000.00		

INSPECTION

Date of Assignment: 17/02/2021

Date Inspected: 18/02/2021

Estimated Period of Repair: 5.0 days

Inspected At:

T & B Motor Repairs Services Pte Ltd
 Blk 160 Sin Ming Drive #08-03, Sin Ming Auto City
 Singapore 575722

Adjuster: KENNETH KONG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 13 Apr 2021)	
Parts:	N/A	NISSAN URVAN 3.0 LWB 5DR 4AT ABS A/B (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBB7087U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT SIDE PANEL LH	Repair	525.50 F	*- FN
2	1		*FRONT HEAD LAMP L/H	Cut	458.70 F	*458.70 FN
3	1		*FRONT BUMPER	Bent	541.00 F	*541.00 FN
4	1		*FRONT BUMPER SIDE RETAINER LH	Distorted	116.10 F	*116.10 FN
5	1		*FRONT BUMPER SIDE SPORT LAMP COVER L/H	Dented	130.10 F	*130.10 FN
6	1		*FRONT GRILLE	Serviceable	475.70 F	*- FN
7	1		*FRONT LOWER ARM LH	Distorted	220.50 F	*220.50 FN
8	1		*FRONT WHEEL BEARING HUB ASSY LH	Bent	596.10 F	*560.00 FN
9	1		*FRONT STEERING RACK END PINION ASSY	Bent / Jammed	1,950.20 F	*1,559.20 FN
10	2		*FRONT STABILIZER BAR LINK LH/RH	Serviceable	103.00 F	*- FN
11	2		*AUTO GEAR BOX OIL PIPE RUBBER HOSE	Serviceable	352.00 F	*- FN
12	1		*AUTO GEAR BOX OIL PIPE	Serviceable	131.60 F	*- FN
13	1		*FRONT TYRE LH	Serviceable	220.00 F	*- FN
14	1		*STEP GARNISH LH	Dented / Cut	416.30 F	*384.30 FN
15	4		*STEP GARNISH CLIPS	Necessary	22.00 F	*22.00 FN
16	8		*FRONT BUMPER CLIPS	Necessary	46.40 F	*46.40 FN
17	1		*FRONT BUMPER SIDE SPORT LAMP L/H	Serviceable	323.70 FS	*- FS
18	2		*(LH/RH) FRONT ENGINE MOUNTING	Serviceable	201.40 FS	*- FS
19	1		*(L/H) FRONT GEAR BOX MOUNTING	Serviceable	191.10 FS	*- FS
20	2		*(LH/RH) FRONT SHOCK ABSORBER	Serviceable	262.40 FS	*- FS
21	1		*FRONT KNUCKLE ARM LH	Bent	351.50 FS	*351.50 FS
22	1		*FRONT LOWER ARM BALL JOINT LH	Serviceable	91.70 FS	*- FS
23	1		*AUTO GEAR BOX OIL COOLER	Punctured	597.40 FS	*597.40 FS
24	1		*FRONT TYRE RIM LH	Serviceable	237.90 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$)

8,562.30

4,987.20

- Nett Item Discount on N Items 0.00/10.00% (\$)

0.00

403.83

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	8,562.30
						4,583.37
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING	New	60.00	50.00
2	CHECK & REPAIR WIRING	New	80.00	20.00
3	SPRAY ANTI-RUST COATING	New	150.00	0.00
4	REMOVE & REPLACE THE NEW FRONT L/H UNDERCARRIAGE PARTS	New	550.00	220.00
5	CHECK & REPLACE THE NEW TRANSMISSION COOLER & TOP TRANSMISSION OIL	New	280.00	180.00
6	COMPUTER WHEEL ALIGNMENT	New	120.00	60.00
7	SPRAY PAINTING ON AFFECTED PORTIONS	New	750.00	500.00
8	LABOUR CHARGE FOR REPAIRING ADJUSTING ,KNOCKING WELDING THE DAMAGED PARTS ,STRAIGHTEN THE ABOVE	New	950.00	400.00
Gross Labour Cost (S\$)			2,940.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >