

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 8798S

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR DOOR RH	TO REPAIR SEE LABOUR	916.50	-
1	REAR DOOR LOCK RH	NOT NECESSARY	433.87	-
1	REAR FENDER RH	TO REPAIR SEE LABOUR	970.10	-
1	REAR FENDER LINER RH	NOT NECESSARY	154.40	-
1	ROCKER PANEL GARNISH RH	CUT / TORN	670.50	645.10
1	REAR WHEEL CAP RH	CUT	185.97	185.97
1	REAR KNUCKLE ARM RH	NOT NECESSARY	580.64	-
1	REAR LOWER ARM RH	NOT NECESSARY	250.21	-
1	REAR TRAILING ARM RH	NOT NECESSARY	210.35	-
1	REAR WHEEL HUB RH	NOT NECESSARY	493.85	-
	LESS 20% DISCOUNT		-973.28	-
	LESS 25% DISCOUNT		-	-207.77
			3,893.11	623.30
1	REAR SPORT RIM RH (SN)	DENTED	1,555.10	600.00
-	LESS 20% DISCOUNT		-311.02	-
			1,244.08	600.00
	SPECIAL NETT ITEMS		.,	
1	REAR TYRE RH (SN)	SERVICEABLE	250.00	-
1	SET REAR FENDER LINER CLIP (SN)	NOT NECESSARY	50.00	-
			300.00	-
	<u>LABOUR</u>			
	TO DO 4 WHEEL ALIGNMENT.		120.00	60.00
	TO TRANSFER REAR DOOR MECHANISM.	NOT NECESSARY	120.00	-
	TO PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR DOOR RH AND REAR FENDER RH.		800.00	400.00
	TO SPRAY PAINTING.		1,000.00	600.00

Report Ref No. CS/SMO21002304/Uvf3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO REMOVE & REFIX REAR UNDERCARRIAGE.	NOT NECESSARY	120.00	-
			2,160.00	1,060.00
	GRAND TOTAL		7,597.19	2,283.30

RECOMMENDED COST OF LUMP SUM REPAIRS	1,800.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/SMO21002304/Uvf3q2

CHUA KANG SENG