

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21002305/DTD3N2**Date:** 31/08/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00003882001

Claimant Vehicle No : XE944R **Insured Vehicle No :** YL359G

Date of Loss: 19/01/2021 Nature of Claim: TP **Claim No:** SNM21D200940/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **XE944R**

Make & Model: MITSUBISHI FUSO, 10.7 D FV70HJA00064 (M) Engine No: OM457298441

Reg. Date: 28/08/2015 (Man. Year: 2015) Chassis No: FP51SDA10183

Colour: Blue Odometer: 400538 km

Engine Capacity: 11967 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 295/80R22.5 Rear Tyre Size: 295/80R22.5(D)

Front Left Side: HILO 5 mm Rear Left Side: HILO 5/5 mm

Front Right Side: HILO 5 mm Rear Right Side: HILO 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	36,997.02	6,838.02	30,159.00	81.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,400.00	2,190.00	12,210.00	84.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	51,397.02	9,028.02	42,369.00	82.43
Approved Total (Overridden) (S\$)		7,000.00		
(S\$)	51,397.02	7,000.00	44,397.02	86.38
+ GST 7.00/7.00% (S\$)	3,597.79	490.00	3,107.79	86.38
Nett Amount (S\$)	54,994.81	7,490.00	47,504.81	86.38

INSPECTION

Date of Assignment: 18/02/2021

Date Inspected: 19/02/2021 Inspected At: JWG International Pte Ltd (HQ)
Blk 10, Ang Mo Kio Ind Park 2A., #03-08 AMK
AutoPoint
Singapore 568047

Estimated Period of Repair: 6.0 days

Adjuster: BRYAN TANI**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 31 Aug 2021)**Parts:** N/A MITSUBISHI FUSO 10.7 D FV70HJA00064 (M) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for XE944R)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR LH	Dented/Torn	2,980.00 FL	*1,992.07 FL
2	1		*FRONT DOOR LOCK LH	Not Necessary	510.00 FL	*- FL
3	1		*FRONT DOOR WEATHER STRIP LH	Not Necessary	439.00 FL	*- FL
4	1		*FRONT DOOR WINDOW MOULDING LH	Not Necessary	239.00 FL	*- FL
5	2		*FRONT DOOR HINGE	Repair	356.00 FL	*- FL
6	1		*FRONT DOOR INNER TRIM BOARD LH	Not Necessary	1,782.50 FL	*- FL
7	1		*FRONT SIGNAL LAMP LH	Not Necessary	980.80 FL	*- FL
8	1		*FRONT SIGNAL LAMP PANEL LH	Mounting Broken	1,114.20 FL	*593.26 FL
9	1		*FRONT SIGNAL LAMP WIRE HARNESS	Not Necessary	1,992.40 FL	*- FL
10	1		*FRONT CENTER PANEL	Not Necessary	1,292.00 FL	*- FL
11	1		*FRONT SIGNAL LAMP LOWER PANEL LH	No such part	789.20 FL	*- FL
12	1		*FRONT BUMPER	Dented	2,901.00 FL	*2,259.31 FL
13	1		*FRONT BUMPER CENTER GARNISH	Not Necessary	1,401.20 FL	*- FL
14	1		*FRONT REINFORCEMENT BAR	Not Necessary	1,928.00 FL	*- FL
15	1		*FRONT BUMPER SPONGE	No such part	498.20 FL	*- FL
16	1		*HEAD LAMP LH	Mounting Cracked	1,980.20 FL	*784.93 FL
17	1		*HEAD LAMP HOLDER LH	Broken	390.00 FL	*210.48 FL
18	1		*HEAD LAMP WIRE HARNESS	Not Necessary	1,690.00 FL	*- FL
19	1		*FOG LAMP LH	Mounting Cracked	1,004.20 FL	*293.25 FL
20	1		*FOG LAMP HOLDER LH	Broken	410.00 FL	*179.75 FL
21	1		*FOG LAMP WIRE HARNESS	Not Necessary	1,724.00 FL	*- FL
22	1		*FRONT LOWER STEP PANEL LH	Bent	892.00 FL	*337.52 FL
23	1		*FRONT LOWER STEP GARNISH LH	Broken	485.00 FL	*132.51 FL
24	1		*FRONT CENTER STEP PANEL LH	Serviceable	878.00 FL	*- FL
25	1		*FRONT CENTER STEP GARNISH LH	Not Necessary	498.00 FL	*- FL
26	1		*FRONT PANEL	Not Necessary	3,982.40 FL	*- FL
27	1		*FRONT PANEL FUSO EMBLEM	Not Necessary	104.20 FL	*- FL
28	1		*FRONT PANEL TOP GRILLE	Not Necessary	398.20 FL	*- FL
29	1		*FRONT PANEL LOWER GRILLE	Not Necessary	423.90 FL	*- FL
30	1		*FRONT PANEL LOGO	Not Necessary	112.40 FL	*- FL
31	1		*FRONT PANEL SUPER GREAT EMBLEM	Not Necessary	129.80 FL	*- FL
32	1		*SIDE ROUND MIRROR LH	Broken	1,230.00 FL	*177.68 FL
33	1		*FRONT DOOR REFLECTOR LH	Broken	192.00 FL	*118.70 FL
34	1		*LH BUMPER BRACKET	Bent	380.00 FL	*162.78 FL
35	1		*FRONT PANEL CLIPS	Not Necessary	50.00 FS	*- FS
36	1		*SIGNAL LAMP PANEL CLIPS	Necessary	50.00 FS	*20.00 FS
37	1		*FRONT CENTER PANEL CLIPS	Not Necessary	50.00 FS	*- FS
38	1		*FRONT SIGNAL LAMP LOWER PANEL CLIPS	No such part	50.00 FS	*- FS
39	1		*FRONT BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
40	1		*FRONT BUMPER CENTER GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
41	1		*SIGNAL LAMP CLIPS	Not Necessary	50.00 FS	*- FS
42	1		*HEAD LAMP CLIPS	Not Necessary	50.00 FS	*- FS
43	1		*FOG LAMP CLIPS	Not Necessary	50.00 FS	*- FS
44	1		*FRONT DOOR INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
45	1		*FRONT PANEL COMPANY STICKER	Not Necessary	2,000.00 FS	*- FS
46	1		*FRONT DOOR ADVERTISEMENT STICKER	Necessary	2,000.00 FS	*300.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
F=Franchise part. S=SpcNett. L=ListItemDisc.							
					Sub Total (S\$)	40,607.80	7,562.24
					- List Item Discount on L Items 10.00/10.00% (S\$)	3,610.78	724.22
					Total Parts (S\$)	36,997.02	6,838.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILIATE REPAIRS	New	600.00	0.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	6,000.00	1,200.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	6,000.00	800.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
5	TO RNR FRONT DOOR MECHANISM TO FACILITATE REPAIRS	New	250.00	120.00
6	TO RNR REAR DOOR MECHANISM TO FACILITATE REPAIRS	New	250.00	0.00
7	TO RNR REAR WINDSCREEN TO FACILITATE REPAIRS	New	500.00	0.00
8	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
9	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS.RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
Gross Labour Cost (\$\$)			14,400.00	2,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >