

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG20014661/GQD3E2-1

Date: 13/04/2021

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29141713MKF		
Claimant Vehicle No :	SME1686J	Insured Vehicle No :	SMS3499X		
Date of Loss:	29/12/2020	Nature of Claim:	TP	Claim No:	632598

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME1686J	Engine No:	LEB5604773
Make & Model:	HONDA FREED HYBRID, 1.5 G (A)	Chassis No:	GB71070657
Reg. Date:	20/09/2018 (Man. Year: 2018)	Odometer:	183803 km
Colour:	Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,243.80	3,156.36	3,087.44	49.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,420.00	1,610.00	1,810.00	52.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,663.80	4,766.36	4,897.44	50.68
Approved Total (Overridden) (S\$)		3,800.00		
Nett Amount (S\$)	9,663.80	3,800.00	5,863.80	60.68

INSPECTION

Date of Assignment:	30/12/2020	Apex Motoring
Date Inspected:	05/01/2021	Inspected At: 25 Kaki Bukit Road 4, #01-55 Synergy @ KB
Estimated Period of Repair:	5.0 days	Singapore 417800

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Apr 2021)
Parts:	M1-MPV	HONDA FREED HYBRID 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SME1686J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,064.20 F	*925.30 FL
2	2		*REAR BUMPER SIDE RETAINER	Serviceable	94.00 F	*- FL
3	2		*REAR BUMPER SIDE SUPPORT	Serviceable	158.00 F	*- FL
4	1		*SET REAR BUMPER CLIPS	Necessary	35.00 F	*35.00 FL
5	1		*REAR END PANEL	Buckled	717.25 F	*623.70 FL
6	1		*REAR END PANEL TOP GARNISH	Deformed	178.95 F	*178.95 FL
7	1		*REAR FLOOR PANEL	Repair	1,214.60 F	*- FL
8	1		*TAILGATE	Buckled	1,265.50 F	*1,180.60 FL
9	1		*TAILGATE LOGO EMBLEM	Necessary	77.00 F	*59.20 FL
10	1		*TAILGATE FREED EMBLEM	Necessary	64.20 F	*52.30 FL
11	1		*TAILGATE HYBRID EMBLEM	Necessary	62.10 F	*62.10 FL
12	1		*TAILGATE INNER LOCK	Jammed	181.00 F	*181.00 FL
13	1		*TAILGATE INNER TRIM BOARD	Serviceable	331.90 F	*- FL
14	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Serviceable	35.00 F	*- FL
15	1		*TAILGATE WEATHERSTRIP	Deformed	194.00 F	*168.70 FL
16	1		*REAR WINDSCREEN MOULDING	Necessary	91.10 F	*91.10 FL
17	1		*SET REVERSE SENSOR	Not Working	300.00 FS	*200.00 FS
18	1		*REAR NO PLATE	Buckled	60.00 FS	*40.00 FS
19	1		*ROLL REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*30.00 FS
20	1		*ROLL REAR END PANEL SEALANT	Necessary	60.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,243.80	3,867.95
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	711.59
Total Parts (\$\$)	6,243.80	3,156.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND REWIRE	New	60.00	30.00
2	TO REMOVE AND REINSTALL TAILGATE COMPONENTS	New	80.00	60.00
3	TO REMOVE AND REINSTALL REAR WINDSCREEN	New	150.00	120.00
4	TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY	New	120.00	60.00
5	TO REMOVE AND REINSTALL REVERSE SENSOR	New	140.00	40.00
6	TO REMOVE AND REINSTALL REVERSE CAMERA	New	150.00	40.00
7	TO APPLY ANTI-RUST	New	120.00	60.00
8	TO PUTTY AND SPRAY-PAINT OF AFFECTED AREAS	New	1,200.00	600.00
9	TO PANEL BEAT AND RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS	New	1,400.00	600.00
Gross Labour Cost (\$\$)			3,420.00	1,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >