

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: YU DOMINIC YISHAN Policy Particulars:- (THIRD PARTY CLAIM) Insured Veh. SHD 3766M Policy No. VFX/P2419138 Coverage (\$) Claim No. S1M0335G Excess (\$) Assign From YU DOMINIC YISHAN Assign Date Vehicle Particulars & Condition Make & Model TOYOTA HIACE Ref: CS3/ASM21002310/Gvf3e2 03/03/2021 Code: ASM Code: ASM Veh. Inspected GBG 5738L 0.00 Claim No. S1M0335G Excess (\$) 0.00 Vehicle Particulars & Condition
SINGAPORE 068811
Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SHD 3766M Veh. Inspected GBG 5738L Policy No. VFX/P2419138 Coverage (\$) 0.00 Claim No. S1M0335G Excess (\$) 0.00 Assign From YU DOMINIC YISHAN Assign Date 18/02/2021 2. Vehicle Particulars & Condition
Insured Veh. SHD 3766M Veh. Inspected GBG 5738L
Policy No. VFX/P2419138 Coverage (\$) 0.00
Claim No. S1M0335G Excess (\$) 0.00 Assign From YU DOMINIC YISHAN Assign Date 18/02/2021 Vehicle Particulars & Condition
Assign From YU DOMINIC YISHAN Assign Date 18/02/2021 2. Vehicle Particulars & Condition
2. Vehicle Particulars & Condition
Make & Model TOYOTA HIACE c.c. 2982
Engine No. HIDDEN Year of Reg. 2017
Chassis No. JTFHT02P600230685 Colour WHITE
Odometer 88581 KM Steering IN ORDER
Brakes IN ORDER Modification NIL
General GOOD
3. Conditions of Tyres
Size Make Balance
R/H Front Tyre 195 R15 DURATURN 6 mm
L/H Front Tyre 195 R15 DURATURN 6 mm
R/H Rear Tyre 195 R15 DURATURN 6 mm
L/H Rear Tyre 195 R15 DURATURN 6 mm
4. Description of Damages
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.
5. General Information
Accident Date 12/02/2021 Inspect Date / Time 19/02/2021 (11:00 AM)
Survey held at KIM SENG TECK MOTOR WORKS
BLK 3021A UBI ROAD 1 #01-42 SINGAPORE 408715
5a. Remarks
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000
5b. Estimate Days of Repair
ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days

Report Ref No. CS3/ASM21002310/Gvf3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor