

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE			Ref:	CS3/ASM21002315/Gvd3e2	
	8 SHENTON WAY TOWERSINGAPOR	-		Date:	25/02/2021	
	ATTN : YU DOMIN	IC YISHAN		Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SH 6136K	Veh. Inspected	ł	SLM 9011Z	
	Policy No.	VFX/P2419138	Coverage (\$)		0.00	
	Claim No.	S1M0337K	Excess (\$)		0.00	
	Assign From	YU DOMINIC YISHAN	Assign Date		18/02/2021	
2.	Vehicle Particulars & Condition					
	Make & Model	VOLKSWAGEN JETTA 1.4	c.c		1390	
	Engine No.	HIDDEN	Year of Reg.		2015	
	Chassis No.	WVWZZZ16ZEM059053	Colour		RED	
	Odometer	175783 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	215/60 R16	DUNLOP		5 mm	
	L/H Front Tyre	215/60 R16	DUNLOP		5 mm	
	R/H Rear Tyre	215/60 R16	DUNLOP		5 mm	
	L/H Rear Tyre	215/60 R16	DUNLOP		5 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.					
5.	General Information					
	Accident Date 16/02/2021 Inspect Date / Time 18/02/2021 (05:10 PM)				18/02/2021 (05:10 PM)	
	Survey held at	Survey held at ECLIPSE AUTO PTE LTD				
		155 KAKI BUKIT AVENUE 1 #01 □ 00 SHUN LI INDUSTRIAL PARK SINGAPORE 416012				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000					
5b.	b. Estimate Days of Repair					
	ESTIMATED NORM	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days				

Report Ref No. CS3/ASM21002315/Gvd3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A
Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.