

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGZ 2402R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR L/H FENDER	CRUMPLED	900.00	900.00
1	REAR L/H SMALLER FENDER	CRUMPLED	400.00	250.00
1	LEFT TAILLAMP	CRUMPLED	800.00	350.00
1	REAR BUMPER	CRUMPLED	800.00	612.00
2	REAR BUMPER RETAINER	BROKEN (1 PC ONLY)	320.00	70.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	2,000.00	-
1	REAR BOOT LOCK	SERVICEABLE	550.00	-
1	REAR TAILGATE	TO REPAIR SEE LABOUR	1,100.00	-
1	REAR TAILGATE BRACKET	SERVICEABLE	250.00	-
1	REAR BUMPER TOP STEP GARNISH	SERVICEABLE	300.00	-
1	RUBBER MOULDING	SERVICEABLE	80.00	-
	LESS 25% DISCOUNT		-	-545.50
			7,500.00	1,636.50
	SPECIAL NETT ITEMS			
1	REAR BUMPER PANEL CLIP (SN)	NECESSARY	150.00	30.00
			150.00	30.00
	LABOUR			
	REMOVE AND REFIT PANELS.	NOT NECESSARY	600.00	-
	APPLY TUFF KOTE.		300.00	40.00
	REMOVE,REFIT AND REPLACED DAMAGE AND CHECK UP REAR ELECTRICAL WIRING.		150.00	30.00
	REMOVE AND REFIT INNER GARNISHES TRIM TO ASSIST REPAIR.		200.00	30.00
	TO PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR END PANEL AND REAR TAILGATE.		600.00	600.00
	TO RESPRAY PAINTING.		900.00	700.00
			2,750.00	1,400.00
	GRAND TOTAL		10,400.00	3,066.50

Report Ref No. CS/LPC21002316/Qtf3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	2,450.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/LPC21002316/Qtf3q2

Ja

OI SUN PIN

Asst. Automotive Assessor

X.S.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser