

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21002320/KBA3Q2
Date: 26/08/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900120153	
Claimant Vehicle No :	GBC5871E	Insured Vehicle No :	SMM3578H	
Date of Loss:	16/02/2021	Nature of Claim:	TP	Claim No: 5832331762SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBC5871E		
Make & Model:	MITSUBISHI CANTER, 3.0 D (M)	Engine No:	4M42A91421
Reg. Date:	19/03/2013 (Man. Year: 2012)	Chassis No:	FB70BBA20549
Colour:	White	Odometer:	311928 km
Engine Capacity:	2977 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	195 R15X8 (D)
Front Left Side:	OHTSU 8 mm	Rear Left Side:	OHTSU 9/9 mm
Front Right Side:	OHTSU 8 mm	Rear Right Side:	OHTSU 9/9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,409.53	7,794.39	615.14	7.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,890.00	2,290.00	600.00	20.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,299.53	10,084.39	1,215.14	10.75
Approved Total (Overridden) (S\$)		8,050.00		

(S\$)	11,299.53	8,050.00	3,249.53	28.76
+ GST 7.00/7.00% (S\$)	790.97	563.50	227.47	28.76
Nett Amount (S\$)	12,090.50	8,613.50	3,477.00	28.76
+ Car Rental (8.0 x S\$90.00/day + 7.00% GST) (S\$)		770.40		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		9,391.90		

INSPECTION

Date of Assignment: 18/02/2021

Date Inspected: 18/02/2021

Estimated Period of Repair: 7.0 days

Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)
 Blk 1019 #01-374/382, Yishun Industrial Park A
 Singapore 768761

Adjuster: KENNETH KONG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	821.47 FL	*821.47 FL
2	1		*FRONT GRILLE	Cracked	559.10 FL	*559.10 FL
3	2		*HEADLAMPS	O/S Broken / N/S Mtg Cracked	1,270.20 FL	*1,270.20 FL
4	2		*SIGNAL LAMPS	N/S Mtg Cracked / O/S Broken	422.68 FL	*422.68 FL
5	1		*SIDE LAMPS	O/S Broken	369.00 FL	*184.50 FL
6	1		*FRONT PANEL	Bent	1,593.50 FL	*1,461.60 FL
7	1		*FRONT WIPER GARNISH	Mtg Cracked	399.85 FL	*399.85 FL
8	1		*FRONT WINDSCREEN GLASS RUBBER (50%)	Necessary	267.48 FS	*178.32 FS
9	1		*AIRCON EVAPORATOR	Housing Cracked	3,398.70 FL	*3,013.80 FL
10	1		*AIR-CON BLOWER	Cracked	1,156.10 FL	*1,156.10 FL
11	2		*TAILLAMPS	Cracked	400.30 FL	*400.30 FL
12	1		*TAILGATE STICKER (MITSUBISHI)	Necessary	104.50 FL	*104.50 FL
13	1		*STICKER -60KM/H	Necessary	10.00 FS	*10.00 FS
14	1		*STICKER -13 PAX	Necessary	10.00 FS	*10.00 FS
15	1		*REAR NUMBER PLATE	Bent	18.00 FS	*18.00 FS
16	1		*REAR SPARE TYRE HOLDER	Distorted	310.00 FL	*310.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,110.88	10,320.42
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,701.35	2,526.03
Total Parts (\$\$)	8,409.53	7,794.39

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE AND REFIX FRONT WINDSCREEN GLASS	New	60.00	60.00
2	REMOVE & REFIX DASHBOARD ,METER ASSY AND CHECK WIRING	New	250.00	240.00
3	REMOVE AND REFIX AIRCON CHECK ,VACUUM & REFILL GAS	New	100.00	100.00
4	REMOVE & REFIX FRT BUMPER ASSY ,GRILLE ,HEADLAMPS ,SIDE LAMPS ,SIGNAL LAMPS ,CUT WELD & RENEW FRT PANEL & REALIGN THE SAME	New	800.00	600.00
5	PUTTY & RESPRAY ON FRT PANEL ,GRILLE ,FRT BUMPER	New	680.00	540.00
6	REMOVE & REFIX TAILLAMPS ,REAR SPARE TYRE HOLDER ,KNOCK & REPAIR REAR SPARE TYRE BRACKET & REALIGN THE SAME	New	500.00	350.00
7	PUTTY & RESPRAY ON TAILGATE ,REAR END PANEL ,REAR SPARE TYRE BRACKET	New	500.00	400.00
Gross Labour Cost (\$\$)			2,890.00	2,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >